

# ExxonMobil Baton Rouge Emergency Response Notification Records (Spills/Releases)

## EXXON

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON	19930802		PRESSURE VESSEL / UNKNOWN PRESSURE VESSEL/UNKNOWN	HYDROCARBONS	0	LBS
EXXON	19940718	TANK OR CONTAINER	ABOVE GROUND STORAGE TANK/LEAKED MATERIAL, CAUSES UNKNOWN ABOVE GROUND STORAGE TANK/LEAKED MATERIAL, CAUSES UNKNOWN	BENZENE	0	UNK
EXXON	19941011	FITTING	WASTEWATER COOLING TOWER / SYSTEM UPSET WASTE WATER COOLING TOWER / SYSTEM UPSET	HYDROGEN SULFIDE	0	UNK
EXXON	19950201	VALVE	TOWER IN UNIT/BLOCK VALVE INADVERTENTLY CLOSED>OVERPRESSURED TOWER IN UNIT,BLOCK VLVE INADVERTENTLY CLOSED>OVERPRESSURED	HYDROGEN SULFIDE	0	UNK
EXXON	19950201	VALVE	TOWER IN UNIT/BLOCK VALVE INADVERTENTLY CLOSED>OVERPRESSURED TOWER IN UNIT,BLOCK VLVE INADVERTENTLY CLOSED>OVERPRESSURED	UNCOMBUSTED HYDROCARBONS	0	UNK
EXXON	19950222	OVERFLOW	ABOVE GROUND TANK NO. 476/ OVERFLOW ABOVE GROUND TANK NO.476 / OVERFLOW	BENZENE (WATER MIXTURE)	100	GAL
EXXON	19950409		TANK 934//LEAK DEVELOPED IN TANK CAUSING MATERIALS TO RELEASE	NAPHTHALENE	100	LBS
EXXON	19950411		NPDES OUTFALL NO. 003 / OVERFLOW / DUE TO HEAVY RAINFALL	OIL: CRUDE	5	GAL
EXXON	19950508		STORM WATER CARRY OVER	OIL: CRUDE	1	GAL
EXXON	19950518		NPDS NO.003//SHEEN DISCOVERED AT THE OUTFALL	UNKNOWN OIL	0	UNK
EXXON	19950922	FITTING	FLARE STACK / BLOCKED MOV FLARE STACK / BLOCKED MOV	SULFUR DIOXIDE	0	UNK

EXXON	19951103		TRANSFER PUMP ON A STORAGE TANK/EQUIPMENT FAILURE	BENZENE	0	NON
EXXON	19951106	UNKNOWN	COKE DRUM/RELEASED MATERIALS DUE TO UNKNOWN REASONS COKE DRUM / RELEASED MATERIALS DUE TO UNKNOWN REASONS	HYDROGEN SULFIDE	0	UNK
EXXON	19951210	FITTING	DEPROPENIZER, FAULTY STEAM TRACING CAUSED PRESSURE FREEZE DEPROPENIZER / FAULTY STEAM TRACING CAUSED PRESSURE TRANSMITTER TO FREEZE	BUTADIENE	0	UNK
EXXON	19951218	POWER FAILURE	LIGHT END UNIT,POWER OUTTAGE DURING STORM CAUSED PUMP LOSS LIGHT END UNIT / POWER OUTAGE DURING STORM CAUSED THE LOSS OF A PUMP	BENZENE	0	UNK
EXXON	19951218	POWER FAILURE	LIGHT END UNIT,POWER OUTTAGE DURING STORM CAUSED PUMP LOSS LIGHT END UNIT / POWER OUTAGE DURING STORM CAUSED THE LOSS OF A PUMP	BUTADIENE	0	UNK
EXXON	19951218	POWER FAILURE	LIGHT END UNIT,POWER OUTTAGE DURING STORM CAUSED PUMP LOSS LIGHT END UNIT / POWER OUTAGE DURING STORM CAUSED THE LOSS OF A PUMP	XYLENE (O-, M-, P-, & MIXTURES)	0	UNK
EXXON	19951226		PRODUCT LOADING LINE/HOLE IN LINE	GASOLINE: AUTOMOTIVE (UNLEADED)	0	UNK
EXXON	19960127		STORM WATER DISSCHARGE/RESIDUAL OIL CARRIED OUT BY HEAVY RAINS	OTHER OIL	0	UNK
EXXON	19960203	VALVE	PIPESTILL UNITS, LINES FROZE OVER THE WEEKEND,CAUSING PRESSURE* PIPESTILL UNITS / LINES FROZE OVER THE WEEKEND CAUSING THE PRESSURE RELIEF VALVES TO GO OFF	BENZENE	0	UNK

EXXON	19960203	VALVE	PIPESTILL UNITS, LINES FROZE OVER THE WEEKEND, CAUSING PRESSURE* PIPESTILL UNITS / LINES FROZE OVER THE WEEKEND CAUSING THE PRESSURE RELIEF VALVES TO GO OFF	HYDROGEN SULFIDE	0	UNK
EXXON	19960221	CONTAINER LEAK	SULFUR RECOVERY UNITS DIVERTED GAS TO INCINERATOR>CLOSED VALVE SULFUR RECOVERY UNITS DIVERTED GAS TO AN INCINERATOR DUE TO VALVE THAT TRIPPED CLOSED	HYDROGEN SULFIDE	0	UNK
EXXON	19960221	CONTAINER LEAK	SULFUR RECOVERY UNITS DIVERTED GAS TO INCINERATOR>CLOSED VALVE SULFUR RECOVERY UNITS DIVERTED GAS TO AN INCINERATOR DUE TO VALVE THAT TRIPPED CLOSED	CARBON DISULFIDE	0	UNK
EXXON	19960221	CONTAINER LEAK	SULFUR RECOVERY UNITS DIVERTED GAS TO INCINERATOR>CLOSED VALVE SULFUR RECOVERY UNITS DIVERTED GAS TO AN INCINERATOR DUE TO VALVE THAT TRIPPED CLOSED	CARBON NYLSULFIDE	0	UNK
EXXON	19960222	FITTING	SULFUR RECOVERY UNIT, COMPRESSOR TRIPPED, DIVERTED GAS>INCIN/ SULFUR RECOVERY UNIT / COMPRESSOR TRIPPED AND GAS WAS DIVERTED TO INCINERATOR	SULFUR DIOXIDE	0	UNK
EXXON	19960222	FITTING	SULFUR RECOVERY UNIT, COMPRESSOR TRIPPED, DIVERTED GAS>INCIN/ SULFUR RECOVERY UNIT / COMPRESSOR TRIPPED AND GAS WAS DIVERTED TO INCINERATOR	HYDROGEN SULFIDE	0	UNK
EXXON	19960303	FITTING	FLARE STACK , UNIT UPSET FLARE STACK / UNIT UPSET	SULFUR DIOXIDE	0	UNK
EXXON	19960309	IMPROPER VALVE HANDLING	LOADING OPERATIONS, OPEN DRAIN VALVE ON THE MANIFOLD LOADING OPERATIONS / OPEN DRAIN VALVE ON THE MANIFOLD	OIL: DIESEL	1	GAL

EXXON	19960424	CONTAINER LEAK	KETONE DEWAXING UNIT DRUM, WHEN OPERATORS OPENED DRUM, MAT LEAKED KETONE DEWAXING UNIT DRUM / WHEN OPERATORS OPENED DRUM MATERIAL LEAKED OUT	METHYL ETHYL KETONE	2000	LBS
EXXON	19960501		T/B COASTAL 311/TRANSFER HOSE DEVELOPED A LEAK	OIL: CRUDE	2	GAL
EXXON	19960603	FITTING	HYDROCRACKER, FLOW INDICATOR FAILURE HYDROCRACKER / FLOW INDICATOR FAILURE	SULFUR DIOXIDE	0	UNK
EXXON	19960603	FITTING	HYDROCRACKER, FLOW INDICATOR FAILURE HYDROCRACKER / FLOW INDICATOR FAILURE	HYDROCARBONS	0	UNK
EXXON	19960614		DURING TRANSFER OF PRODUCT / SOME RESIDUAL FROM HOSE WAS RELEASED	OIL, FUEL: NO. 2-D	1	GAL
EXXON	19960616		NO 7 PIPE STILL TOWER / UNIT UPSET	HYDROGEN SULFIDE	0	NON
EXXON	19960616		NO 7 PIPE STILL TOWER / UNIT UPSET	HYDROCARBONS	0	UNK
EXXON	19960616		HHLA NORTH ET15A EXHANGER / FLANGE LEAK RESULTED IN FIRE	HYDROGEN SULFIDE	0	UNK
EXXON	19960616		HHLA NORTH ET15A EXHANGER / FLANGE LEAK RESULTED IN FIRE	CRUDE HYDROCARBON FEEDSTOCK (CON	0	UNK
EXXON	19960624		LANDING BARGE(100FT IN LENGTH / VSL WAS DISCOVERED TAKING ON WATER LAST NIGHT / POSSIBLE RELEASE FROM THE SLOP TANKS, QUANTITY UNKNOWN	WASTE OIL	0	UNK
EXXON	19960728	CONTAINER LEAK	TUBE RUPTURED IN CARBON MONOXIDE FURNACE TUBE RUPTURE IN CARBON MONOXIDE FURNACE	CARBON MONOXIDE	0	UNK
EXXON	19960728	CONTAINER LEAK	TUBE RUPTURED IN CARBON MONOXIDE FURNACE TUBE RUPTURE IN CARBON MONOXIDE FURNACE	SULFUR DIOXIDE	0	UNK

EXXON	19960806	CONTAINER LEAK	WATER COOLING TOWER, EXCHANGER LEAK WATER COOLING TOWER / EXCHANGER LEAK	HYDROGEN SULFIDE	0	UNK
EXXON	19960810		FLARE STACK / SYSTEM UPSET	SULFUR DIOXIDE	0	NON
EXXON	19960810		FLARE STACK / SYSTEM UPSET	HYDROGEN SULFIDE	0	NON
EXXON	19960810	FITTING	FLARE STACK / SYSTEM UPSET FLARE STACK / SYSTEM UPSET	SULFUR DIOXIDE	0	UNK
EXXON	19960810	FITTING	FLARE STACK / SYSTEM UPSET FLARE STACK / SYSTEM UPSET	HYDROGEN SULFIDE	0	UNK
EXXON	19960903		DRIP PAN ON A DOCK/DRIP PAN CRACKED	OIL: DIESEL	2	GAL
EXXON	19960910	CONTAINER LEAK	COOLING TOWER / LEAK IN AN EXCHANGER COOLING TOWER/LEAK IN AN EXCHANGER	HYDROCARBONS	0	UNK
EXXON	19960927		FLARE/SOUR GAS SYSTEM UPSET	SULFUR DIOXIDE	0	NON
EXXON	19960927		FLARE/SOUR GAS SYSTEM UPSET	HYDROGEN SULFIDE	0	NON
EXXON	19960927		FLARE/SOUR GAS SYSTEM UPSET	HYDROCARBONS	0	NON
EXXON	19961010	FITTING	COKER UNIT FLARE, COMPRESSOR FAILURE COKER UNIT FLARE / COMPRESSOR FAILURE	HYDROGEN SULFIDE	0	UNK
EXXON	19961010	FITTING	COKER UNIT FLARE, COMPRESSOR FAILURE COKER UNIT FLARE / COMPRESSOR FAILURE	SULFUR DIOXIDE	0	UNK
EXXON	19961010	FITTING	COKER UNIT FLARE, COMPRESSOR FAILURE COKER UNIT FLARE / COMPRESSOR FAILURE	HYDROCARBONS	0	UNK
EXXON	19961010	VALVE	CRUDE SAFETY VALVE ON PIPE STILL UNIT BLEW TO ATMOSPHERIC** CRUDE SAFETY VALVE ON PIPESTILL UNIT BLEW TO ATMOSPHERIC BLOWDOWN DRUM	BENZENE	0	UNK

EXXON	19961010	VALVE	CRUDE SAFETY VALVE ON PIPE STILL UNIT BLEW TO ATMOSPHERIC** CRUDE SAFETY VALVE ON PIPESTILL UNIT BLEW TO ATMOSPHERIC BLOWDOWN DRUM	BENZENE HYDROCARBON MIX (CONT.	0	UNK
EXXON	19961014		FLARE UNIT NO 5 AND 20, ELECTRICIAN CHANGING BREAKER,CUT POWER FLARE UNIT NO. 5 AND 20 / ELECTRIAN WAS CHANGING BREAKER AND CUT POWERTO COMPRESSOR	SULFUR DIOXIDE	0	UNK
EXXON	19961014		FLARE UNIT NO 5 AND 20, ELECTRICIAN CHANGING BREAKER,CUT POWER FLARE UNIT NO. 5 AND 20 / ELECTRIAN WAS CHANGING BREAKER AND CUT POWERTO COMPRESSOR	HYDROGEN SULFIDE	0	UNK
EXXON	19961014		FLARE UNIT NO 5 AND 20, ELECTRICIAN CHANGING BREAKER,CUT POWER FLARE UNIT NO. 5 AND 20 / ELECTRIAN WAS CHANGING BREAKER AND CUT POWERTO COMPRESSOR	HYDROCARBON	0	UNK
EXXON	19961014		FLARE SOUR WATER STRIPPER,OIL IN STRIPPER CAUSED AMMONIA ACID* FLARE SOUR WATER STRIPPER / OIL IN STRIPPER CAUSED AMMONIA ACID GAS TO BE FLARED / #17 AND #19 FLARES	HYDROGEN SULFIDE	0	UNK
EXXON	19961014		FLARE SOUR WATER STRIPPER,OIL IN STRIPPER CAUSED AMMONIA ACID* FLARE SOUR WATER STRIPPER / OIL IN STRIPPER CAUSED AMMONIA ACID GAS TO BE FLARED / #17 AND #19 FLARES	SULFUR DIOXIDE	0	UNK
EXXON	19961014		FLARE SOUR WATER STRIPPER,OIL IN STRIPPER CAUSED AMMONIA ACID* FLARE SOUR WATER STRIPPER / OIL IN STRIPPER CAUSED AMMONIA ACID GAS TO BE FLARED / #17 AND #19 FLARES	HYDROCARBONS	0	UNK

EXXON	19961029	CONTAINER LEAK	COOLING TOWER EXCHANGER, TUBES DEVELOPED A LEAK CAUSING MAT REL COOLING TOWER EXCHANGER / THE EXCHANGER TUBES DEVELOPED A LEAK CAUSING THE RELEASE OF THE MATERIAL	HYDROGEN SULFIDE	0	UNK
EXXON	19961029	CONTAINER LEAK	COOLING TOWER EXCHANGER, TUBES DEVELOPED A LEAK CAUSING MAT REL COOLING TOWER EXCHANGER / THE EXCHANGER TUBES DEVELOPED A LEAK CAUSING THE RELEASE OF THE MATERIAL	BUTADIENE	0	UNK
EXXON	19961122	CONTAINER LEAK	EXCHANGER LEAKING INTO COOLING TOWER EXCHANGER LEAKING INTO COOLING TOWER	HYDROGEN SULFIDE	0	UNK
EXXON	19961122	CONTAINER LEAK	EXCHANGER LEAKING INTO COOLING TOWER EXCHANGER LEAKING INTO COOLING TOWER	BENZENE	0	UNK
EXXON	19961122	CONTAINER LEAK	EXCHANGER LEAKING INTO COOLING TOWER EXCHANGER LEAKING INTO COOLING TOWER	BUTADIENE	0	UNK
EXXON	19961210	CONTAINER LEAK	CAUSTIC PIPING, GASKET FAILURE CAUSING A PIN HOLE LEAK CAUSTIC PIPING / GASKET FAILURE CAUSING A PIN HOLE LEAK	SULFIDIC SPENT CAUSTIC	0	UNK
EXXON	19970107	VALVE	PROCEESS UNIT, UNIT UPSET, A SAFETY VALVE BLEW PROCESS UNIT / UNIT UPSET.....A SAFETY VALVE BLEW	HYDROGEN SULFIDE	0	UNK
EXXON	19970107	VALVE	PROCEESS UNIT, UNIT UPSET, A SAFETY VALVE BLEW PROCESS UNIT / UNIT UPSET.....A SAFETY VALVE BLEW	LIGHT HYDROCARBON	0	UNK
EXXON	19970107	VALVE	PROCEESS UNIT, UNIT UPSET, A SAFETY VALVE BLEW PROCESS UNIT / UNIT UPSET.....A SAFETY VALVE BLEW	1,-3 BUTADIENE	0	UNK

EXXON	19970115		M/V OMEGA VENTURE L / A LINE DEVELOPED A LEAK	OTHER OIL	1	GAL
EXXON	19970128	CONTAINER LEAK	COOLING TOWER,EXCHANGER LEAK FROM PROCESS TO COOLING WATER SIDE COOLING TOWER / EXCHANGER LEAK FROM THE PROCESS SIDE TO THE COOLING WATER SIDE	BUTADIENE	0	UNK
EXXON	19970225	CONTAINER LEAK	THERMAL WELL OF REACTOR ON POWER FORMER UNIT,BROKEN/LEAKED THERMAL WELL OF REACTOR ON POWER-FORMER UNIT / BROKEN-LEAKED	BENZENE	0	UNK
EXXON	19970225	CONTAINER LEAK	THERMAL WELL OF REACTOR ON POWER FORMER UNIT,BROKEN/LEAKED THERMAL WELL OF REACTOR ON POWER-FORMER UNIT / BROKEN-LEAKED	XYLENE (O-, M-, P-, & MIXTURES)	0	UNK
EXXON	19970228	POWER FAILURE	FLARING, POWER TRIPPED DURING MAINTENANCE FLARING / POWER TRIPPED DURING MAINTENANCE	HYDROGEN SULFIDE	0	UNK
EXXON	19970331	FLANGE	POWERFORMER UNIT, FLANGE LEAK DUE TO UNKNOWN CAUSE POWERFORMER UNIT / FLANGE LEAK DUE TO UNK CAUSE	BENZENE	0	UNK
EXXON	19970331	FLANGE	POWERFORMER UNIT, FLANGE LEAK DUE TO UNKNOWN CAUSE POWERFORMER UNIT / FLANGE LEAK DUE TO UNK CAUSE	XYLENE (O-, M-, P-, & MIXTURES)	0	UNK
EXXON	19970405		SALT WATER DISCHARGE OUTFALL/EXCESS RAIN CAUSED OVERFLOW	OIL: CRUDE	1	GAL
EXXON	19970427	UNKNOWN	SEAL VENT ON COMPRESSOR,CAUSE OF RELEASE UNK AT TIME OF REPORT SEAL VENT ON COMPRESSOR / CAUSE OF RELEASE UNKNOWN AT TIME OF REPORT	HYDROGEN SULFIDE	0	UNK
EXXON	19970625		ABANDONED DOCK SERVICE LINE (12 INCH PIPELINE) / THE LINE WAS BEING REMOVED AND RESIDUAL MATERIAL WAS ACCIDENTALLY RELEASED	OIL: CRUDE	1	CUP



EXXON	19970816	OVERFLOW	COMPARTMENT ON BARGE RCT105 OVERFILLED COMPARTMENT ON BARGE RCT105 OVER FILLED	SULFURIC CAUSTIC	5	GAL
EXXON	19970917		BARGE "BRIDGET B" / #2 HOLDING TANK DEVELOPED A PIN HOLE SIZE LEAK	JET FUEL: JP-8	1	OUN
EXXON	19971021		OLD PIPING BEING DISMANTLED OLD PIPING/BEING DISMANTLED	WASTE OIL	0	UNK

## EXXON BATON ROUGE

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON BATON ROUGE	19900608		CALLER'S COMPANY OWNS TOWING VESSEL WHICH WAS INVOLVED WITH A HOSE DISCONNECTION BETWEEN A BARGE AND DOCK	JET FUEL: JP-5 (KEROSENE, HEAVY)	0	UNK

## EXXON BATON ROUGE PLASICS

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON BATON ROUGE PLASICS	19911012		STORAGE TANK / OVERFILLED	HEXANE	0	NON
EXXON BATON ROUGE PLASICS	19911012		STORAGE TANK / OVERFILLED	ISOOCTANE	0	NON
EXXON BATON ROUGE PLASICS	19920527		ABOVE GROUND STORAGE TANK/HIGH LEVEL ALARM FAILURE	1-HEXENE	0	UNK
EXXON BATON ROUGE PLASICS	19930103	FITTING	PROCESS REACTOR / RUPTURE DISK BLEW PROCESS REACTOR / RUPTURE DISK BLEW	ETHYLENE		LBS

## EXXON BATON ROUGE PLASTICS

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON BATON ROUGE PLASTICS	19930401	OVERFLOW	MIX TANK / OVERFILLED MIX TANK / OVERFILLED	ISOPAR	100	GAL

## EXXON BATON ROUGE REF.

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON BATON ROUGE REF.	19970328	VALVE	HEAT EXCHANGER / LEAKING VALVE HEAT EXCHANGER/LEAKING VALVE	BENZENE	0	UNK
EXXON BATON ROUGE REF.	19970328	VALVE	HEAT EXCHANGER / LEAKING VALVE HEAT EXCHANGER/LEAKING VALVE	HYDROGEN SULFIDE	0	UNK

## EXXON BATON ROUGE REFINER

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON BATON ROUGE REFINER	19971126	CONTAINER LEAK	UNDERGROUND BROKEN SEWER LINE(WASTE CODE OF F037)UNKNOWN UNDER GROUND BROKEN SEWER LINE (WASTE CODE OF F037) / UNKNOWN CAUSE	PRIMARY SLUDGE	0	UNK

## EXXON CHEM BATON ROUGE

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEM BATON ROUGE	19920930	FITTING	CARBON ABSORBTION UNIT/DURING DRAINING, SPILL OCCURRED CARBON ABSORBTION UNIT/ DURING DRAINING, SPILL OCCURRED	TRIMETHYLPENTANE		LBS

## EXXON CHEM BRPP

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEM BRPP	19971122	VALVE	REACTOR DUMP VALVE,INTERLOCK HIGH REACTOR PRESSURE, OPENED SOURCE: REACTOR DUMP VALVE:/ HIGH PRESSURE CAUSED THE INTERLOCK TO OPEN WHICH RELEASED THE MATERIAL	ETHYLENE	0	UNK
EXXON CHEM BRPP	19971122	VALVE	REACTOR DUMP VALVE,INTERLOCK HIGH REACTOR PRESSURE, OPENED SOURCE: REACTOR DUMP VALVE:/ HIGH PRESSURE CAUSED THE INTERLOCK TO OPEN WHICH RELEASED THE MATERIAL	HEXENE	0	UNK

## EXXON CHEMICAL

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL	19891206		FAILED (FLANGE)	FIRE WATER/OUTFALL WASTEWATER		
EXXON CHEMICAL	19900108		DUE TO EXLOSION WHICH KNOCKED OUT VAPOR EMISSION SYST	BENZENE	0	NON
EXXON CHEMICAL	19900219		SAFETY VALVE ON TOWER ON RUBBER MANUFACTURING UNIT/OVERPRESSURE OF SYSTEM	METHYL CHLORIDE	0	NON
EXXON CHEMICAL	19900307		BENZENE TANK/ADJACENT REFINERY EXPLOSION DAMAGED THE TANK, FORCING A ROOF SUPPORT THROUGH THE TANK FLOOR, RELEASING BENZENE.	BENZENE	0	LBS
EXXON CHEMICAL	19900317		ABOVEGROUND STORAGE TANK / HOLE IN THE TANK DUE TO AN UNKNOWN CAUSE.	METHYL ETHYL KETONE	0	NON
EXXON CHEMICAL	19900317		HEAT EXCHANGER / FLANGE LEAKED	BENZENE	0	NON
EXXON CHEMICAL	19900427		ABOVEGROUND STORAGE TANK / BLEEDER VALVE WAS ACCIDENTALLY LEFT OPEN	BENZENE	0	NON
EXXON CHEMICAL	19900517		STORAGE TANK/HOLE IN TANK.	PHOSPHORIC ACID	17500	LBS
EXXON CHEMICAL	19900522		LEVEL INSTRUMENT ON CONDENSER / INSTRUMENT FAILURE	METHYL CHLORIDE	0	NON
EXXON CHEMICAL	19900522		LEVEL INSTRUMENT ON CONDENSER / INSTRUMENT FAILURE	HYDROCHLORIC ACID	0	NON
EXXON CHEMICAL	19900611		HOLE DEVELOPED IN A FEED BIND TO SFA TANK / CORROSION	SULFURIC ACID AND WATER (68% SFA	0	NON
EXXON CHEMICAL	19900612		TUBING TO A SYSTEM FEED LINE WAS RUPTURED WHEN IT WAS BEING SAND BLASTED	BENZENE	0	NON
EXXON CHEMICAL	19900619		POLLUTION CONTROL DEVICE/ACCIDENTAL SHUTDOWN	MALEIC ANHYDRIDE	0	NON

EXXON CHEMICAL	19900619	VAPOR RECOVERY SYSTEM / COMPRESSOR FAILED	BENZENE (14.5 LBS = QTY BNZ)	0	NON
EXXON CHEMICAL	19900706	TANK / OVERFLOW OF THE TANK DUE TO EQUIPMENT FAILURE	BENZENE	0	NON
EXXON CHEMICAL	19900815	ABOVE GROUND STORAGE TANK / SAFETY VALVE RELEASED DUE TO PRESSURE.	METHYL CHLORIDE	0	NON
EXXON CHEMICAL	19900815	ABOVE GROUND STORAGE TANK / SAFETY VALVE RELEASED DUE TO PRESSURE.	HYDROGEN CHLORIDE	0	NON
EXXON CHEMICAL	19900824	STORAGE TANK VAPOR RECOVERY SYSTEM / RELEASE DUE TO HIGH BACK PRESSURE	NATURAL GAS	0	NON
EXXON CHEMICAL	19900902	VALVE PACKING ON A PROCESS UNIT LEAKED, RELEASING 100 LBS OF METHYL CHLORIDE	METHYL CHLORIDE	0	NON
EXXON CHEMICAL	19900902	FLANGE ON AN EXCHANGER LEAKING	SULFURIC ACID WITH BUTENES	0	NON
EXXON CHEMICAL	19900920	FLANGE/ LEAKING	BENZENE	0	NON
EXXON CHEMICAL	19900922	TANK INLET/ FLANGE LEAKING	HYDROCARBONS ( 31% BENZENE )	0	NON
EXXON CHEMICAL	19900925	PUMP HOSE/ HOSE BROKE	BENZENE (31%)	0	NON
EXXON CHEMICAL	19901029	TRANSFER PUMP/ SEAL FAILED	BENZENE	0	NON
EXXON CHEMICAL	19901029	SAFETY VALVE ON LIGHT OIL UNIT TOWER/ UNKNOWN CAUSE	BENZENE	0	NON
EXXON CHEMICAL	19901030	HOLE IN A OUTLET HEADER OF SAFETY VALVE MANIFOLD	BENZENE (10% MAX)	0	NON
EXXON CHEMICAL	19910128	EXCAVATING AND STRUCK AN UNDERGROUND LINE	MIXTURE OF HYDROCARBONS	0	NON
EXXON CHEMICAL	19910128	PROCESS PIPING / DUE TO A FLANGE FAILURE.	BENZENE	0	NON

EXXON CHEMICAL	19910223	AGITATOR SEAL ASSEMBLY / DISCOVERED A LEAK IN THE UNIT, CAUSE UNKNOWN.	METHYL CHLORIDE	0	NON
EXXON CHEMICAL	19910223	AGITATOR SEAL ASSEMBLY / DISCOVERED A LEAK IN THE UNIT, CAUSE UNKNOWN.	HEXANE	0	NON
EXXON CHEMICAL	19910310	TRANSFER PUMP / SEAL FAILURE	BENZENE	0	NON
EXXON CHEMICAL	19910321	ABOVEGROUND STORAGE TANK/BROKEN COUPLING	ANTHRACENE	0	NON
EXXON CHEMICAL	19910330	SAMPLE PUMP SEAL FAILED.	BENZENE	0	NON
EXXON CHEMICAL	19910409	FLOW METER / LEAKING FITTING	HEXANE	0	NON
EXXON CHEMICAL	19910415	3" GAS LINE/LEAK	PROPYLENE	0	NON
EXXON CHEMICAL	19910423	FEED PUMP/ SEAL FAILURE	BENZENE (35%)	0	NON
EXXON CHEMICAL	19910424	PUMP SEAL / UNKNOWN	BUTADIENE	0	NON
EXXON CHEMICAL	19910501	PIPE WITHIN FACILITY DEVELOPED PINHOLE LEAK	BENZENE (52%) QTY IS AN ESTIMATE	0	NON
EXXON CHEMICAL	19910506	FITTING ON PROCESS UNIT FAILED.	BENZENE	0	NON
EXXON CHEMICAL	19910511	FLANGE/LEAKED DUE PRESSURE RISE	1-HEXENE	0	NON
EXXON CHEMICAL	19910511	TUBING CRACKED DUE TO STRESS	BENZENE	0	NON
EXXON CHEMICAL	19910604	3/4 TUBE ON FLOW METER FITTING BROKE DUE TO CORROSION	HEXANE	0	NON
EXXON CHEMICAL	19910616	BOILER / VENT STREAM RELEASED MATERIAL DUE TO BACK PRESSURE	BUTADIENE	0	NON
EXXON CHEMICAL	19910620	VENT STREAM OVERPRESSURED	BUTADIENE	0	NON
EXXON CHEMICAL	19910625	CONTROL VALVE/OPERATOR ERROR BY MAINTENANCE WORKER	HEXANE	0	NON
EXXON CHEMICAL	19910625	NONE SPECIFIED	HEXANE		

EXXON CHEMICAL	19910708	PROCESS UNIT / BLEEDER VALVE LEFT OPEN	METHYL CHLORIDE	0	NON
EXXON CHEMICAL	19910816	LEAKING FLANGE GASKET ON A REACTOR	HEXANE	0	NON
EXXON CHEMICAL	19910818	OVER HEAD LINE IN A PROCESS UNIT/CORROSION	BENZENE	0	NON
EXXON CHEMICAL	19910910	TRANSFER LINE / PUMP SEAL FAILED	BUTADIENE	0	NON
EXXON CHEMICAL	19910916	COMPRESSOR / SEAL FAILED	BENZENE	0	NON
EXXON CHEMICAL	19910917	PROCESS UNIT / WHILE REFILLING, DRUM OVERFILLED	HEXANE	0	NON
EXXON CHEMICAL	19910919	PUMP FLANGE GASKET FAILED ON A PROCESS UNIT	HEXANE	60	LBS
EXXON CHEMICAL	19910919	PUMP FLANGE GASKET FAILED ON A PROCESS UNIT	METHYL CHLORIDE	60	LBS
EXXON CHEMICAL	19910926	TUBING LEAK IN PROCESS UNIT/FAGITUE	1-HEXENE	0	NON
EXXON CHEMICAL	19911026	NO.26 FLARE / PILOT LIGHT OUT	BUTADIENE	0	NON
EXXON CHEMICAL	19911124	PROCESS UNIT PIPING/GASKET FAILURE	BENZENE (EXTRACT MATERIAL-70% BE	0	NON
EXXON CHEMICAL	19911125	HOLE IN INSTRUMENT TUBING	HEXANE	0	NON
EXXON CHEMICAL	19911202	FLARE STACK / PILOT WENT OUT	BENZENE	0	NON
EXXON CHEMICAL	19911202	FLARE STACK / PILOT WENT OUT	PROPYLENE	0	NON
EXXON CHEMICAL	19911202	PROCESS DRUM IN PROCESS UNIT / DRUM LEAKED WHILE BEING PREPARED FOR USE	HEXANE	0	NON
EXXON CHEMICAL	19911204	PUMP SEAL FAILED ON TOWER	BUTADIENE	0	NON
EXXON CHEMICAL	19911212	SEAL LEG ON PROCESS UNIT/ELECTRICAL PROBLEM	BUTADIENE	0	NON

EXXON CHEMICAL	19911214		FLANGE LEAK ON A PROCESS UNIT/EQUIPMENT FAILURE OF A GASKET	HEXANE	0	NON
EXXON CHEMICAL	19911215		FILTER/FILTER WAS NOT EMPTIED AS IT SHOULD HAVE BEEN BEFORE REPAIR MAINTENANCE WAS PERFORMED ON THE FILTER.	HEXANE	0	NON
EXXON CHEMICAL	19911220		PROCESS UNIT VALVE/POWER BLIP CAUSED VALVE TO SHUT RESULTING IN THE RELEASE	BUTADIENE	0	NON
EXXON CHEMICAL	19911226		PROCESS PIPING/MAINTENANCE	DIMETHYL FORMAMIDE	0	NON
EXXON CHEMICAL	19920103	VALVE	COMPRESSOR VENT ON A PROCESS UNIT/VALVE FAILURE COMPRESSOR VENT ON A PROCESS UNIT/VALVE FAILURE.	HEXANE		LBS
EXXON CHEMICAL	19920109	HOSE	MIXTURE SEAL IN PROCESS UNIT/LEAKING SEAL MIXTURE SEAL IN PROCESS UNIT / LEAKING SEAL	HEXANE		LBS
EXXON CHEMICAL	19920116	FITTING	PROCESS UNIT/SPILLAGE WHEN A SAMPLE WAS TAKEN. PROCESS UNIT/ SPILLAGE WHEN A SAMPLE WAS TAKEN	HEXANE		LBS
EXXON CHEMICAL	19920118		FLARE PILOT/PILOT IS OUT	ETHYLENE	0	NON
EXXON CHEMICAL	19920118		FLARE PILOT/PILOT IS OUT	PROPYLENE	0	NON
EXXON CHEMICAL	19920119	FITTING	STORAGE SPHERE/LEAKING LEVEL GAUGE. STORAGE SPHERE/LEAKING LEVEL GAUGE	BUTADIENE		LBS
EXXON CHEMICAL	19920121		PUMP CONNECTION ON A TOWER/DUE TO A LOOSE CONNECTION PUMP CONNECTION ON A A TOWER / DUE TO A LOOSE CONNECTION	BENZENE		GAL
EXXON CHEMICAL	19920125	FITTING	MIXER IN A PROCESS UNIT/SEAL FAILURE MIXER IN A PROCESS UNIT/SEAL FAILURE	HEXANE		LBS

EXXON CHEMICAL	19920125	FITTING	PROCESS UNIT/SEAL FAILURE IN PUMP PROCESS UNIT/SEAL FAILURE IN PUMP	BUTADIENE		GAL
EXXON CHEMICAL	19920126	VALVE	VALVE ON A PIPE IN PROCESS UNIT/GASKET FAILURE VALVE ON A PIPE IN PROCESS UNIT/ GASKET FAILURE	HEXANE		LBS
EXXON CHEMICAL	19920204	RAIN OR SNOW	PILOT OUT ON ONE OF FLARE STACKS DUE TO RAIN PILOT OUT ON ONE OF FLARE STACKS / DUE TO RAIN	BUTADIENE		LBS
EXXON CHEMICAL	19920209	PUMP	PROCESS UNIT PUMP/FAILED GASKET PROCESS UNIT PUMP/FAILED GASKET	BORON TRICHLORIDE		GAL
EXXON CHEMICAL	19920226	PUMP	PUMP ON PROCESS UNIT/SEAL FAILURE PUMP ON PROCESS UNIT/SEAL FAILURE	HEXANE		GAL
EXXON CHEMICAL	19920229		FLARE PROCESS UNIT//PILOT OUT	BUTADIENE	0	NON
EXXON CHEMICAL	19920305	FITTING	FLARE STACK/PILOT WENT OUT FLARE STACK/PILOT WENT OUT	PROPYLENE	0	LBS
EXXON CHEMICAL	19920307	FLANGE	6 INCH FLANGE ON TRANSFER PIPE LEAKING DUE TO GASKET FAILURE 6 INCH FLANGE ON TRANSFER PIPE LEAKING DUE TO GASKET FAILURE	HEXANE		LBS
EXXON CHEMICAL	19920315	FITTING	PROCESS UNIT LINE/GASKET FAILURE PROCESS UNIT LINE/GASKET FAILURE	HEXANE		LBS
EXXON CHEMICAL	19920319	VALVE	PIPELINE IN PROCESS AREA/BLOCK VALVE LEAKING PIPELINE IN PROCESS AREA/ BLOCK VALVE LEAKING.	HEXANE		LBS
EXXON CHEMICAL	19920415		ROD OUT TOOL ON PROCESS UNIT/PACKING LEAK	1-HEXENE	0	NON
EXXON CHEMICAL	19920502		SAFETY VALVE/BELLOWS FAILURE.	HEXANE	0	NON
EXXON CHEMICAL	19920508		STORAGE TANK/UNBOLTING FLANGE WHEN PRODUCT SPILLED	CARBON BLACK OIL BOTTOMS	0	NON
EXXON CHEMICAL	19920513		PROCESS VESSEL IN UNIT/VALVE FAILURE	HEXANE	0	NON



EXXON CHEMICAL	19920513		PIPING IN FACILITY HAD MATERIAL SPILL DURING MAINTENANCE	HEXANE	0	NON
EXXON CHEMICAL	19920516		FEED PUMP/OPERATOR ERROR	HEXANE	0	NON
EXXON CHEMICAL	19920518		4" PIPELINE / LEAKED	HEXANE	0	NON
EXXON CHEMICAL	19920519		PROCESS UNIT/SAFETY VALVE RELEASED DUE TO HIGH PRESSURE	HEXANE	0	NON
EXXON CHEMICAL	19920519		PROCESS UNIT LINE/LEAKING FLANGE	HEXANE	0	NON
EXXON CHEMICAL	19920526	IMPROPER MAINTENANCE	6 INCH PROCESS LINE/RESIDUAL SPILLED DURING REPAIR 6 INCH PROCESS LINE/RESIDUAL SPILLED DURING REPAIR	HEXANE		GAL
EXXON CHEMICAL	19920528		PROCESS UNIT/BLEW PUMP SEAL	HEXANE	0	NON
EXXON CHEMICAL	19920529		ON SITE TRANSPORT TRUCK/UNKNOWN LEAK IN TANK OF TRUCK	PROCESSED WASTE WATER	0	NON
EXXON CHEMICAL	19920531		PUMP / SEAL FAILURE	METHYL CHLORIDE	0	NON
EXXON CHEMICAL	19920602		6" PIPE/OPENED WITH SOME PRODUCT STILL IN LINE	HEXANE	0	NON
EXXON CHEMICAL	19920605		EXCHANGER / GASKET FAILURE	HEXANE	0	NON
EXXON CHEMICAL	19920621		FEED TANK//MATERIAL GOT ONTO THE OUTSIDE OF THE TANK	BENZENE	0	NON
EXXON CHEMICAL	19920722	TANK OR CONTAINER	ROOF DRAIN LINE ON EXTERNAL FLOATING ROOF TANK/LEAKING LINE ROOF DRAIN LINE ON EXTERNAL FLOATING ROOF TANK / LEAKING LINE	HEXANE		UNK
EXXON CHEMICAL	19920722	OVERFLOW	MIXING DRUM ON PROCESSING UNIT/OVERFLOW DUE TO OPERATOR ERROR MIXING DRUM ON PROCESSING UNIT/OVERFLOW DUE TO OPERATOR ERROR	HEXANE(CONTAINED IN RUBBER CEMEN		LBS
EXXON CHEMICAL	19920802		A PUMP HAD A VALVE LEFT OPEN A PUMP HAD A VALVE LEFT OPEN	HEXANE (C-6 TO C-9 OLEFIN MATERI		LBS

EXXON CHEMICAL	19920803		PROCESS UNIT/LEAKED DUE TO PRESSURE UPSET PROCESS UNIT / LEAKED DUE TO PRESSURE UPSET	HYDROCHLORIC ACID		LBS
EXXON CHEMICAL	19920803		PROCESS UNIT/LEAKED DUE TO PRESSURE UPSET PROCESS UNIT / LEAKED DUE TO PRESSURE UPSET	HEXANE	0	LBS
EXXON CHEMICAL	19920805	IMPROPER MAINTENANCE	PROCESS PIPING/MATERIAL SPILLED DURING REPAIRS PROCESS PIPING / MATERIAL SPILLED DURING REPAIRS	QUENCH OIL		LBS
EXXON CHEMICAL	19920805	PUMP	PROCESS UNIT PUMP/SEAL FAILED PROCESS UNIT PUMP/SEAL FAILED	BUTADIENE		LBS
EXXON CHEMICAL	19920810	FITTING	PIN HOLE LEAK IN PROCESS UNIT PIN HOLE LEAK IN PROCESS UNIT	HEXANE		LBS
EXXON CHEMICAL	19920812	PUMP	PUMP SEAL FAILURE/EQUIPMENT FAILURE PUMP SEAL FAILURE/EQUIPMENT FAILURE	BUTADIENE		LBS
EXXON CHEMICAL	19920820		PROCESS UNIT HAD A VALVE LEAK	HEXANE	0	NON
EXXON CHEMICAL	19920821	IMPROPER OPERATION	ROLL-OFF BIN/WHILE LOADING,MATERIAL SPILLED FROM TAILGATE ROLL OFF BIN / WHILE LOADING MATERIAL SPILLED FROM TAILGATE	WATER CONTAMINATED WITH LEAD		LBS
EXXON CHEMICAL	19920821	VALVE	PROCESS VESSEL/VALVE LEAKING PROCESS VESSEL/ VALVE LEAKING	HEXANE		LBS
EXXON CHEMICAL	19920829		VAPOR RECOVERY SYSTEM / COMPRESSOR FAILED	BENZENE	0	NON
EXXON CHEMICAL	19920830		STORAGE TANK/VENTED DUE TO FAILURE	HEXANE	0	NON
EXXON CHEMICAL	19920831		CHLORINE CYLINDER/VALVE LEAKING	CHLORINE	0	NON
EXXON CHEMICAL	19920831		ANALYZER VENTS/ SOLENOID VALVE WAS INCORRECTLY WIRED	BUTADIENE	0	NON
EXXON CHEMICAL	19920903		PROCESS PIPING / MATERIAL SPILLED DURING REPAIRS	HEXANE	0	NON

EXXON CHEMICAL	19920907		PROCESS PIPE/LEAKED	METHYL TERT-BUTYL ETHER	0	NON
EXXON CHEMICAL	19920925		STORAGE TANK / CLOGGED HOSE	TANK BOTTOM SLUDGE (D018)		UNK
EXXON CHEMICAL	19920926		DRAINLINE ON WASTEWATER TANK//CORROSION	WASTE WATER		UNK
EXXON CHEMICAL	19921005	HOSE	CONTRACTOR VEHICLE/RUPTURED RADIATOR HOSE CONTRACTOR VEHICLE/RUPTURED RADIATOR HOSE	ETHYLENE GLYCOL		LBS
EXXON CHEMICAL	19921008	PUMP	PUMP ON PROCESS UNIT / GASKET FAILURE PUMP ON PROCESS UNIT/GASKET FAILURE	BORON TRIFLOURIDE MIXTURE		LBS
EXXON CHEMICAL	19921020	CONTAINER LEAK	PLUG LINE / LEAKED MATERIAL PLUG LINE LEAKED MATERIAL	HEXANE		LBS
EXXON CHEMICAL	19921104		PROCESS UNIT/MAT.DISCOVERED IN IT POSSIBLY VALVE MALFUNCTION PROCESS UNIT/MAT.DISCOVERED IN IT/POSSIBLY VALVE MALFUNCTION	HEXANE		LBS
EXXON CHEMICAL	19921113		SEAL ON A PUMPED FAILED	BUTADIENE	0	NON
EXXON CHEMICAL	19921124	VALVE	SAFETY VALVE BYPASS/LEAKING VALVES ALLOWED MAT.TO ENTER FLARE SAFETY VALVE BYPASS/LEAKING VALVES ALLOWED MAT.TO ENTER FLARE	HYDROCHLORIC ACID		LBS
EXXON CHEMICAL	19921201	PUMP	PUMP TO PROCESS UNIT /HEAD GASKET FAILED PUMP TO PROCESS UNIT/HEAD GASKET FAILED	BORON TRIFLUORIDE		LBS
EXXON CHEMICAL	19921202		CALLER DISCOVERED A POOL OF LIQUID HYDROCARBONS CALLER DISCOVERED A POOL OF LIQUID HYDROCARBONS	HEXANE		LBS
EXXON CHEMICAL	19921214	FITTING	PROCESS UNIT PIPING / LEAKED PROCESS UNIT PIPING/LEAKED	HEXANE		LBS
EXXON CHEMICAL	19921230	IMPROPERLY SECURED FLANGE	PUMP / FLANGE NOT TIGHTENED PROPERLY PUMP/FLANGE NOT TIGHTENED PROPERLY	HEXANE		LBS

EXXON CHEMICAL	19930101	PUMP	PUMP SEAL / FAILED PUMP SEAL/FAILED	BENZENE HYDROCARBON MIX (CONT.	LBS
EXXON CHEMICAL	19930112		STORAGE TANK / OPEN TAP STORAGE TANK/OPEN TAP	HEXANE	UNK
EXXON CHEMICAL	19930118	FITTING	PROCESS SEWER SYSTEM/PROCESS UPSET PROCESS SEWER SYSTEM/PROCESS UPSET	HEXANE	LBS
EXXON CHEMICAL	19930120	RAIN OR SNOW	A RAINWATER DETENTION TANK OVERFLOWED DUE TO RAINFALL A RAINWATER DETENTION TANK OVERFLOWED DUE TO RAINFALL	WASTE WATER CONTAINING OIL	UNK
EXXON CHEMICAL	19930121		THERE IS A BAD SMELL IN THE AIR THERE IS A BAD SMELL IN THE AIR	UNKNOWN	UNK
EXXON CHEMICAL	19930201	PIPELINE	PIPING AT WASTE WATER TREATMENT PLANT/CORROSION PIPING AT WASTE WATER TREATMENT PLANT/CORROSION	UNTREATED WASTE WATER (D018 HAZM	LBS
EXXON CHEMICAL	19930207	VALVE	PROCESS UNIT / VALVE LEAKED PROCESS UNIT/VALVE LEAKED	HEXANE	LBS
EXXON CHEMICAL	19930208	PUMP	PROCESSING PUMP / SEAL FAILURE PROCESSING PUMP/SEAL FAILURE	BUTADIENE	LBS
EXXON CHEMICAL	19930209		WASTE WATER TREATMENT PLANT / UNKNOWN WASTE WATER TREATMENT PLANT/UNKNOWN	HEXANE	LBS
EXXON CHEMICAL	19930217	VALVE	PIPING LINE / BLOCK VALVE FAILED PIPING LINE / BLOCK VALVE FAILED	HEXANE	LBS
EXXON CHEMICAL	19930227		ABOVE GROUND STORAGE TANK / PROCESS UPSET ABOVE GROUND STORAGE TANK / PROCESS UPSET	HEXANE	LBS
EXXON CHEMICAL	19930302	PIPELINE	BREAK IN A WELD/8"TO10"LINE, CAUSE UNKNOWN BREAK IN A WELD/8"TO 10" LINE, CAUSE UNKNOWN	SULFURIC ACID	0 UNK

EXXON CHEMICAL	19930303		WASTE WATER PLANT PIPING/SPILL, POSSIBLY DUE TO CORROSION WASTE WATER PLANT PIPING/SPILL, POSSIBLY DUE TO CORROSION	D018 HAZ WASTE WATER		LBS
EXXON CHEMICAL	19930304		OVERPRESSURE STACK ON STORAGE TANK / PRESSURE SURGE OVERPRESSURE STACK ON STORAGE TANK / PRESSURE SURGE	HEXANE		LBS
EXXON CHEMICAL	19930312		HEAT EXCHANGER / LEAKING HEAD GASKET	HEXANE	0	NON
EXXON CHEMICAL	19930317	IMPROPER VALVE HANDLING	BLEEDER VALVE / VALVE LEFT OPEN BLEEDER VALVE/VALVE LEFT OPEN	HEXANE		LBS
EXXON CHEMICAL	19930324	OVERFLOW	55-GALLON DRUM, OVERFILLED THE DRUM 55 GAL DRUM/OVERFILLED THE DRUM	HEXANE	0	LBS
EXXON CHEMICAL	19930401		PROCESS SYSTEM VENTED TO PREVENT OVERPRESSURIZATION (EQUIPMENT FAILURE)	VINYL ACETATE	0	NON
EXXON CHEMICAL	19930401		PROCESS SYSTEM VENTED TO PREVENT OVERPRESSURIZATION (EQUIPMENT FAILURE)	ETHYLENE	0	NON
EXXON CHEMICAL	19930404	FITTING	WATER SEAL LEG ON A VENT TO A PROCESS VESSEL/WATER SEAL FAILED WATER SEAL LEG ON A VENT TO A PROCESS VESSEL/WATER SEAL FAILED	BENZENE	0	LBS
EXXON CHEMICAL	19930404	FITTING	WATER SEAL LEG ON A VENT TO A PROCESS VESSEL/WATER SEAL FAILED WATER SEAL LEG ON A VENT TO A PROCESS VESSEL/WATER SEAL FAILED	HEXANE	0	
EXXON CHEMICAL	19930418		EXCHANGER HEAD / LEAKED EXCHANGER HEAD/LEAKED	HEXANE	0	LBS
EXXON CHEMICAL	19930418		EXCHANGER HEAD / LEAKED EXCHANGER HEAD/LEAKED	BENZENE	0	
EXXON CHEMICAL	19930424	FITTING	HEXANE PROCESS REACTOR AGITATOR SEAL/LEAKED HEXANE PROCESS REACTOR AGITATOR SEAL/LEAKED	HEXANE	0	LBS

EXXON CHEMICAL	19930427		PROCESS UNIT PIPING/BLOCK VALVE AND BLEEDER VALVE FAILURE	HEXANE	0	NON
EXXON CHEMICAL	19930427	VALVE	PROCESS UNIT PIPING/BLOCK VALVE AND BLEEDER VALVE FAILURE PROCESS UNIT PIPING/BLOCK VALVE AND BLEEDER VALVE FAILURE	HEXANE	0	LBS
EXXON CHEMICAL	19930517		ROLL-OFF BIN CONTAINING WASTE/LEAKED WHILE BEING MOVED ROLL OFF BIN CONTAINING WASTE/LEAKED WHILE BEING MOVED	BENZENE	0	LBS
EXXON CHEMICAL	19930518	BROKEN CONTAINERS	STORAGE TANK/ VENTED DUE TO BROKEN GASKET STORAGE TANK/VENTED DUE TO BROKEN GASKET	HEXANE	0	UNK
EXXON CHEMICAL	19930524		TUBE ON A HEAT EXCHANGER / UNKNOWN TUBE ON A HEAT EXCHANGER/UNKNOWN	HEXANE	0	LBS
EXXON CHEMICAL	19930610	FLANGE	PROCESS PIPE AT THE FACILITY WAS LEAKING FROM A FLANGE A PROCESS PIPE AT THE FACILITY WAS LEAKING FROM A FLANGE	OTHER OIL (GAS OIL)	0	LBS
EXXON CHEMICAL	19930629		TRANSFER HOSE / CAUSE UNKNOWN TRANSFER HOSE / CAUSE UNKNOWN	COBALT COMPOUNDS	0	LBS
EXXON CHEMICAL	19930702	CONTAINER LEAK	PROCESS PIPING/LEAKED DUE TO A PIN HOLE PROCESS PIPING/LEAKED DUE TO A PINHOLE	COBALT ACETATE (OUS)	0	LBS
EXXON CHEMICAL	19930707	CONTAINER LEAK	6 INCH PIPING ON A REACTOR/PIN HOLE LEAK DEVELOPED IN PIPING 6 INCH PIPING ON A REACTOR/ PIN HOLE LEAK DEVELOPED IN PIPING	HEXANE	0	LBS
EXXON CHEMICAL	19930718	TANK OR CONTAINER	ABOVE GROUND WASTEWATER TANK / CORROSION ABOVE GROUND WASTEWATER TANK / CORROSION	LOW PH WASTE WATER	0	LBS
EXXON CHEMICAL	19930730		SUSPECTED UNDERGROUND PIPELINE/LEAKING DUE TO UNKNOWN CAUSE SUSPECTED UNDERGROUND PIPELINE/LEAKING DUE TO UNKNOWN CAUSE	PROCESSED GAS OIL	0	LBS

EXXON CHEMICAL	19930730		EXCHANGER HEAD GASKET/ LEAKING DUE TO UNKNOWN REASONS EXCHANGER HEAD GASKET/LEAKING DUE TO UNKOWN REASONS	HEXENE	0	LBS
EXXON CHEMICAL	19930730		EXCHANGER HEAD GASKET/ LEAKING DUE TO UNKNOWN REASONS EXCHANGER HEAD GASKET/LEAKING DUE TO UNKOWN REASONS	1,3-PENTADIENE	0	
EXXON CHEMICAL	19930806	FLANGE	A HEAT EXCHANGER HEAD GASKET HAD A FLANGE LEAK A HEAT EXCHANGER HEAD GASKET HAD A FLANGE LEAK	HEXANE	0	LBS
EXXON CHEMICAL	19930806	FLANGE	A HEAT EXCHANGER HEAD GASKET HAD A FLANGE LEAK A HEAT EXCHANGER HEAD GASKET HAD A FLANGE LEAK	1,3-PENTADIENE	0	
EXXON CHEMICAL	19930806	FLANGE	A HEAT EXCHANGER HEAD GASKET HAD A FLANGE LEAK A HEAT EXCHANGER HEAD GASKET HAD A FLANGE LEAK	ISOPRENE	0	LBS
EXXON CHEMICAL	19930809	PIPELINE	ELEVATED TRANSFER LINE / EXTERNAL CORROSION ELEVATED TRANSFER LINE/ EXTERNAL CORROSION	POLYCYCLIC ORGANIC MATERIAL	0	LBS
EXXON CHEMICAL	19930811	PUMP	PUMP / SEAL LEAK PUMP /SEAL LEAK	BENZENE	0	LBS
EXXON CHEMICAL	19930813		CHECK VALVE WITHIN THE PROCESS PIPING/POSSIBLY A FLANGE LEAK CHECK VALVE WITHIN THE PROCESS PIPING/POSSIBLY A FLANGE LEAK	METHYL CHLORIDE	130	LBS
EXXON CHEMICAL	19930915	PUMP	STORAGE TANK / PUMP SEAL FAILURE STORAGE TANK/PUMP SEAL FAILURE	HEXANE	0	LBS
EXXON CHEMICAL	19930915		ABOVE GROUND STORAGE DRUM/VALVE WAS LEFT IN THE OPEN POSITION STORAGE DRUM/VALVE WAS LEFT IN THE OPEN POSITION	HEXANE	0	LBS
EXXON CHEMICAL	19930920	VALVE	FLANGE ON BLOCK VALVE, CAUSE OF RELEASE IS UNKNOWN FLANGE ON BLOCK VALVE / CAUSE OF RELEASE IS UNKNOWN	HEXANE	0	LBS

EXXON CHEMICAL	19931008	CONTAINER LEAK	BLOCK VALVE ON FACILITY FEED LINE/ BONNET GASKET LEAKING BLOCK VALVE ON FACILITY FEED LINE/ BONNET GASKET LEAKING	BENZENE	0	LBS
EXXON CHEMICAL	19931008	CONTAINER LEAK	BLOCK VALVE ON FACILITY FEED LINE/ BONNET GASKET LEAKING BLOCK VALVE ON FACILITY FEED LINE/ BONNET GASKET LEAKING	HEXANE	0	
EXXON CHEMICAL	19931010	PIPELINE	OIL TRANSPORT LINE / GASKET FAILURE OIL TRANSPORT LINE /GASKET FAILURE	POLYCYCLIC ORGANIC MATTER	0	LBS
EXXON CHEMICAL	19931020	FLANGE	HEAT EXCHANGER / FLANGE LEAKED HEAT EXCHANGER / FLANGE LEAKED	HEXANE	0	LBS
EXXON CHEMICAL	19931021	VALVE	PROCESS VESSEL //LEAKED DUE TO AN OPEN PROCESS VALVE PROCESS VESSEL//LEAKED DUE TO AN OPEN PROCESS VALVE	HEXANE	0	LBS
EXXON CHEMICAL	19931021	VALVE	PROCESS VESSEL //LEAKED DUE TO AN OPEN PROCESS VALVE PROCESS VESSEL//LEAKED DUE TO AN OPEN PROCESS VALVE	METHYL CHLORIDE	0	
EXXON CHEMICAL	19931101	VALVE	A TRANSFER LINE HAD A VALVE LEAK A TRANSFER LINE HAD A VALVE LEAK	HEXANE	0	LBS
EXXON CHEMICAL	19931118		HYDROCARBON LINE//LEAKED DUE TO UNKNOWN REASONS	METHYL TERT-BUTYL ETHER	0	NON
EXXON CHEMICAL	19931123		PIPING IN PROCESSING UNIT/RELEASE IS DUE TO LEAKING AROUND PACKING AND GASKETS	BUTADIENE	0	NON
EXXON CHEMICAL	19931213	IMPROPER OPERATION	2 INCH LINE/RELEASE OCCURRED WHEN LINE WAS MISTAKENLY OPEN 2 INCH LINE/RELEASE OCCURRED WHEN LINE WAS MISTAKENLY OPEN	HEXANE	0	LBS
EXXON CHEMICAL	19931220	PUMP	PUMP FOR PROCESS UNIT / CRACKED OILER ROD PUMP FOR PROCESS UNIT/CRACKED OILER ROD	BORON TRIFLUORIDE	0	LBS



EXXON CHEMICAL	19931228	FITTING	PROCESS FLARE RUPTURED DISC AT FEED ANALYZER LEADING TO FLARE PROCESS FLARE RUPTURED DISC AT FEED ANALYZER LEADING TO FLARE	BUTADIENE	0	LBS
EXXON CHEMICAL	19931229		A COMPRESSOR HAD AN INSTRUMENT AIR LINE CUT BY ACCIDENT**** A COMPRESSOR HAD AN INSTRUMENT AIR LINE CUT BY ACCIDENT ****	METHYL CHLORIDE	0	LBS
EXXON CHEMICAL	19931229		A COMPRESSOR HAD AN INSTRUMENT AIR LINE CUT BY ACCIDENT**** A COMPRESSOR HAD AN INSTRUMENT AIR LINE CUT BY ACCIDENT ****	HYDROGEN CHLORIDE	0	
EXXON CHEMICAL	19931231	CONTAINER LEAK	LEAKING SEAL ON PROCESS VESSEL / CAUSE UNKNOWN LEAKING SEAL ON PROCESS VESSEL/ CAUSE UNKNOWN	HEXANE	0	LBS
EXXON CHEMICAL	19940105	CONTAINER LEAK	VENT LINE//LEAKED DUE TO BEING LEFT OPEN VENT LINE//LEAKED DUE TO BEING LEFT OPEN	HEXANE	0	LBS
EXXON CHEMICAL	19940105	FITTING	FLARE STACK, COMPRESSOR FAILED RESULTING IN VENTING GAS STREAM FLARE STACK / COMPRESSOR FAILED RESULTING IN VENTING GAS STREAM	BUTADIENE	0	LBS
EXXON CHEMICAL	19940106	IMPROPER MAINTENANCE	5-GAL BUCKET,RELEASE OCCURRED WHEN MATERIAL SPILLED>MAINTENANCE 5-GAL BUCKET,RELEASE OCCURRED WHEN MATERIAL SPILLED>MAINTENANCE	HEXANE	0	LBS
EXXON CHEMICAL	19940107	FITTING	SEAL ON A DISPERSER D-115B,RELEASE DUE TO RUPTURED SEAL SEAL ON A DISPERSER D-115B/RELEASE IS DUE TO RUPTURED SEAL	HEXANE	0	LBS
EXXON CHEMICAL	19940108	POWER FAILURE	PROCESSING UNIT/POWER UPSET CAUSED A VENT TO TRIP PROCESSING UNIT/POWER UPSET CAUSED A VENT TO TRIP	HYDROGEN SULFIDE	0	LBS

EXXON CHEMICAL	19940108	POWER FAILURE	PROCESSING UNIT/POWER UPSET CAUSED A VENT TO TRIP PROCESSING UNIT/POWER UPSET CAUSED A VENT TO TRIP	CARBON MONOXIDE	0	
EXXON CHEMICAL	19940112	FITTING	HEAT EXCHANGER IN CHEMICAL PROCESS/GASKET FAILURE HEAT EXCHANGER IN CHEMICAL PROCESS / GASKET FAILURE	HEXANE	0	LBS
EXXON CHEMICAL	19940128	HOSE	HOSE COUPLING ON TANK TRUCK BROKE LOOSE DURING CLEANING HOSE COUPLING ON TANK TRUCK BROKE LOOSE DURING CLEANING	BENZENE	0	LBS
EXXON CHEMICAL	19940206	CONTAINER LEAK	PROCESSING LINE/ LEAKED DUE TO EXTERNAL CORROSION PROCESSING LINE/LEAKED DUE EXTERNAL CORROSION	BUTADIENE	0	LBS
EXXON CHEMICAL	19940206	CONTAINER LEAK	PROCESSING LINE/ LEAKED DUE TO EXTERNAL CORROSION PROCESSING LINE/LEAKED DUE EXTERNAL CORROSION	BENZENE	0	
EXXON CHEMICAL	19940225		2 INCH PIPE/RESIDUAL MAT RELEASED FROM VENT LINE>UNK CAUSES 2 INCH PIPE/RESIDUAL MAT RELEASED FROM VENT LINE>UNK CAUSES	HEXANE	0	UNK
EXXON CHEMICAL	19940301	PUMP	BLOWN PUMP SEAL BLOWN PUMP SEAL	HEXANE	0	UNK
EXXON CHEMICAL	19940301	PUMP	BLOWN PUMP SEAL BLOWN PUMP SEAL	BENZENE	0	UNK
EXXON CHEMICAL	19940318	PUMP	PUMP/ SEAL LEAKED DUE TO UNKNOWN CAUSES PUMP/SEAL LEAKED DUE TO UNKNOWN CAUSES	BENZENE	0	UNK
EXXON CHEMICAL	19940330	VALVE	WASTE CONTAINMENT TANK FLANGE//LEAKED DUE TO VALVE FAILURE WASTE CONTAINMENT TANK FLANGE//LEAKED DUE TO A VALVE FAILURE	UNTREATED WASTE WATER	0	UNK
EXXON CHEMICAL	19940401	PUMP	PUMP ON PROCESS UNIT / SEAL FAILED PUMP ON PROCESS UNIT / SEAL FAILED	BUTADIENE	0	UNK

EXXON CHEMICAL	19940406	VALVE	TOWER IN PROCESS UNIT/SAFETY VALVE RELEASED,CAUSE UNKNOWN TOWER IN PROCESS UNIT,SAFETY VALVE RELEASED, CAUSE UNKNOWN	METHALLYL CHLORIDE	0	UNK
EXXON CHEMICAL	19940406	VALVE	TOWER IN PROCESS UNIT/SAFETY VALVE RELEASED,CAUSE UNKNOWN TOWER IN PROCESS UNIT,SAFETY VALVE RELEASED, CAUSE UNKNOWN	HYDROCHLORIC ACID	0	UNK
EXXON CHEMICAL	19940406	POWER FAILURE	PROCESS UNIT TOWER/SAFETY VALVE OPENED DURING POWER FAILURE PROCESS UNIT TOWER//SAFETY VALVE OPENED DURING POWER FAILURE	HEXANE	0	UNK
EXXON CHEMICAL	19940424	PIPELINE	LINE IN PROCESS UNIT/DEVELOPED HOLE, UNKNOWN CAUSE LINE IN PROCESS UNIT/DEVELOPED HOLE, UNKNOWN CAUSE	RESIN(NORMAL HEXANE)	0	UNK
EXXON CHEMICAL	19940425	FITTING	PROCESS UNIT/RUPTURE DISK FAILED ON REACTOR,RELEASING MAT. PROCESS UNIT/RUPTURE DISK FAILED ON REACTOR,RELEASING MAT.	O-XYLENE	0	UNK
EXXON CHEMICAL	19940501	PIPELINE	2 INCH OVERHEAD LINE/HOLE DEVELOPED IN LINE DUE TO CORROSION 2 INCH OVERHEAD LINE/HOLE DEVELOPED IN LINE DUE TO CORROSION	HEXANE	0	UNK
EXXON CHEMICAL	19940501	PIPELINE	2 INCH OVERHEAD LINE/HOLE DEVELOPED IN LINE DUE TO CORROSION 2 INCH OVERHEAD LINE/HOLE DEVELOPED IN LINE DUE TO CORROSION	BENZENE	0	UNK
EXXON CHEMICAL	19940502		FLARE / CAUSE OF FLARE ACTIVATION IS BEING INVESTIGATED	BUTADIENE	0	NON
EXXON CHEMICAL	19940516	OVERFLOW	SUMPS/OVEFLOW DUE TO HEAVY RAINS,PUMPS ALSO FAILED>POWERFAIL SUMPS/OVERFLOW DUE TO HEAVY RAINS,PUMPS ALSO FAILED>POWERFAIL	HEXANE	0	UNK

EXXON CHEMICAL	19940517	LIGHTNING	REACTOR/ELECTRICAL STORM CAUSED RELEASE REACTOR/ELECTRICAL STORM CAUSED RELEASE	ETHYLENE	0	UNK
EXXON CHEMICAL	19940520	IMPROPER OPERATION	WASTEWATER SEWER SYSTEM/BROKE PIPE DURING CONSTRUCTION WASTEWATER SEWER SYSTEM/BROKE PIPE DURING CONSTRUCTION	POLYCYCLIC	0	UNK
EXXON CHEMICAL	19940520	IMPROPER OPERATION	WASTEWATER SEWER SYSTEM/BROKE PIPE DURING CONSTRUCTION WASTEWATER SEWER SYSTEM/BROKE PIPE DURING CONSTRUCTION	BENZENE	0	UNK
EXXON CHEMICAL	19940527	PUMP	A SEAL FAILED ON A PUMP IN A PROCESSING UNIT A SEAL FAILED ON A PUMP IN A PROCESSING UNIT	HEXANE	0	UNK
EXXON CHEMICAL	19940527	PUMP	A SEAL FAILED ON A PUMP IN A PROCESSING UNIT A SEAL FAILED ON A PUMP IN A PROCESSING UNIT	ISOPRENE	0	UNK
EXXON CHEMICAL	19940605	PIPELINE	UNLOADING LINE/LIQUID WAS TRAPPED IN LINE & RELEASED>VENT UNLOADING LINE/LIQUID WAS TRAPPED IN LINE & RELEASED>VENT	HEXANE	0	UNK
EXXON CHEMICAL	19940607	HOSE	HOSE/DRAINING MAT TO PROCESS SEWER DISENGAGED,SPILING>GROUND HOSE DRAINING MAT TO PROCESS SEWER DISENGAGED,SPILLING>GROUND	POLYCYCLIC ORGANIC MATTER W/ PRO	0	UNK
EXXON CHEMICAL	19940628	PIPELINE	3/4 INCH PIPELINE // PLUG BLEW CAUSING SPILL 3/4 INCH PIPELINE // PLUG BLEW CAUSING SPILL	ESCOREZ RAFFINATE	0	UNK
EXXON CHEMICAL	19940704	CONTAINER LEAK	LEAKING PLUG ON A METER LEAKING PLUG ON A METER	BROMINE	0	UNK
EXXON CHEMICAL	19940708	RAIN OR SNOW	SUMP/SUMP OVERFLOWED DUE TO HEAVY RAIN SUMP/SUMP OVERFLOWED DUE TO HEAVY RAIN	UNKNOWN OIL	0	UNK
EXXON CHEMICAL	19940728	IMPROPER VALVE HANDLING	PROCESS CONTACTOR/LEAKED DURING REMOVAL OF BLOCK VALVE PROCESS CONTACTOR//LEAKED DURING REMOVAL OF BLOCK VALVE	HEXANE	0	UNK

EXXON CHEMICAL	19940731	CONTAINER LEAK	PIPING FITTING / LEAKED PIPING FITTING/LEAKED	BROMENE	0	UNK
EXXON CHEMICAL	19940823		PROCESS PIPING HAD RESIDUAL MAT IN IT/RELEASED>MAINTENANCE PROCESS PIPING HAD RESIDUAL MAT IN IT/RELEASED>MAINTENANCE	HEXANE	0	UNK
EXXON CHEMICAL	19940912	PIPELINE	PROCESS LINE/LINE DAMAGED DURING FIRE AND LEAKED DURING** PROCESS LINE/LINE DAMAGED DURING FIRE AND LEAKED DURING**	LEAN OIL	0	UNK
EXXON CHEMICAL	19940912	PIPELINE	PROCESS LINE/LINE DAMAGED DURING FIRE AND LEAKED DURING** PROCESS LINE/LINE DAMAGED DURING FIRE AND LEAKED DURING**	BUTADIENE	0	UNK
EXXON CHEMICAL	19940912	PIPELINE	PROCESS LINE/LINE DAMAGED DURING FIRE AND LEAKED DURING** PROCESS LINE/LINE DAMAGED DURING FIRE AND LEAKED DURING**	BENZENE	0	UNK
EXXON CHEMICAL	19940912		UNKNOWN/UNKNOWN //FOUND OIL ON SOIL UNKNOWN//UNKNOWN//FOUND OIL ON SOIL	BENZENE	0	UNK
EXXON CHEMICAL	19940912		UNKNOWN/UNKNOWN //FOUND OIL ON SOIL UNKNOWN//UNKNOWN//FOUND OIL ON SOIL	HEXENE	0	UNK
EXXON CHEMICAL	19940912		UNKNOWN/UNKNOWN //FOUND OIL ON SOIL UNKNOWN//UNKNOWN//FOUND OIL ON SOIL	POLYCYCLIC ORGANIC MATERIAL	0	UNK
EXXON CHEMICAL	19940914		PROCESS LINE // DAMAGED TO FIRE PROCESS LINE//DAMAGED TO FIRE	BENZENE	0	UNK
EXXON CHEMICAL	19940914		PROCESS LINE // DAMAGED TO FIRE PROCESS LINE//DAMAGED TO FIRE	UNKNOWN OIL	0	UNK
EXXON CHEMICAL	19940929	FLANGE	FLANGE ON HEAT EXCHANGER, LEAKED DUE TO UNKNOWN CAUSES FLANGE ON HEAT EXCHANGER,LEAKED DUE TO UNKNOWN CAUSES	METHYL TERT-BUTYL ETHER	0	UNK

EXXON CHEMICAL	19941004	PIPELINE	6 INCH PIPELINE IS LEAKING DUE TO UNKNOWN CAUSES 6 INCH PIPE/LINE IS LEAKING DUE TO UNKNOWN CAUSES	HEXANE	0	UNK
EXXON CHEMICAL	19941009	VALVE	BLOCK VALVE / MECHANICAL FAILURE BLOCK VALVE / MECHANICAL FAILURE	HEXANE	0	UNK
EXXON CHEMICAL	19941015	VALVE	OIL FEED DRUM BLOCK VALVE PACKING FAILED OIL FEED DRUM BLOCK VALVE PACKING FAILED	POLYCYCLIC ORGANIC MATERIAL	0	UNK
EXXON CHEMICAL	19941024	PUMP	PUMP HAD A SEAL LEAK PUMP HAD A SEAL LEAK	1,3 BUTADIENE	0	UNK
EXXON CHEMICAL	19941027	FITTING	SIGHT GLASS ON TOWER / CRACKED SIGHT GLASS ON TOWER/CRACKED	BUTADIENE	0	UNK
EXXON CHEMICAL	19941029		STORAGE TANKS/ VAPOR RECOVERY SYSTEM FAILED DUE TO POWER FAILURE ON CONTROLS	BENZENE/ 47 LBS PER HOUR	0	UNK
EXXON CHEMICAL	19941029		STORAGE TANKS/ VAPOR RECOVERY SYSTEM FAILED DUE TO POWER FAILURE ON CONTROLS	HEXANE// 4 LBS PER HOUR	0	UNK
EXXON CHEMICAL	19941029		HEAT EXCHANGER IN A PROCESS UNIT/A GASKET BEGAN TO LEAK	HEXANE	0	NON
EXXON CHEMICAL	19941104	PUMP	PRESSURE GUAGE ON A PUMP / THE GUAGE BLEW OUT PRESSURE GAUGE ON A PUMP/THE GAUGE BLEW OUT	HEXANE	0	LBS
EXXON CHEMICAL	19941113	PUMP	PUMP FROM PROCESSING UNIT TO STORAGE TANK HAD SEAL LEAK PUMP FROM A PROCESSING UNIT TO A STORAGE TANK HAD A SEAL LEAK	HEXANE	0	UNK
EXXON CHEMICAL	19941113	PUMP	PUMP FROM PROCESSING UNIT TO STORAGE TANK HAD SEAL LEAK PUMP FROM A PROCESSING UNIT TO A STORAGE TANK HAD A SEAL LEAK	BENZENE	0	UNK
EXXON CHEMICAL	19941114		UNKNOWN/HIGHER THAN NORMAL VAPORS COMING FROM WASTEWATER UNKNOWN/HIGHER THAN NORMAL VAPORS COMING FROM WASTEWATER	VAPORS FROM WASTE WATER	0	UNK

EXXON CHEMICAL	19941114		UNKNOWN/HIGHER THAN NORMAL VAPORS COMING FROM WASTEWATER UNKNOWN/HIGHER THAN NORMAL VAPORS COMING FROM WASTEWATER	HEXANE	0	UNK
EXXON CHEMICAL	19941120	CONTAINER LEAK	PROCESS VESSEL D101/LEAKED DUE TO UNKNOWN CAUSES PROCESS VESSEL D201/LEAKED DUE TO UNKNOWN CAUSES	HEXANE	0	UNK
EXXON CHEMICAL	19941121	CONTAINER LEAK	PIN HOLE LEAK IN A 4 INCH TRANSFER LINE PIN HOLE LEAK IN A 4 INCH TRANSFER LINE	HEXANE	0	UNK
EXXON CHEMICAL	19941121	CONTAINER LEAK	PIN HOLE LEAK IN A 4 INCH TRANSFER LINE PIN HOLE LEAK IN A 4 INCH TRANSFER LINE	BENZENE	0	UNK
EXXON CHEMICAL	19941125		HOLE IN PROCESS PIPING/LEAKED	RESIN FEED	0	LBS
EXXON CHEMICAL	19950108	FITTING	UNKNOWN/UNKNOWN HYDROCARBON ALARM WENT OFF UNKNOWN/UNKNOWN/HYDROCARBON ALARM WENT OFF	HEXANE	0	UNK
EXXON CHEMICAL	19950121	VALVE	FAILED BLOCK LINE ON A BLOCK VALVE FAILED BLOCK LINE ON A BLOCK VALVE	HEXANE	0	UNK
EXXON CHEMICAL	19950121	VALVE	FAILED BLOCK LINE ON A BLOCK VALVE FAILED BLOCK LINE ON A BLOCK VALVE	VANADIUM OXITRICHLORIDE	0	UNK
EXXON CHEMICAL	19950130	PIPELINE	GROUND WATER REMEDIATION PIPING SYSTEM,CORROSION(APPROX 2 INCH) GROUND WATER REMEDIATION PIPING SYSTEM / CORROSION (APPROX. 2-IN PIPING)	D018 HAZWASTE (BENZENE)	17	LBS
EXXON CHEMICAL	19950214	FLANGE	PROCESSED PIPING, FAILURE OF A FLANGE PROCESSED PIPING/ FAILURE OF A FLANGE	CHLORINE	0	UNK
EXXON CHEMICAL	19950217	PUMP	LEAKAGE AROUND PRESSURE GUAGE ON SPLITTER BOTTOMS PUMP LEAKAGE AROUND PRESSURE GUAGE ON SPLITTER BOTTOMS PUMP	POLYCYCLIC ORGANIC MATTER	0	UNK

EXXON CHEMICAL	19950329	VALVE	TURBINE GENERATOR,STEAM INJECTION LOST,CONTROL VALVE MALFUN. TURBINE GENERATOR,STEAM INJECTION LOST,CONTROL VALVE MALFUNC.	NOX (NITROGEN DIOXIDE/NITROGEN OX	0	UNK
EXXON CHEMICAL	19950329	VALVE	TURBINE GENERATOR,STEAM INJECTION LOST,CONTROL VALVE MALFUN. TURBINE GENERATOR,STEAM INJECTION LOST,CONTROL VALVE MALFUNC.	SULFUR DIOXIDE	0	UNK
EXXON CHEMICAL	19950417	FITTING	ETHYLENE MANUFACTURING FACILITY, GAS TURBINE ON UNIT SLOWED ETHYLENE MANUFACTURING FACILITY,GAS TURBINE ON UNIT SLOWED	BENZENE	0	UNK
EXXON CHEMICAL	19950417	FITTING	ETHYLENE MANUFACTURING FACILITY, GAS TURBINE ON UNIT SLOWED ETHYLENE MANUFACTURING FACILITY,GAS TURBINE ON UNIT SLOWED	HEXANE	0	UNK
EXXON CHEMICAL	19950417	FITTING	ETHYLENE MANUFACTURING FACILITY, GAS TURBINE ON UNIT SLOWED ETHYLENE MANUFACTURING FACILITY,GAS TURBINE ON UNIT SLOWED	1,3-BUTADIENE	0	UNK
EXXON CHEMICAL	19950421	PIPELINE	4 INCH FEED LINE,RELEASED MATS DUE TO UNKNOWN REASONS 4 INCH FEED LINE,RELEASED MATS DUE TO UNKNOWN REASONS	BUTADIENE	0	UNK
EXXON CHEMICAL	19950422		1 INCH LINE PLUGGED, DRAINED BY COMPANY 1 INCH LINE PLUGGED, DRAINED BY COMPANY	HEXANE	0	LBS
EXXON CHEMICAL	19950505	VALVE	BLEEDER VALVE, LEFT OPEN BLEEDER VALVE / LEFT OPEN	HEXANE	0	UNK
EXXON CHEMICAL	19950602		FLARE STACK/FEED COMPRESSOR TRIPPED, CAUSES UNKNOWN FLARE STACK/FEED COMPREESSOR TRIPPED, CAUSES UNKNOWN	BUTADIENE	0	UNK



EXXON CHEMICAL	19950602		FLARE STACK/FEED COMPRESSOR TRIPPED, CAUSES UNKNOWN FLARE STACK/FEED COMPRESSOR TRIPPED, CAUSES UNKNOWN	BENZENE	0	UNK
EXXON CHEMICAL	19950602		FLARE STACK/FEED COMPRESSOR TRIPPED, CAUSES UNKNOWN FLARE STACK/FEED COMPRESSOR TRIPPED, CAUSES UNKNOWN	HEXANE	0	UNK
EXXON CHEMICAL	19950620	CONTAINER LEAK	PUMP SEAL LEAK, PROCESS UNIT PUMP SEAL LEAK //PROCESS UNIT	DIMETHYLFORMAMIDE	0	UNK
EXXON CHEMICAL	19950625	FIRE	DRUM 350 FIRE IN OXO ALCOHOL UNIT, UNKNOWN DRUM 350 FIRE IN OXO ALCOHOL UNIT, UNKNOWN	COBALT COMPOUNDS	0	UNK
EXXON CHEMICAL	19950627	CONTAINER LEAK	PROCESSED WATER DRUM #D120, DEVELOPED A LEAK PROCESSED WATER DRUM NO. D120 / DEVELOPED A LEAK	HEXANE	0	UNK
EXXON CHEMICAL	19950906	FITTING	ABOVE GROUND STORAGE TANK,PROCESS UIT D-100 FAILED,BACKUP>REL ABOVE GROUND STORAGE TANK,PROCESS UNITD-100 FAILED,BACKUP>REL	METHYL CHLORIDE	0	UNK
EXXON CHEMICAL	19951027	VALVE	SAFETY RELIEF VALVE TO A FLARE,VALVE CLOSED ON A COMPRESSOR SAFETY RELIEF VALVE TO A FLARE/VALVE CLOSED ON A COMPRESSOR/UNKNOWN	BUTADIENE	0	UNK
EXXON CHEMICAL	19951114	CONTAINER LEAK	1.5 INCH DRAIN LINE IN A LAB/EQUIPMENT FAILURE 1.5 INCH DRAIN LINE IN A LAB/EQUIPMENT FAILURE	D018 HAZARDOUS WASTE	0	UNK
EXXON CHEMICAL	19951114	CONTAINER LEAK	1.5 INCH DRAIN LINE IN A LAB/EQUIPMENT FAILURE 1.5 INCH DRAIN LINE IN A LAB/EQUIPMENT FAILURE	D001	0	UNK
EXXON CHEMICAL	19951114	CONTAINER LEAK	1.5 INCH DRAIN LINE IN A LAB/EQUIPMENT FAILURE 1.5 INCH DRAIN LINE IN A LAB/EQUIPMENT FAILURE	D035	0	UNK

EXXON CHEMICAL	19951115	FLANGE	A FLANGE ON HEAT EXCHANGER, DISTILLATION TOWER, EQUIP FAILURE A FLANGE ON A HEAT EXCHANGER ON A DISTILLATION TOWER/EQUIPMENT FAILURE	BENZENE	0	UNK
EXXON CHEMICAL	19951122	PUMP	PUMP, FAILED PRESSURE GAUGE PUMP / FAILED PRESSURE GAUGE	HAZARDOUS WASTE ( D001 & D035 )	0	UNK
EXXON CHEMICAL	19951229	VALVE	SAFETY VALVE, UNKNOWN SAFETY VALVE, UNKNOWN	BENZENE	0	UNK
EXXON CHEMICAL	19960117	CONTAINER LEAK	WASTEWATER TREATMENT SYSTEM IS SHOWING HIGH LEVELS OF WASTE WASTE WATER TREATMENT SYSTEM IS SHOWING HIGH LEVELS OF WASTE	BENZENE	0	UNK
EXXON CHEMICAL	19960205	FREEZING	FLANGE ON A GAS COMPRESSOR, FLANGE LEAKED DUE TO WEATHER FLANGE ON A GAS COMPRESSOR / FLANGE LEAKED DUE TO WEATHER//COLD//	BUTADIENE	0	UNK
EXXON CHEMICAL	19960205	FREEZING	FLANGE ON A GAS COMPRESSOR, FLANGE LEAKED DUE TO WEATHER FLANGE ON A GAS COMPRESSOR / FLANGE LEAKED DUE TO WEATHER//COLD//	BENZENE	0	UNK
EXXON CHEMICAL	19960603		PROCESS PIPING (SIZE UNKNOWN) / THE PIPING APPEARS TO BE LEAKING DUE TO CORROSION	BENZENE	0	NON
EXXON CHEMICAL	19960610	UNKNOWN	ABOVE GROUND STORAGE TANK CAUGHT FIRE RELEASING MATERIALS ABOVE GROUND STORAGE TANK CAUGHT FIRE RELEASING MATERIALS	BENZENE	0	UNK
EXXON CHEMICAL	19960618		SLOP TANKS 8 AND 9 / TANKS WERE OVERPRESSURIZED DUE TO UNKNOWN CAUSES CAUSING THE PSV'S ON THE TANKS TO RELEASE THE MATERIAL	BENZENE	0	NON
EXXON CHEMICAL	19960702	UNKNOWN	HEAT EXCHANGER ON A REACTOR, CAUSE UNKNOWN HEAT EXCHANGER ON A REACTOR / CAUSE UNKNOWN	NAPHTHALENE	0	UNK

EXXON CHEMICAL	19960702	UNKNOWN	HEAT EXCHANGER ON A REACTOR, CAUSE UNKNOWN HEAT EXCHANGER ON A REACTOR / CAUSE UNKNOWN	TOLUENE	0	UNK
EXXON CHEMICAL	19960702	UNKNOWN	HEAT EXCHANGER ON A REACTOR, CAUSE UNKNOWN HEAT EXCHANGER ON A REACTOR / CAUSE UNKNOWN	STYRENE	0	UNK
EXXON CHEMICAL	19960710	PUMP	DEPROPANIZER BOTTOMS PUMP / SEAL LEAKING DEPROPANIZER BOTTOMS PUMP / SEAL LEAKING	BENZENE	0	UNK
EXXON CHEMICAL	19960710	PUMP	DEPROPANIZER BOTTOMS PUMP / SEAL LEAKING DEPROPANIZER BOTTOMS PUMP / SEAL LEAKING	BUTADIENE	0	UNK
EXXON CHEMICAL	19960725	CONTAINER LEAK	COOLING TOWER, EXCHANGER LEAKING COOLING TOWER/EXCHANGER LEAKING	BENZENE	0	UNK
EXXON CHEMICAL	19960728	CONTAINER LEAK	SCN FEED FILTER ON AROMATICS UNIT, LEAKED OUT OF GASKET SCN FEED FILTER ON AROMATICS UNIT / LEAKED OUT OF GASKET	BENZENE	0	UNK
EXXON CHEMICAL	19960729	FITTING	LOW LEVEL IN PROCESS VESSEL CAUSED MAT TO VENT THRU WATER DRAIN* LOW LEVEL IN A PROCESS VESSEL CAUSED MATERIAL TO VENT THROUGH WATER DRAIN LINE	METHYL CHLORIDE	0	UNK
EXXON CHEMICAL	19961004	PUMP	PUMP IN A PROCEESS UNIT, SEAL FAILED PUMP IN A PROCESS UNIT / SEAL FAILED	BENZENE	0	UNK
EXXON CHEMICAL	19961012	VALVE	SOURCE:DARLA UNIT, CAUSE: SAFETY VALVE RELEASE SOURCE: DARLA UNIT/CAUSE: SAFETY VALVE RELEASE.	1,3 BUTADIENE	0	UNK
EXXON CHEMICAL	19970109		FLARE UNIT UPSET CAUSED MATERIAL TO FLARE FLARE / UNIT UPSET CAUSED MATERIAL TO FLARE	BENZENE	0	UNK
EXXON CHEMICAL	19970109		FLARE UNIT UPSET CAUSED MATERIAL TO FLARE FLARE / UNIT UPSET CAUSED MATERIAL TO FLARE	BUTADIENE	0	UNK

EXXON CHEMICAL	19970124	FITTING	CHARGE GAS COMPRESSOR UNIT,TRIPPED CAUSING RELEASE TO FLARE CHARGE GAS COMPRESSOR UNIT / THE COMPRESSOR TRIPPED CAUSING THE RELEASET TO THE FLARE SYSTEM	BENZENE	0	UNK
EXXON CHEMICAL	19970124	FITTING	CHARGE GAS COMPRESSOR UNIT,TRIPPED CAUSING RELEASE TO FLARE CHARGE GAS COMPRESSOR UNIT / THE COMPRESSOR TRIPPED CAUSING THE RELEASET TO THE FLARE SYSTEM	BUTADIENE	0	UNK
EXXON CHEMICAL	19970124	FITTING	CHARGE GAS COMPRESSOR UNIT,TRIPPED CAUSING RELEASE TO FLARE CHARGE GAS COMPRESSOR UNIT / THE COMPRESSOR TRIPPED CAUSING THE RELEASET TO THE FLARE SYSTEM	NITROGEN OXIDE	0	UNK
EXXON CHEMICAL	19970131	IMPROPER VALVE HANDLING	STORAGE NO 13068,VALVE TO EMISSIONS CONTROL DEVICE LEFT OPEN STORAGE NO. 13068 / VALVE TO EMMISIONS CONTROL DEVICE WAS LEFT CLOSED	BENZENE	0	UNK
EXXON CHEMICAL	19970220	FITTING	FLARE, COMPRESSOR TRIPPED OFF LINE FLARE / COMPRESSOR TRIPPED OFF-LINE	NITROGEN OXIDE	0	UNK
EXXON CHEMICAL	19970416	PUMP	MISALIGNED PUMP ON FLARE SYSTEM MISALIGNED PUMP ON FLARE SYSTEM	NITROGEN OXIDE	0	UNK
EXXON CHEMICAL	19970418	PUMP	DEPROPANIZER BOTTOM PUMP,SEAL FAILURE CAUSED THE RELEASES DEPROPANIZER BOTTOM PUMP / SEAL FAILURE CAUSED THE RELEASE	BENZENE	0	UNK
EXXON CHEMICAL	19970418	PUMP	DEPROPANIZER BOTTOM PUMP,SEAL FAILURE CAUSED THE RELEASES DEPROPANIZER BOTTOM PUMP / SEAL FAILURE CAUSED THE RELEASE	BUTADIENE	0	UNK
EXXON CHEMICAL	19970422		DIAPHRAGM SEAL FAILURE ON PUMP/PART OF WASTEWATER UNIT	BENZENE	0	NON
EXXON CHEMICAL	19970516	VALVE	PROCESS UNIT ( BUTADIENE) LEAKING VALVE PROCESS UNIT (BUTADIENE) / LEAKING VALVE	BUTADIENE	0	UNK

EXXON CHEMICAL	19970618	RAIN OR SNOW	WASTEWATER TREATMENT UNIT TANK1,HEAVY RAIN CAUSING UNIT TO WASTE WATER TREATMENT UNIT TANK 1-HEAVY RAIN IS CAUSING UNIT TO HAVE TROUBLE KEEPING UP	UNTREATED WASTE WATER AND RAIN W	0	UNK
EXXON CHEMICAL	19970813	PUMP	HYDROCARBON PUMP #UP04B/SEAL ON PUMP FAILED RELEASING MAT HYDROCARBON PUMP #UP04B/SEAL ON PUMP FAILED RELEASING MATERIAL	BUTADIENE	0	UNK
EXXON CHEMICAL	19970903	CONTAINER LEAK	SOURCE: HEAT EXCHANGER IN A PROCESS UNIT/CAUSE: LEAKING SOURCE: HEAT EXCHANGER IN A PROCESS UNIT/CAUSE: LEAKING	BENZENE	0	UNK
EXXON CHEMICAL	19970903	CONTAINER LEAK	SOURCE: HEAT EXCHANGER IN A PROCESS UNIT/CAUSE: LEAKING SOURCE: HEAT EXCHANGER IN A PROCESS UNIT/CAUSE: LEAKING	BUTADIENE	0	UNK
EXXON CHEMICAL	19971023	CONTAINER LEAK	3 INCH PROCESS LINE DEVELOPED LEAK,CAUSE UNDER INVESTIGATION 3 INCH PROCESS LINE DEVELOPED LEAK / CAUSE IS UNDER INVESTIGATION	OIL: CRUDE	0	UNK
EXXON CHEMICAL	19971023	CONTAINER LEAK	PROCESS LINE LEAK, CAUSE UNDER INVESTIGATION PROCESS LINE LEAK / CAUSE UNDER INVESTIGATION	ISOPRENE	0	UNK
EXXON CHEMICAL	19971215		FLARE / A COMPRESSOR SHUT DOWN RESULTING IN A RELEASE TO THE ATMOSPHERE	ETHYLENE	0	NON
EXXON CHEMICAL	19971215		FLARE / A COMPRESSOR SHUT DOWN RESULTING IN A RELEASE TO THE ATMOSPHERE	NITROGEN OXIDE	0	NON
EXXON CHEMICAL	19971215		ETHLENE COMPRESSOR / COMPRESSOR SHUT DOWN CAUSING SOME PRODUCT TO GO TO THE FLARE	BUTADIENE	0	NON
EXXON CHEMICAL	19971215		COMPRESSOR / UNIT WAS SHUT DOWN BY SAFETY DEVICE	BENZENE	0	NON

## EXXON CHEMICAL AMERICA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL AMERICA	19930421		REACTOR/BLEEDER NOT CLOSED WHEN UNIT BROUGHT ON LINE REACTOR/BLEEDER NOT CLOSED WHEN UNIT BROUGHT ON LINE	TOLUENE	0	LBS
EXXON CHEMICAL AMERICA	19930612	FITTING	RUPTURED DISK ON REACTOR RUPTURED DISK ON REACTOR	O-XYLENE	0	LBS
EXXON CHEMICAL AMERICA	19930613	VALVE	DRAIN VALVE ON HEXANE DRUM / DRAIN VALVE LEAKED DRAIN VALVE ON HEXANE DRUM / DRAIN VALVE LEAKED	HEXANE	0	LBS
EXXON CHEMICAL AMERICA	19931110	IMPROPER OPERATION		HEXANE	0	LBS
EXXON CHEMICAL AMERICA	19941012	CONTAINER LEAK	TRANSFER LINE/PIN HOLE LEAK DUE TO UNKNOWN CAUSES TRANSFER LINE/PIN HOLE LEAK DUE TO UNKNOWN CAUSES	HEXANE	0	UNK
EXXON CHEMICAL AMERICA	19941012	CONTAINER LEAK	TRANSFER LINE/PIN HOLE LEAK DUE TO UNKNOWN CAUSES TRANSFER LINE/PIN HOLE LEAK DUE TO UNKNOWN CAUSES	1,3-PENTADIENE	0	UNK
EXXON CHEMICAL AMERICA	19941015	CONTAINER LEAK	LEAKING IN PIPING CONNECTION DUE TO AN UNKNOWN CAUSE LEAKING IN PIPING CONNECTION DUE TO AN UNKNOWN CAUSE	HEXENE	0	UNK
EXXON CHEMICAL AMERICA	19941015	CONTAINER LEAK	LEAKING IN PIPING CONNECTION DUE TO AN UNKNOWN CAUSE LEAKING IN PIPING CONNECTION DUE TO AN UNKNOWN CAUSE	BENZENE	0	UNK
EXXON CHEMICAL AMERICA	19941018	FITTING	COMPRESSOR/THERMO CUPPLER BLEW, RESULTING IN RELEASE COMPRESSOR/THERMO CUPPLER BLEW RESULTING IN RELEASE	HYDROCHLORIC ACID	0	UNK
EXXON CHEMICAL AMERICA	19941018	FITTING	COMPRESSOR/THERMO CUPPLER BLEW, RESULTING IN RELEASE COMPRESSOR/THERMO CUPPLER BLEW RESULTING IN RELEASE	METHALLYL CHLORIDE	0	UNK

EXXON CHEMICAL AMERICA	19941018	FITTING	PROCESS UNIT NO RLA-1/BLOCK VALVE ON EXCHANGER MALFUNCTIONED PROCESS UNIT NO.RLA-1/BLOCK VALVE ON EXCHANGER MALFUNCTIONED RESULTING IN RELEASE	METHALLYL CHLORIDE	0	UNK
EXXON CHEMICAL AMERICA	19941018	FITTING	METHYL CHLORIDE PIPING,THERMAL COUPLING RUPTURED DUE TO UNK METHYL CHLORIDE PIPING,THERMAL COUPLING RUPTURED DUE TO UNK	METHYL CHLORIDE	0	UNK
EXXON CHEMICAL AMERICA	19941019	VALVE	MAT RELEASED THRU PARTIALLY OPENED BLEEDER VALVE ON EXCHANGER MAT RELEASED THRU PARTIALLY OPENED BLEEDER VALVE ON EXCHANGER	BUTADIENE	0	UNK
EXXON CHEMICAL AMERICA	19950411	RAIN OR SNOW	OVERFLOWED TRICKLING FILTERS & SEPARATOR>EXCESSIVE RAINFALL OVERFLOWED TRICKLING FILTERS & SEPARATOR>EXCESSIVE RAINFALL	UNTREATED PROCESS WASTE WATER	0	UNK
EXXON CHEMICAL AMERICA	19950411	CONTAINER LEAK	10 INCH PROCESS LINE/SMALL LEAK DEVELOPED, REASONS UNKNOWN 10 INCH PROCESS LINE,SMALL LEAK DEVELOPED,REASONS UNKNOWN	SULFUR DIOXIDE	0	UNK
EXXON CHEMICAL AMERICA	19950501	FITTING	A BLOWN SEAL ON A DRUM A BLOWN SEAL ON A DRUM	HEXANE	0	UNK
EXXON CHEMICAL AMERICA	19950503	IMPROPER VALVE HANDLING	ABOVE GROUND STORAGE TANK, OPEN VALVE ABOVE GROUND STORAGE TANK, OPEN VALVE	HEXANE	0	UNK
EXXON CHEMICAL AMERICA	19950518	FITTING	TURBINE GENERATOR,LOST STEAM INJECTION TURBINE GENERATOR//LOST STEAM INJECTION	NITROGEN OXIDE	0	UNK
EXXON CHEMICAL AMERICA	19950522	CONTAINER LEAK	STORAGE TANK #1658 WATER DRAW LINE LEAKED, CAUSES UNKNOWN STORAGE TANK #1658 WATER DRAW LINE LEAKED, CAUSES UNKNOWN	POLYCYCLIC ORGANIC MATTER	0	UNK
EXXON CHEMICAL AMERICA	19950525	VALVE	A VALVE FAILURE ON A PIPELINE A VALVE FAILURE ON A PIPELINE	BENZENE	0	UNK
EXXON CHEMICAL AMERICA	19950525	VALVE	A VALVE FAILURE ON A PIPELINE A VALVE FAILURE ON A PIPELINE	HEXENE	0	UNK

EXXON CHEMICAL AMERICA	19950715	CONTAINER LEAK	PIN HOLE LEAK IN TRANSFER PIPING, UNKNOWN PIN HOLE LEAK IN TRANSFER PIPING, UNKNOWN	1,3 BUTADIENE	0	UNK
EXXON CHEMICAL AMERICA	19950715	CONTAINER LEAK	PIN HOLE LEAK IN TRANSFER PIPING, UNKNOWN PIN HOLE LEAK IN TRANSFER PIPING, UNKNOWN	BENZENE	0	UNK
EXXON CHEMICAL AMERICA	19960105	CONTAINER LEAK	PIPING FLANGE, FLANGE SEPARATED PIPING FLANGE/FLANGE SEPARATED	BROMINE	0	UNK
EXXON CHEMICAL AMERICA	19960215	VALVE	PROCESS UNIT, SAFETY VALVE LIFTED PROCESS UNIT/SAFETY VALVE LIFTED	BENZENE	0	UNK
EXXON CHEMICAL AMERICA	19960220	FLANGE	PIPELINE SYSTEM, FLANGE DEVELOPED A LEAK PIPEING SYSTEM/FLANGE DEVELOPED A LEAK	HAZADOUS WASTE(D001)	0	UNK
EXXON CHEMICAL AMERICA	19960507	CONTAINER LEAK	WATER WELL PUMP SEAL, SEAL CHAMBER DEVELOPED A LEAK WATER WELL PUMP/SEAL CHAMBER DEVELOPED A LEAK	MERCURY	0	UNK

## EXXON CHEMICAL AMERICAS

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL AMERICAS	19920904		RAIL CAR/LEAKING FROM 4" BOTTOM VALVE DUE TO GASKET FAILURE	METHYL ETHYL KETONE	0	NON

## EXXON CHEMICAL BATON ROUG

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL BATON ROUG	19930209	PUMP	FUEL OIL PUMP / SEAL LEAKED FUEL OIL PUMP / SEAL LEAKED	METHANOL	0	LBS
EXXON CHEMICAL BATON ROUG	19930209	PUMP	FUEL OIL PUMP / SEAL LEAKED FUEL OIL PUMP / SEAL LEAKED	XYLENE (O-, M-, P-, & MIXTURES)	0	LBS
EXXON CHEMICAL BATON ROUG	19930213	FITTING	HIGH TEMPERATURE INTERLOCK / FAULTY THERMO-COUPLER HIGH TEMPERATURE INTERLOCK/FAULTY THERMO-COUPLER	ETHYLENE		LBS



EXXON CHEMICAL BATON ROUG	19930213	FITTING	HIGH TEMPERATURE INTERLOCK / FAULTY THERMO-COUPLER HIGH TEMPERATURE INTERLOCK/FAULTY THERMO-COUPLER	ACETALDEHYDE	0	LBS
------------------------------	----------	---------	--	--------------	---	-----

## EXXON CHEMICAL CO

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL CO	19900131		INSTRUMENT FAILURE.	BENZENE	0	NON
EXXON CHEMICAL CO	19900804		LEAK IN STORAGE TANK UNKNOWN CAUSE	BENZENE	0	NON
EXXON CHEMICAL CO	19900809		FLOWLINE FROM THE I.P.A. UNIT / FLOWLINE FAILED.	SULFURIC ACID (65%)	0	NON
EXXON CHEMICAL CO	19900913		STORAGE DRUM D-40/ VALVE LEAKED THROUGH	ISOPRENE	150	GAL
EXXON CHEMICAL CO	19910304		DISCHARGE LINE/SPLIT DURING MAINTANCE	MIXED HYDROCARBONS	0	NON
EXXON CHEMICAL CO	19910406		PUMP/SEAL ON THE PUMP BLEW OUT.	BUTADIENE	0	NON
EXXON CHEMICAL CO	19910418		DRUM / LEVEL INSTRUMENT TAP ON THE DRUM LEAKED.	HEXANE	0	NON
EXXON CHEMICAL CO	19910418		DRUM / LEVEL INSTRUMENT TAP ON THE DRUM LEAKED.	METHYL CHLORIDE	0	NON
EXXON CHEMICAL CO	19910527		4" PIPELINE LEAK / CORROSION	SULFURIC ACID	0	NON
EXXON CHEMICAL CO	19910717		PROCESS UNIT / VENTING WAS DUE TO AN INSTRUMENTATION PROBLEM.	METHANE	0	NON
EXXON CHEMICAL CO	19910721		MIXING DRUM / MECHANICAL SEAL FAILURE	HEXANE	0	NON
EXXON CHEMICAL CO	19910803		TRANSFER LINE / LEAKING ELBOW JOINT	BORON TRIFLORIDE	0	NON
EXXON CHEMICAL CO	19911021		STORAGE TANK / MATERIAL SPILLED WHILE LINE WAS BEING FLUSHED	BENZENE	0	NON

EXXON CHEMICAL CO	19911101		UNIT VALVE FAILURE/FILTER FAILURE	BENZENE	0	NON
EXXON CHEMICAL CO	19920127	PUMP	RUBBER UNIT/PUMP WAS BEING REMOVED RUBBER UNIT/ PUMP WAS BEING REMOVED	HEXANE		LBS
EXXON CHEMICAL CO	19920205	VALVE	RUBBER PRODUCTION UNIT/SEAL FAILURE ON VALVE RUBBER PRODUCTION UNIT/SEAL FAILURE ON VALVE	HEXANE		LBS
EXXON CHEMICAL CO	19920223	TANK OR CONTAINER	STORAGE TANK/OVERFLOWED STORAGE TANK / OVERFLOWED	BENZENE		LBS
EXXON CHEMICAL CO	19920326	FITTING	FLARE/ PILOT LIGHT WENT OUT FLARE/PILOT LIGHT WENT OUT	BUTADIENE		LBS
EXXON CHEMICAL CO	19920327	CONTAINER LEAK	SACK UNIT/ PUMP LEAK/ SEAL FAILURE SACK UNIT/PUMP LEAK/SEAL FAILURE	BUTADIENE		LBS
EXXON CHEMICAL CO	19920501		STRIPPER VENT/VENT LINE WAS PLUGGED	HEXANE	0	NON
EXXON CHEMICAL CO	19920504		RUBBER 3 UNIT / FAULTY PROCEDURE	HEXANE	0	NON
EXXON CHEMICAL CO	19920512		VISTALON UNIT D-20 FLASH DRUM/PROCEEDURAL ERROR.	HEXANE	0	NON
EXXON CHEMICAL CO	19920512		VISTALON UNIT D20 FLASH DRUM/ LEAKING VALVE	HEXANE	0	NON
EXXON CHEMICAL CO	19920609		PUMP 130/SEAL FAILURE	HEXANE	0	NON
EXXON CHEMICAL CO	19920615		WASTE WATER TREATMENT PUMP HAS A HOLE IN DISCHARGE LINE	UNTREATED WASTE WATER CONTAINING	0	NON
EXXON CHEMICAL CO	19920618		BUS/GAS TANK	GASOLINE: AUTOMOTIVE (4.23G PB/G	0	NON
EXXON CHEMICAL CO	19920627		TRANSFER LINE AT ESCOREZ UNIT/THERMAL EXPANSION.	PETROLEUM RESIN W/ HEXANE	0	NON

EXXON CHEMICAL CO	19920629	IMPROPER HOSE CONNECTION	RUBBER UNIT/LEAKED FROM TUBING THAT WAS DISCONNECTED RUBBER UNIT / LEAKED FROM TUBING THAT WAS DISCONNECTED	HEXANE		LBS
EXXON CHEMICAL CO	19920630		A PURIFICATION UNIT HAD A VALVE RELEASE A PURIFICATION UNIT HAD A VALVE RELEASE	ISOBUTYLENE		LBS
EXXON CHEMICAL CO	19920630		A PURIFICATION UNIT HAD A VALVE RELEASE A PURIFICATION UNIT HAD A VALVE RELEASE	METHYL ALCOHOL	0	LBS
EXXON CHEMICAL CO	19920706	CONTAINER LEAK	PURIFICATION UNIT/EXCHANGER COIL LEAKING PURIFICATION UNIT/ EXCHANGER COIL LEAKING	PROPYLENE AND HEAVIER HYDROCARBI		LBS
EXXON CHEMICAL CO	19920730		WATER TREATMENT SYSTEM/COUPLING FAILURE IN TUBING	CYCLOHEXYLAMINE		UNK
EXXON CHEMICAL CO	19920918		FLANGE AT VISTALON UNIT/INSTALLING BLIND FLANGE FLANGE AT VISTALON UNIT/INSTALLING BLIND FLANGE	HEXANE		LBS
EXXON CHEMICAL CO	19921001	FITTING	VISTALON UNIT/LEAKING TUBE ON AN EXCHANGER VISTALON UNIT/ LEAKING TUBE ON AN EXCHANGER	HEXANE		LBS
EXXON CHEMICAL CO	19921105		PROCESS UNIT / BLEEDER VALVE LEAKING	BENZENE	0	NON
EXXON CHEMICAL CO	19921203	VALVE	AEROMATIC UNIT / SAFETY VALVE BLEW AEROMATIC UNIT / SAFETY VALVE BLEW	BENZENE		LBS
EXXON CHEMICAL CO	19921223	VALVE	VISTALON UNIT / LEAKING VALVE VISTALON UNIT/LEAKING VALVE	HEXANE		LBS
EXXON CHEMICAL CO	19921224	FITTING	VISTALON UNIT/ INTERNAL SEAL FAILED VISTALON UNIT/INTERNAL SEAL FAILED.	HEXANE		LBS
EXXON CHEMICAL CO	19930202	CONTAINER LEAK	HALOBUTYL UNIT / REACTOR SEAL LEAK HALOBUTYL UNIT / REACTOR SEAL LEAK	HEXANE		LBS

EXXON CHEMICAL CO	19930317		ACETATE UNIT / LEAKED DUE TO UNKNOWN CAUSE ACETATE UNIT / LEAKED DUE TO UNKNOWN CAUSE	ACETATE ESTER		GAL
EXXON CHEMICAL CO	19930521	OVERFLOW	ABOVE GROUND STORAGE TANK/ OVERFILLED STORAGE TANK / OVERFILLED	ISOOCTANE	0	UNK
EXXON CHEMICAL CO	19930527	PIPELINE	FACILITY PIPEING /PIN HOLE LEAK DUE TO EXTERNAL CORROSION FACILITY PIPEING/PINHOLE LEAK DUE TO EXTERNAL CORROSION	PETROLEUM NAPHTHA	0	LBS
EXXON CHEMICAL CO	19930805		FEED LINE FOR A RLA1 UNIT(PROCESS UNIT) LINE HAS FAILED FEED LINE FOR A RLA1 UNIT(PROCESS UNIT)/LINE HAS FAILED	METHYL CHLORIDE	0	LBS
EXXON CHEMICAL CO	19930805		FEED LINE FOR A RLA1 UNIT(PROCESS UNIT) LINE HAS FAILED FEED LINE FOR A RLA1 UNIT(PROCESS UNIT)/LINE HAS FAILED	ISOBUTYLENE	0	
EXXON CHEMICAL CO	19930805		FEED LINE FOR A RLA1 UNIT(PROCESS UNIT) LINE HAS FAILED FEED LINE FOR A RLA1 UNIT(PROCESS UNIT)/LINE HAS FAILED	ISOPRENE	0	LBS
EXXON CHEMICAL CO	19930823		TANK#683 FROM PLASTICIZER UNIT,RELIEF VALVE,LEAK,CAUSE UNKNOWN TANK#683 FROM PLASTICIZER UNIT,RELIEF VALVE,LEAK,CAUSE UNKNOWN	PHTHALATE ESTER	0	LBS
EXXON CHEMICAL CO	19930824		HEART CUT DISTILLATE UNIT/SEED CONTAMINATE CAUSED THE RELEASE HEART CUT DISTILLATE UNIT/SEED CONTAMINATE CAUSED THE RELEASE	METHYL TERT-BUTYL ETHER	0	LBS
EXXON CHEMICAL CO	19930824		HEART CUT DISTILLATE UNIT/SEED CONTAMINATE CAUSED THE RELEASE HEART CUT DISTILLATE UNIT/SEED CONTAMINATE CAUSED THE RELEASE	TER-AMYL METHYL ETHER	0	

EXXON CHEMICAL CO	19930825		STORAGE DRUM/DRUM WAS ASSUMED EMPTY,WHEN OPENED, MAT ESCAPED STORAGE DRUM/DRUM WAS ASSUMED EMPTY,WHEN OPENED, MAT ESCAPED	HEXANE	0	LBS
EXXON CHEMICAL CO	19930910	PUMP	STORAGE TANK ON VISTA LON UNIT/SEAL FAILURE ON GAUGE HATCH STORAGE TANK ON VISTA LON UNIT/SEAL FAILURE ON GAUGE HATCH	HEXANE	0	LBS
EXXON CHEMICAL CO	19930913	IMPROPER OPERATION	A PROCESS UNIT HAD A VENT LINE LEFT OPEN A PROCESS UNIT HAD A VENT LINE LEFT OPEN	HEXANE	0	LBS
EXXON CHEMICAL CO	19930921		B LINE LOW PRESSURE SEPERATOR/OVER PRESSURED DUE TO POSSIBLE PLUG IN LINE	ETHYLENE	0	UNK
EXXON CHEMICAL CO	19930927		DRUM D28 FLASH DRUM ON THE VISTALON UNIT/GASKET BLEW OUT	HEXANE	0	NON
EXXON CHEMICAL CO	19930929		A PROCESS UNIT HAD A SAFETY VALVE VENT EXCESS PRESSURE	HEXANE	0	NON
EXXON CHEMICAL CO	19931027		BLEEDER VALVE ON MIXING DRUM, PLUG LOOSE, CAUSES UNKNOWN BLEEDER VALVE ON MIXING DRUM, PLUG LOOSE, CAUSES UNKNOWN	HEXANE	0	LBS
EXXON CHEMICAL CO	19931208	FITTING	GASKET ON VISTALOM UNIT,RELEASE CAUSED BY GASKET FAILURE GASKET ON VISTALOM UNIT,RELEASE CAUSED BY GASKET FAILURE	HEXANE	0	LBS
EXXON CHEMICAL CO	19931223	FITTING	REACTOR SYSTEM//OPENED EMERGENCY DUMP SYSTEM REACTOR SYSTEM//OPENED EMERGENCY DUMP SYSTEM	ETHYLENE	0	LBS
EXXON CHEMICAL CO	19931223	FITTING	REACTOR SYSTEM//OPENED EMERGENCY DUMP SYSTEM REACTOR SYSTEM//OPENED EMERGENCY DUMP SYSTEM	VINYL ACETATE	0	
EXXON CHEMICAL CO	19940125	VALVE	PACKING GLAND LEAK IN A BLOCK VALVE PACKING GLAND LEAK IN A BLOCK VALVE	HEXANE	0	LBS

EXXON CHEMICAL CO	19940216	FLANGE	VISTALON UNIT/FLANGE LEAK IN HEXANE LINE VISTALON UNIT/FLANGE LEAK IN HEXANE LINE	HEXANE	0	UNK
EXXON CHEMICAL CO	19940223		DIVERSION SEWER PIPE/CAUSE IS UNKNOWN AT THIS TIME DIVERSION SEWER PIPE/CAUSE IS UNKNOWN AT THIS TIME	DIESEL FUEL	0	UNK
EXXON CHEMICAL CO	19940304	IMPROPER VALVE HANDLING	VISTALON UNIT/DRUM 164/VALVE LEFT OPEN RESULTING IN RELEASE VISTALON UNIT/DRUM 164/VALVE LEFT OPEN RESULTING IN RELEASE	HEXANE	0	UNK
EXXON CHEMICAL CO	19940304	IMPROPER VALVE HANDLING	VISTALON UNIT/DRUM 164/VALVE LEFT OPEN RESULTING IN RELEASE VISTALON UNIT/DRUM 164/VALVE LEFT OPEN RESULTING IN RELEASE	UNKNOWN MATERIAL	0	UNK
EXXON CHEMICAL CO	19940306	CONTAINER LEAK	RECIRCULATION LINE, LEAKED DUE TO A PIN HOLE IN AN ELBOW RECIRCULATION LINE//LEAKED DUE TO A PINHOLE IN A ELBOW	COBALT WATER	0	UNK
EXXON CHEMICAL CO	19940310	VALVE	AROMATICS UNIT,FLOW LINE VALVE LEAKED WHILE BEING REPAIRED AROMATICS UNIT/FLOW LINE VALVE LEAKED WHILE BEING REPAIRED	BENZENE	0	UNK
EXXON CHEMICAL CO	19940330	OVERFLOW	NON HAZMAT TANK TRUCK/OVERFLOWED WHILE BEING FILLED NON HAZMAT TANK TRUCK//OVERFLOWED WHILE BEING FILLED	HEXANE ZARSOL	0	UNK
EXXON CHEMICAL CO	19940419	VALVE	VISTA LINE UNIT//LEAKED DUE TO A VALVE FAILURE VISTA LINE UNIT//LEAKED DUE TO A VALVE FAILURE	HEXANE	0	UNK
EXXON CHEMICAL CO	19940419	IMPROPER OPERATION	1 INCH LINE/MATERIAL ACCIDENTLY RELEASED DUE TO HUMAN ERROR 1 INCH LINE/MATERIAL ACCIDENTLY RELEASED DUE TO HUMAN ERROR	HEXANE	0	UNK

EXXON CHEMICAL CO	19940501	VALVE	HALOBUTYL PROCESS UNIT/SAFETY VALVE LEAKED, RELEASE RESULTED HALOBUTYL PROCESS UNIT/SAFETY VALVE LEAKED,RELEASE RESULTED	HEXANE	0	UNK
EXXON CHEMICAL CO	19940613		PUMP ON THE ESCOREZ 1000 UNIT / SEAL FAILURE	HEXANE	0	NON
EXXON CHEMICAL CO	19940613	FITTING	PROCESSING UNIT SUPPLY LINE /MECHANICAL FAILURE PROCESSING UNIT SUPPLY LINE/MECHANICAL FAILURE	HEXANE	0	UNK
EXXON CHEMICAL CO	19940620	PUMP	BUTADIENE EXTRACT UNIT HAD A SEAL ON A PUMP FAIL BUTADIENE EXTRACT UNIT HAD A SEAL ON A PUMP FAIL	DIMETHYLFORMAMIDE	0	UNK
EXXON CHEMICAL CO	19940622	IMPROPER OPERATION	STORAGE TANK 1977/MANWAY OPENED DUE TO PRESSURE RELEASE STORAGE TANK 1977/MANWAY OPENED DUE TO PRESSURE RELEASE*	HEXANE	0	UNK
EXXON CHEMICAL CO	19940808		CRACKING UNIT/CAUGHT ON FIRE DUE TO UNKNOWN REASONS CRACKING UNIT//CAUGHT ON FIRE DUE TO UNKNOWN REASONS	HEXANE	0	UNK
EXXON CHEMICAL CO	19940811	HOSE	PUMP FOR WASTEWATER TREATMENT SYSTEM,HOSE RUPTURED>RELEASE PUMP FOR WASTE WATER TREATMENT SYSTEM/HOSE RUPTURED RESULTING IN RELEASE	BENZENE-HAZMAT WASTE D018 .5 PPM	0	UNK
EXXON CHEMICAL CO	19940920		COOLING TOWER/UNKNOWN SHEEN DEVELOPED AT OUTFALL NO. 004 DURING WATER RELEASE	UNKNOWN OIL	0	UNK
EXXON CHEMICAL CO	19941203	FITTING	FLOW INSTRUMENT ON A BROMINE RACK, A GASKET FAILURE FLOW INSTRUMENT ON A BROMINE RACK/A GASKET FAILURE	BROMINE	0	UNK
EXXON CHEMICAL CO	19941211		STORAGE TANK 1978 ON HALOBUTYL UNIT,HATCH OPENED>CAUSE UNK STORAGE TABK 1978 ON THE HOLBUTYL UNIT,HATCH OPENED>CAUSE UNK	HEXANE	0	UNK

EXXON CHEMICAL CO	19941227	CONTAINER LEAK	HALOBUTYL UNIT, MAT RELEASED DUE TO PIN HOLE LEAK IN WELD HALOBUTYL UNIT, MAT RELEASED DUE TO PIN HOLE LEAK IN WELD	ISOPRENE	0	UNK
EXXON CHEMICAL CO	19941230	FITTING	ENVIRONMENTAL UNIT/ GASKET FAILURE ENVIRONMENTAL UNIT/GASKET FAILURE	SULFURIC ACID	0	UNK
EXXON CHEMICAL CO	19950128	CONTAINER LEAK	EXCHANGER AT THE AEROMATICS UNIT / LEAK EXCHANGER AT THE AEROMATICS UNIT/LEAK	BENZENE	0	UNK
EXXON CHEMICAL CO	19950128	CONTAINER LEAK	EXCHANGER AT THE AEROMATICS UNIT / LEAK EXCHANGER AT THE AEROMATICS UNIT/LEAK	TOLUENE	0	UNK
EXXON CHEMICAL CO	19950225	FITTING	HALOBUTYL OUTLET TUBE, RELEASE HALOBUTYL OUTLET TUBE/RELEASE	HEXANE	0	UNK
EXXON CHEMICAL CO	19950225	FITTING	HALOBUTYL OUTLET TUBE, RELEASE HALOBUTYL OUTLET TUBE/RELEASE	ISOPRENE	0	UNK
EXXON CHEMICAL CO	19950917		SEWER SYSTEM/UNKNOWN	OTHER OIL	2	GAL
EXXON CHEMICAL CO	19951218	RAIN OR SNOW	WASTEWATER TREATMENT TANK, OVERFLOWED DUE TO HEAVY RAINS WASTE WATER TREATMENT TANK / OVERFLOWED DUE TO HEAVY RAINS / CAPACITY OF SYSTEM 10,000,000GAL	BENZENE - <1%	0	UNK
EXXON CHEMICAL CO	19960205	FLANGE	REFLUX LINE, FLANGE MALFUNCTIONED REFLUX LINE/FLANGE MALFUNCTIONED	BENZENE	0	UNK
EXXON CHEMICAL CO	19960402	FLANGE	PROCESS UNIT, A FLANGE DEVELOPED A LEAK PROCESS UNIT/A FLANGE DEVELOPED A LEAK	BENZENE	0	UNK

## EXXON CHEMICAL CO.

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL CO.	19871002		BLEEDER VALVE ON TANK LEFT OPEN	OIL : CRUDE		
EXXON CHEMICAL CO.	19910402		HEAT EXCHANGER/ OPENED IMPROPERLY	HEXANE	0	NON



EXXON CHEMICAL CO.	19910721		PUMP, SEAL FAILURE ON THE AROMATICS UNIT	BENZENE	0	NON
EXXON CHEMICAL CO.	19910721		PUMP, SEAL FAILURE ON THE AROMATICS UNIT	SULFOLANE	0	NON

## EXXON CHEMICAL COMPANY

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL COMPANY	19900303		3/4" PIPELINE / PIPELINE BROKE DUE TO UNKNOWN CAUSE.	METHYL CHLORIDE	0	UNK

## EXXON CHEMICAL, BATON ROUGE

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICAL, BATON ROUGE	19940708	RAIN OR SNOW	SUMP/SUMP OVERFLOWED DUE TO HEAVY RAIN SUMP/SUMP OVERFLOWED DUE TO HEAVY RAIN	UNKNOWN MATERIAL, OIL OR OIL-LIK	0	UNK

## EXXON CHEMICALS

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICALS	19871002		LEAK IN FEED LINE TO STORAGE TANK DRAIN OPEN ON FIRE WALL.	(EXXATE 700 SOLVENT)		
EXXON CHEMICALS	19871002		LEAK IN FEED LINE TO STORAGE TANK DRAIN OPEN ON FIRE WALL.	(ACCTIC ACID ESTER)		
EXXON CHEMICALS	19930811		VALVE ON A TANK / LEAKED DUE TO UNKNOWN CAUSE VALVE ON A TANK/LEAKED DUE TO UNKNOWN CAUSE	POLY CYCLIC ORGANIC MATTER	0	LBS
EXXON CHEMICALS	19931030	FLOW LINE	FLOW LINE / LEAKING VALVE FLOW LINE/LEAKING VALVE	MINERAL SPIRITS AND RESIN	600	GAL
EXXON CHEMICALS	19931030	IMPROPER VALVE HANDLING	PROCESS LINE / VALVE WAS LEFT OPEN PROCESS LINE/VALVE WAS LEFT OPEN	MINERAL SPIRITS	9	GAL

EXXON CHEMICALS	19961026		WASTE WATER TREATMENT DETENTION TANKS / OVERFLOW CAUSED BY RAINFALL	WASTE WATER PRODUCT MIXED W/RAIN	0	UNK
-----------------	----------	--	---	----------------------------------	---	-----

### EXXON CHEMICALS-BATON R.

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CHEMICALS-BATON R.	19920608		PROCESS LINE/GASKET FAILURE	METHYL ACRYLATE	0	NON
EXXON CHEMICALS-BATON R.	19920608		PROCESS LINE/GASKET FAILURE	HEXANE	0	NON

### EXXON CO USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CO USA	19900203		PINHOLE LEAK IN A BARGE #PG201/DURING LOADING OPS	OIL: DIESEL	5	GAL
EXXON CO USA	19900224		RESEARCH SYNTHETIC GAS PILOT UNIT/FAILED FEED NOZZLE	NICKEL OXIDE	0	NON
EXXON CO USA	19900227		BACK END OF A WASTE MATERIAL CONTAINER FOR A TRUCK WAS NOT CLOSED PROPERLY	KO 49 SLOP OIL	0	NON
EXXON CO USA	19900227		T/B DON/PINHOLE IN TOP OF CARGO TANK #5 PORT	GASOLINE: AUTOMOTIVE (4.23G PB/G)	1	GAL
EXXON CO USA	19900408		REPORTS A BARGE CST2517 BROKE LOOSE FROM ITS MOORINGS AND BROKE A DISCHARGE HOSE	COKE FEED	8	BBL
EXXON CO USA	19900410		DRAIN OUTFALL FROM THE FACILITY. / UNKNOWN	UNKNOWN OIL	0	UNK
EXXON CO USA	19910312		T/B CHOTIN-2983/ SMALL CRACK IN NO. 9 COMPARTMENT	GASOLINE: AUTOMOTIVE (UNLEADED)	1	GAL
EXXON CO USA	19910419		OUTFALL 003 / OVERFLOW	UNKNOWN OIL	1	GAL

EXXON CO USA	19910429		REFINERY SEWER SYSTEM / EXCESS STORM WATER RUNOFF	UNKNOWN OIL	1	GAL
EXXON CO USA	19910502		STORAGE TANK/ LEAKING BOTTOM	SODIUM HYDROXIDE	0	NON
EXXON CO USA	19910502		STORAGE TANK/ LEAKING DUE TO HOLES IN THE BOTTOM	SODIUM HYDROXIDE	0	NON
EXXON CO USA	19910509		UNKNOWN / UNKNOWN SHEEN SIGHTING	UNKNOWN OIL	0	UNK
EXXON CO USA	19910520		BARGE HBL 3002 / PIN HOLE LEAK ON BOTTOM OF BARGE.	OIL, FUEL: NO. 6	5	GAL
EXXON CO USA	19910603		18" DISCHARGE LINE/ PINHOLE LEAK	LIGHT VIRGIN GAS OIL	1	GAL
EXXON CO USA	19910817		SULFUR PLANT INCINERATOR STACK, EXCEEDED 1 LB REPORTABLE QUANTITY	SULFUR DIOXIDE	0	NON
EXXON CO USA	19911001		BLOWN GASKET ON A FLANGE	SULFURIC ACID	0	NON
EXXON CO USA	19920130	IMPROPER OPERATION	HOIPPER/DURING OFF LOADING TO BOX, A RELEASE OCCURRED. HOPPER/ DURING OFF LOADING TO BOX A RELEASE OCCURRED	K048		LBS
EXXON CO USA	19920219		MPDES OUTFALL 003 / DUE TO WEEKEND OVERFLOW OIL IS BEING RELEASED THROUGH THE OUTFALL. OIL IS ALSO SEEPING DOWN EMBANKMENT OF THE CANAL.	OIL: CRUDE	0	NON
EXXON CO USA	19920219		EXCHANGER LEAK/TUBE FAILURE	BENZENE	0	NON
EXXON CO USA	19920305		REFINERY DISCHARGE/ OIL IN EFFLUENT	OIL: CRUDE	1	BBL
EXXON CO USA	19920401		PROCESS UNIT TOWER/RELEASE FROM THE SAFETY VALVE PROCESS UNIT TOWER/RELEASE FROM THE SAFETY VALVE	HYDROGEN SULFIDE		LBS
EXXON CO USA	19920511		ARMWASH HEADER/GASKET FAILED	OIL, FUEL: NO. 2-D	1	BBL
EXXON CO USA	19920813		ROLL OFF BOX/MATERIAL SPILLED OUT OF BOX WHEN IT WAS LIFTED	F037, F038 SLUDGE	0	NON

EXXON CO USA	19920926		LEAKING TRANSFER LINE	OIL: DIESEL		UNK
EXXON CO USA	19920927		8" PIPELINE HAD PINHOLE LEAK	OIL: CRUDE	0	NON
EXXON CO USA	19920928		FUEL BLENDING PAD/FIRE WAS CAUSE OF MATERIAL LEAKAGE	DAF FLOAT		UNK
EXXON CO USA	19930219		STORAGE TANK OVERFILL STORAGE TANK OVERFILL	METHYL TERT-BUTYL ETHER		UNK
EXXON CO USA	19930930		STORAGE TANK WITHIN REFINERY / EXXON SUSPECTS A RELEASE DUE TO A DROP OF THE LEVEL WITHIN THE TANK	JET FUEL: JP-4	0	NON
EXXON CO USA	19931128		ABOVE GROUND STORAGE TANK/ LEAK/ UNKNOWN CAUSE/ LEAK WAS 43 FEET UP ON THE SIDE/	GASOLINE: AUTOMOTIVE (4.23G PB/G	0	NON
EXXON CO USA	19940104	VALVE	ABOVE GROUND STORAGE TANK, VALVE LEAKED DUE TO UNKNOWN REASONS ABOVE GROUND STORAGE TANK, VALVE LEAKED DUE TO UNKNOWN REASONS	PETROLEUM NAPHTHA	0	UNK
EXXON CO USA	19940104	VALVE	ABOVE GROUND STORAGE TANK, VALVE LEAKED DUE TO UNKNOWN REASONS ABOVE GROUND STORAGE TANK, VALVE LEAKED DUE TO UNKNOWN REASONS	BENZENE	0	
EXXON CO USA	19940429	VALVE	ABSORBER TOWER/LOST COMPRESSOR CAUSING RELIEF VALVE TO OPEN ABSORBER TOWER/LOST COMPRESSOR CAUSING RELIEF VALVE TO OPEN	HYDROGEN GAS WITH HYDROCARBONS	0	UNK
EXXON CO USA	19940622	VALVE	SAFETY VALVE RELEASED/EQUIPMENT FAILURE SAFETY VALVE RELEASED/EQUIPMENT FAILURE	BUTADIENE	0	UNK
EXXON CO USA	19940708		A SHEEN WAS DISCOVERED COMMING FROM A FACILITY OUTFALL DUE TO RESIDUAL OIL BEING WASHED OUT OF THE SEWER SYSTEM BY TO HEAVY RAINFALL	UNKNOWN OIL	0	UNK
EXXON CO USA	19950425	POWER FAILURE	REFINERY FLARES/POWER OUTTAGE REFINERY FLARES, POWER OUTTAGE	BENZENE	0	UNK

EXXON CO USA	19950425	POWER FAILURE	REFINERY FLARES/POWER OUTTAGE REFINERY FLARES, POWER OUTTAGE	HYDROGEN SULFIDE	0	UNK
EXXON CO USA	19950425	POWER FAILURE	REFINERY FLARES/POWER OUTTAGE REFINERY FLARES, POWER OUTTAGE	SULFUR DIOXIDE	0	UNK
EXXON CO USA	19960129	CONTAINER LEAK	NO.1 LIGHT ENDS UNIT RERUN FURNACE / TUBE LEAKED #1 LIGHT ENDS UNIT RERUN FURNACE/TUBE LEAKED	HYDROCARBONS	0	UNK
EXXON CO USA	19960129	CONTAINER LEAK	NO.1 LIGHT ENDS UNIT RERUN FURNACE / TUBE LEAKED #1 LIGHT ENDS UNIT RERUN FURNACE/TUBE LEAKED	HYDROGEN SULFIDE	0	UNK
EXXON CO USA	19960129	CONTAINER LEAK	NO.1 LIGHT ENDS UNIT RERUN FURNACE / TUBE LEAKED #1 LIGHT ENDS UNIT RERUN FURNACE/TUBE LEAKED	SULFUR DIOXIDE	0	UNK
EXXON CO USA	19960208	CONTAINER LEAK	PIPE STILL#7, FURNACE TUBE FAILED, RESULTED IN FIRE, RELEASE PIPE STILL #7 / FURNACE TUBE FAILED RESULTING IN FIRE AND RELEASE / FURNACE WAS FED BY STORAGE TANK OF UNKNOWN CAPACITY	CRUDE HYDROCARBONS >100LBS	0	UNK
EXXON CO USA	19960208	CONTAINER LEAK	PIPE STILL#7, FURNACE TUBE FAILED, RESULTED IN FIRE, RELEASE PIPE STILL #7 / FURNACE TUBE FAILED RESULTING IN FIRE AND RELEASE / FURNACE WAS FED BY STORAGE TANK OF UNKNOWN CAPACITY	SULFUR DIOXIDE >1LB	0	UNK
EXXON CO USA	19960219	CONTAINER LEAK	HEAT EXCHANGER COOLER,CORROSION CAUSED COOLER TUBE FAILURE HEAT EXCHANGER COOLER / CORROSION CAUSED COOLER TUBE FAILURE / TUBE SIZE UNKNOWN	HYDROCARBON - 2-3% BENZENE	0	UNK
EXXON CO USA	19960221	FITTING	PROCESS UNIT / SYSTEM UPSET PROCESS UNIT/SYSTEM UPSET	BENZENE	0	UNK
EXXON CO USA	19960221	FITTING	PROCESS UNIT / SYSTEM UPSET PROCESS UNIT/SYSTEM UPSET	HYDROGEN SULFIDE	0	UNK

EXXON CO USA	19960221	FITTING	PROCESS UNIT / SYSTEM UPSET PROCESS UNIT/SYSTEM UPSET	CARBONYL SULFIDE	0	UNK
EXXON CO USA	19960321	CONTAINER LEAK	VENT STACK, CO FURNACE FAILED DUE TO A STEAM TUBE RUPTURE VENT STACK/CO FURNACE FAILED DUE TO A STEAM TUBE RUPTURE	SULFUR DIOXIDE	0	UNK
EXXON CO USA	19960529	UNKNOWN	ABOVE GROUND STORAGE TANKN, SUSPECTED HOLE IN BOTTOM OF TANK STORAGE TANK/SUSPECTED HOLE IN BOTTOM OF TANK	WASTE WATER TRACE AMOUNTS OF BE	0	UNK
EXXON CO USA	19960605	FITTING	FLARE SYSTEM, PILOT WENT OUT FLARE SYSTEM / PILOT WENT OUT	HYDROGEN SULFIDE	0	UNK
EXXON CO USA	19960605	FITTING	FLARE SYSTEM, PILOT WENT OUT FLARE SYSTEM / PILOT WENT OUT	SULFUR DIOXIDE	0	UNK
EXXON CO USA	19960607		TANK 396 / ABOVE GROUND STORAGE TANK(CAP: 50000BBL) / OVERFILLED THE TANK / UNKNOWN IF INSTRUMENT FAILURE OR OPER. ERROR	SPENT ACID / PRIMARILY SULFURIC	0	UNK
EXXON CO USA	19960608		TUBING ON 735 TANK / TUBING FAILURE	GASOLINE: AUTOMOTIVE (UNLEADED)	0	NON
EXXON CO USA	19960610	FITTING	CAT CRACKING UNIT, BLOWER WAS TRIPPED ON THE CONTROL DEVICE CAT CRACKING UNIT / BLOWER WAS TRIPPED ON THE CONTROL DEVICE	SULFUR DIOXIDE	0	UNK
EXXON CO USA	19960610	FITTING	CAT CRACKING UNIT, BLOWER WAS TRIPPED ON THE CONTROL DEVICE CAT CRACKING UNIT / BLOWER WAS TRIPPED ON THE CONTROL DEVICE	TOTAL PARTICULATES	0	UNK
EXXON CO USA	19960610	FITTING	CAT CRACKING UNIT, BLOWER WAS TRIPPED ON THE CONTROL DEVICE CAT CRACKING UNIT / BLOWER WAS TRIPPED ON THE CONTROL DEVICE	CARBON MONOXIDE	0	UNK
EXXON CO USA	19960614		#2 LIGHT END UNIT / WELL INTERSEC OF 30IN & 2IN TRANSFER LINES CRACKED	HYDROGEN SULFIDE	0	UNK

EXXON CO USA	19960614		#2 LIGHT END UNIT / WELL INTERSEC OF 30IN & 2IN TRANSFER LINES CRACKED	LIGHT HYDROCARONS	0	UNK
EXXON CO USA	19960917	CONTAINER LEAK	REFINERY SEWER LINE, LINE RUPTURE REFINERY SEWER LINE/LINE RUPTURE	PRIMARY SLUDGE WASTE CODE F037	0	UNK
EXXON CO USA	19970210	CONTAINER LEAK	HYDROCARBON LEAK FROM HEAT EXCHANGER TO COOING TOWER,POSSIBLE HYDROCARBON LEAK FROM THE HEAT EXCHANGER TO THE COOLING TOWER. POSSIBLE LEAK IN TUBE BUNDLE	BUTADIENE, BUTYLENE MIXTURE (INH)	0	UNK
EXXON CO USA	19970210	CONTAINER LEAK	HYDROCARBON LEAK FROM HEAT EXCHANGER TO COOING TOWER,POSSIBLE HYDROCARBON LEAK FROM THE HEAT EXCHANGER TO THE COOLING TOWER. POSSIBLE LEAK IN TUBE BUNDLE	HYDROCARBON	0	UNK
EXXON CO USA	19970210	CONTAINER LEAK	HYDROCARBON LEAK FROM HEAT EXCHANGER TO COOING TOWER,POSSIBLE HYDROCARBON LEAK FROM THE HEAT EXCHANGER TO THE COOLING TOWER. POSSIBLE LEAK IN TUBE BUNDLE	HYDROGEN SULFIDE	0	UNK
EXXON CO USA	19970523	CONTAINER LEAK	FOUL MEA LINE, CORROSION ON LINE FOUL MEA LINE / CORROSION ON LINE	HYDROGEN SULFIDE	0	UNK
EXXON CO USA	19970523	FLANGE	RECYCLE GAS LINE ON HYDROCRACKER UNIT,FLANGE OPENED UP RECYCLE GAS LINE ON HYDROCRACKER UNIT / FLANGE OPENED UP	HYDROGEN SULFIDE	0	UNK
EXXON CO USA	19970526	VALVE	GAS COMPRESSOR,A SAFETY VALVE MALFUNCTIONED GAS COMPRESSOR / A SAFETY VALVE MALFUNCTIONED	HYDROGEN SULFIDE	0	UNK
EXXON CO USA	19970914	CONTAINER LEAK	HEAT EXCHANGER ON COOLING TOWER HAD A LEAK/RELEASE TO ATMOSPHERE COOLING TOWER / A HEAT EXCHANGER DEVELOPED A LEAK CAUSING A RELEASE TO THE ATMOSPHERE	POLY NUCLEAR HYDOCARBINS	0	UNK

EXXON CO USA	19971113		TANK 99,ROOF OF TANK HAD A SEAM SEPARATION,CAUSING VAPOR** TANK 99 / ROOF OF TANK HAD A SEEM SEPARATION CAUSING A VAPOR RELEASE SEPARATION OCCURRED DURING A PROCESS THAT CAUSING TH	BENZENE	0	UNK
--------------	----------	--	--	---------	---	-----

### EXXON CO, USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CO, USA	19920703	IMPROPER STORAGE/HANDLING	DRUM OF KO48//SPILLED WHILE BEING MOVED DRUM OF KO48 // SPILLED WHILE BEING MOVED	HAZARDOUS WASTE KO48		LBS

### EXXON CO. USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CO. USA	19920227	VALVE	PROCESS UNIT/VALVE RELEASE PROCESS UNIT/VALVE RELEASE	BENZENE		LBS

### EXXON CO. USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CO. USA	19871014		HYDRON CRACKING UNIT CRACK IN PIPELINE WELD	CYCLO-PENTANE		

### EXXON CO., U.S.A.

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON CO., U.S.A.	19900827		NO. 10 DISTILLATION UNIT / UPSET IN THE FEED DURING START-UP PROCEDURE	BENZENE	0	NON

EXXON CO., U.S.A.	19900906		FRACTIONATOR UNIT / SAFETY VALVE RELEASED	HYDROGEN SULFIDE	0	NON
-------------------	----------	--	---	------------------	---	-----

EXXON CO., U.S.A.	19901011		COOLING TOWER EXCHANGER/ EQUIPMENT FAILURE	HYDROGEN SULFIDE	0	NON
-------------------	----------	--	--	------------------	---	-----



EXXON CO., U.S.A.	19901011		COOLING TOWER EXCHANGER/ EQUIPMENT FAILURE	NON METHANE HYDROCARBONS	0	NON
EXXON CO., U.S.A.	19910508		LIGHT END UNIT/ SAFETY VALVE OPENED DUE TO OVER-PRESSURE	CHLORINATED HYDROCARBONS	0	NON
EXXON CO., U.S.A.	19910508		LIGHT END UNIT/ SAFETY VALVE OPENED DUE TO OVER-PRESSURE	BENZENE	0	NON
EXXON CO., U.S.A.	19910909		STORAGE TANK/ VALVE LEFT OPEN	BENZENE	0	NON
EXXON CO., U.S.A.	19910909		SAFETY VALVE LEAK ON A DISTILLATION TOWER	BENZENE	0	NON
EXXON CO., U.S.A.	19910923		SAFETY VALVE / FAILED PRESSURE INDICATOR	HYDROCARBONS	0	NON
EXXON CO., U.S.A.	19910923		SAFETY VALVE / FAILED PRESSURE INDICATOR	HYDROGEN SULFIDE	0	NON

## EXXON COMPANY

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON COMPANY	19970523	CONTAINER LEAK	NO.1 SOUR WATER STRIPPER UNIT LINE LEAKED NO. 1 SOUR WATER STRIPPER UNIT LINE LEAKED	AMMONIA, ANHYDROUS	0	UNK

## EXXON COMPANY USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON COMPANY USA	19921229		12" PIPELINE/ REPAIRING A LEAK AND ANOTHER RELEASE OCCURRED	GASOLINE: AUTOMOTIVE (4.23G PB/G)	5	GAL
EXXON COMPANY USA	19930111		AN OUTFALL OVERFLOWED DUE TO HEAVY RAIN	OIL: CRUDE	0	UNK
EXXON COMPANY USA	19931029	RAIN OR SNOW	THE FACILITY STORM WATER INTERNMENT SYSTEM OVERFLOWED>RAINFALL THE FACILITY STORM WATER INTERNMENT SYSTEM OVERFLOWED>RAINFALL	JET FUEL: JP-4	1	BBL

EXXON COMPANY USA	19940105		A BLENDING PAD HAD A GASKET FAIL	GASOLINE: AUTOMOTIVE (UNLEADED)	0	NON
EXXON COMPANY USA	19961025		STORM SEWER SYSTEM / IT APPEARS THAT HEAVY RAIN IS WASHING RESIDUAL MATERIAL FROM THE SEWER LINE CAUSING A SHEEN ON THE WATER	UNKNOWN OIL	0	UNK
EXXON COMPANY USA	19961029	UNKNOWN	OIL WAS RELEASED FROM A HEAT EXCHANGER TO A COOLING TOWER DUE* OIL WAS RELEASED FM A HEAT EXCHANGER TO A COOLING TOWER DUE TO UNKNOWN CAUSES AT THIS TIME	MISC. HYDROCARBONS	0	UNK
EXXON COMPANY USA	19961029	UNKNOWN	OIL WAS RELEASED FROM A HEAT EXCHANGER TO A COOLING TOWER DUE* OIL WAS RELEASED FM A HEAT EXCHANGER TO A COOLING TOWER DUE TO UNKNOWN CAUSES AT THIS TIME	HYDROGEN SULFIDE	0	UNK
EXXON COMPANY USA	19961029	UNKNOWN	OIL WAS RELEASED FROM A HEAT EXCHANGER TO A COOLING TOWER DUE* OIL WAS RELEASED FM A HEAT EXCHANGER TO A COOLING TOWER DUE TO UNKNOWN CAUSES AT THIS TIME	1,-3 BUTADIENE	0	UNK
EXXON COMPANY USA	19961029	CONTAINER LEAK	HEAT EXCHANGER, DEVELOPED A LEAK HEAT EXCHANGER / DEVELOPED A LEAK	HYDROGEN SULFIDE	0	UNK
EXXON COMPANY USA	19961031		STORAGE TANK OVERFILL DURING MAINTENANCE	WASTEWATER(CONTAINS BENZENE)	0	NON
EXXON COMPANY USA	19961211	CONTAINER LEAK	COKER UNIT, COOLER LEAKED GAS INTO ATMOSPHERE AT THE COOLING COKER UNIT / COOLER LEAKED GAS INTO THE ATMOSPHERE AT THE COOLING TOWERREASON FOR LEAK IS UNKNOWN	COKER GAS	0	UNK
EXXON COMPANY USA	19971121		OUTFALL NO.003 / HAEVY RAINS CAUSED A RELEASE AND CREATED A SMALL SHEEN IN CALLAHAN'S BAYOU	OTHER OIL	0	UNK

EXXON COMPANY USA	19971203		FACILITY PIPE(UNK SIZE)LINE LEAKED DUE TO SUSPECTED CORROSION FACILITY PIPE (SIZE UNKNOWN) / THE LINE LEAKED DUE TO SUSPECTED CORROSION	D018 (WASTE WATER CONTAINING BEN	0	UNK
-------------------	----------	--	---	-------------------------------------	---	-----

### EXXON COMPANY, USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON COMPANY, USA	19961031	OVERFLOW	STORAGE TANK OVERFILL DURING MAINTENANCE STORAGE TANK OVERFILL DURING MAINTENANCE	WASTEWATER(CONTAINS BENZENE)	0	UNK

### EXXON OIL CO

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON OIL CO	19930303		DOCKSIDE PUMP HOSE/COUPLING CAME LOOSE	MIXED GAS OIL	0	GAL

### EXXON OIL CO.

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON OIL CO.	19910703		LOADING ARM / HYDRAULIC LINE LEAK	HYDRAULIC OIL	1	OTH

### EXXON OIL COMPANY

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON OIL COMPANY	19940708		OIL SEPERATOR/OVERFILLED DUE TO HEAVY RAINS	UNKNOWN OIL	0	UNK

### EXXON PIPELINE

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON PIPELINE	19900605		FITTING FAILURE FROM A FIELD GATHERING UNIT	OIL: CRUDE	0	UNK

EXXON PIPELINE	19901030		PIPELINE/ LEAKING PACKING ON PUMP	OIL: CRUDE	5	GAL
EXXON PIPELINE	19910325		ABOVE GROUND STORAGE TANK / LEAKY FITTING ON DISCHARGE HOSE	OIL: DIESEL	1	GAL
EXXON PIPELINE	19911215		12" PIPELINE/HAS BECOME EXPOSED DUE TO EROSION OF SURFACE MATERIAL	OIL: CRUDE	0	NON
EXXON PIPELINE	19930126		6 INCH GATHERING PIPELINE/UNKNOWN/SHEEN DESC NOT AVAILABLE 6 INCH GATHERING PIPELINE/UNKNOWN SHEEN DESC NOT AVAILABLE	OIL: CRUDE		GAL
EXXON PIPELINE	19930130		PROVER ON A FLOW LINE/UNKNOWN	OIL: CRUDE	0	UNK
EXXON PIPELINE	19930210		UNK.PIPELINE/UNK.METERS SHOWED PRESSURE DROP INDICATING RELEASE. UNK.PIPELINE/UNK.METERS SHOWED PRESSURE DROP INDICATING RELEASE	OIL: CRUDE		UNK
EXXON PIPELINE	19930412		PIPELINE / LEAKING	OIL: CRUDE(2 DROPS = .0009 GAL)	2	OTH
EXXON PIPELINE	19930607		6 INCH PIPELINE / CAUSE UNKNOWN 6 INCH PIPELINE / CAUSE UNKNOWN	OIL: CRUDE	25	BBL
EXXON PIPELINE	19930621		2" VALVE ON A SUMP TANK SUCTION LINE / VALVE FAILED	OIL: CRUDE	1	GAL
EXXON PIPELINE	19930627		METER TUBING/RELEASED PRODUCT TO UNKNOWN CAUSES METER TUBING/RELEASED PRODUCT TO TO UNKNOWN CAUSES	OIL: CRUDE	0	UNK
EXXON PIPELINE	19930628		8 INCH PIPELINE WAS LEAKING DUE TO UNKNOWN CAUSE 8 INCH PIPELINE WAS LEAKING DUE TO UNKNOWN CAUSE	OIL: CRUDE	0	UNK
EXXON PIPELINE	19930702	CONTAINER LEAK	4 INCH PIPELINE/ LEAKING DUE TO UNKNOWN REASONS 4 INCH PIPELINE/LEAKING DUE TO UNKNOWN REASONS	OIL: CRUDE	25	BBL

EXXON PIPELINE	19930721	PUMP	PROPANE PUMP / SEAL FAILURE PROPANE PUMP / SEAL FAILURE	PROPANE	0	LBS
EXXON PIPELINE	19930818	TANK OR CONTAINER	AST/FLOATING ROOF,OIL WAS PUSHED OUT ON ROOF DURING MAINTENANCE AST/FLOATING ROOF,OIL WAS PUSHED OUT ON ROOF DURING MAINTENANCE	OIL: CRUDE	0	LBS
EXXON PIPELINE	19930916		8 INCH PIPELINE / UNKNOWN 8 INCH PIPELINE / UNKNOWN	OIL: CRUDE	3	BBL
EXXON PIPELINE	19931004		8 INCH TRANSMISSION PIPELINE / UNKNOWN	OIL: CRUDE	2	BBL
EXXON PIPELINE	19931021		A 16 INCH PIPELINE WAS LEAKING DUE TO UNKNOWN CAUSE A 16 INCH PIPELINE WAS LEAKING DUE TO UNKNOWN CAUSE	OIL: CRUDE	0	UNK
EXXON PIPELINE	19931021	CONTAINER LEAK	16 INCH PIPELINE LEAKING DUE TO UNKNOWN CAUSE 16 INCH PIPELINE LEAKING DUE TO UNKNOWN CAUSE	OIL: CRUDE	0	LBS
EXXON PIPELINE	19931023		UNK/CALLER STATES CITIZEN SAW OIL POCKET IN AREA NEAR EXXON LINE UNK/CALLER STATES CITIZEN SAW OIL POCKET IN AREA NEAR EXXON LINE	OIL: CRUDE	0	UNK
EXXON PIPELINE	19931025	IMPROPER OPERATION	4 INCH GATHERING PIPELINE / STRUCK BY LOGGERS 4 INCH GATHERING PIPELINE / STRUCK BY LOGGERS	OIL: CRUDE	0	UNK
EXXON PIPELINE	19931125		STRUCTURE LINE ON PUMP / FLANGE LEAK	OIL: CRUDE (OTH = PINT)	1	OTH
EXXON PIPELINE	19931213	PIPELINE	8 INCH PIPELINE / SPILLED WHILE BEING TESTED 8 INCH PIPELINE, SPILLED WHILE BEING TESTED	OIL: CRUDE	3	BBL
EXXON PIPELINE	19940125		8 INCH PIPELINE/CAUSE UNKNOWN AT THIS TIME 8 INCH PIPELINE/CAUSE UNKNOWN AT THIS TIME	OIL: CRUDE	0	UNK

EXXON PIPELINE	19940430		16 INCH PIPELINE/IF RELEASE OCCURRED, THE CAUSE IS UNKNOWN 16 INCH PIPELINE/IF RELEASE OCCURRED, THE CAUSE IS UNKNOWN	OIL: CRUDE	0	UNK
EXXON PIPELINE	19940523		4" LINE / CORROSION	OIL: CRUDE	0	NON
EXXON PIPELINE	19940705	PIPELINE	16 INCH PIPELINE / UNKNOWN 16 INCH PIPELINE / UNKNOWN	OIL: CRUDE	250	BBL
EXXON PIPELINE	19940921	PIPELINE	4-INCH PIPELINE, CLEANING "OUT OF SERVICE"LINE,A SMALL AMT* 4-INCH PIPELINE,CLEANING"OUT OF SERVICE"LINE, A SMALL AMT*	OIL: CRUDE	0	UNK
EXXON PIPELINE	19941005	CONTAINER LEAK	10 INCH PIPELINE LEAKED DUE TO CORROSION 10 INCH PIPELINE LEAKED DUE TO CORROSION	OIL: CRUDE	50	BBL
EXXON PIPELINE	19941020	FITTING	ETHYLENE TOWER/MATERIAL WAS RELEASED DURING PURGING ETHYLENE TOWER/MATERIAL WAS RELEASED DURING PURGING	SULFUR DIOXIDE	0	UNK
EXXON PIPELINE	19950131		4 INCH BELOW GROUND PIPELINE/SMALL SHEEN NOTICED WHILE PUMPING WATER INTO PIPELINE//TAKING PIPELINE OUT OF SERVICE/DISPLACING WITH WATER	OIL: CRUDE	1	PNT

## EXXON PIPELINE CO

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON PIPELINE CO	19900606		UNK/UNK	OIL: CRUDE	100	BBL
EXXON PIPELINE CO	19910621		6" PIPELINE/ UNKNOWN	OIL: CRUDE	0	UNK
EXXON PIPELINE CO	19910708		CATCH PAN / OVERFLOW DUE TO HEAVY RAINS	OIL: CRUDE	0	GAL
EXXON PIPELINE CO	19910926		4 INCH DISCHARGE LINE / UNKNOWN	OIL: CRUDE	5	BBL

EXXON PIPELINE CO	19911030		8 INCH UNDERGROUND PIPELINE / DISCOVERED A BROKEN VALVE ON THE LINE.	BUTANE	0	NON
EXXON PIPELINE CO	19920106	FITTING	CRUDE OIL PUMP/FAILED DIAPHRAGM CRUDE OIL PUMP / FAILED DIAPHRAM	OIL: CRUDE		BBL
EXXON PIPELINE CO	19920227		REPORTING 2 EXPOSED PIPELINES (8 INCH AND 12 INCH)		0	
EXXON PIPELINE CO	19920227		REPORTING A 12 INCH EXPOSED PIPELINE		0	
EXXON PIPELINE CO	19920227		REPORTING AN EXPOSED PIPELINE (8 INCH)		0	
EXXON PIPELINE CO	19920227		REPORTING A "HAZARD TO NAVIGATION" - 12 INCH PIPELINE COVERED BY LESS THAN 1 FT OF WATER		0	
EXXON PIPELINE CO	19920227		REPORTING A "HAZARD TO NAVIGATION" - 12 INCH PIPELINE COVERED BY LESS THAN 1 FT OF WATER		0	
EXXON PIPELINE CO	19920319		UNKNOWN/UNKNOWN (PUMPING STATION DRIP PAN OVERFLOWED) UNKNOWN/UNKNOWN (PUMPING STATION DRIP PAN OVERFLOWED)	OIL: CRUDE		GAL
EXXON PIPELINE CO	19920320		12 INCH PIPELINE/VANDALIZED	OIL: CRUDE		UNK
EXXON PIPELINE CO	19920521		8" CRUDE OIL PIPELINE/UNKNOWN	OIL: CRUDE	0	UNK
EXXON PIPELINE CO	19920629		4 INCH PIPELINE/UNKNOWN	OIL: CRUDE	0	GAL
EXXON PIPELINE CO	19920727		METER INDICATING SHORTAGE OF MATERIAL COMING IN A PIPELINE METER INDICATING SHORTAGE OF MATERIAL COMING IN A PIPELINE	OIL: CRUDE		UNK
EXXON PIPELINE CO	19920807		REPORTING AN EXPOSED 12" PIPELINE AND AN 8" PIPELINE		0	

EXXON PIPELINE CO	19920831		ABANDONED 4" PIPELINE/TREE FELL ON LINE BREAKING OFF A HEADER NIPPLE	OIL: CRUDE	3	BBL
EXXON PIPELINE CO	19920904		4" PIPELINE/LEAK DUE TO UNKNOWN CAUSE, SUSPECTED THIRD PARTY DAMAGE	OIL: CRUDE	1	GAL
EXXON PIPELINE CO	19920916		UNKNOWN / UNKNOWN COMPANY WAS NOTIFIED THAT OIL WAS LEAKING FROM A PUMPING STATION	OIL: CRUDE	0	UNK
EXXON PIPELINE CO	19920918		NON-REGULATED 6 INCH PIPELINE/CORROSION BELIEVED TO BE CAUSE NON-REGULATED 6 INCH PIPELINE/CORROSION BELIEVED TO BE CAUSE	OIL: CRUDE		LBS
EXXON PIPELINE CO	19920921	PIPELINE	PIPELINE/ LEAKED PIPELINE / LEAKED	OIL: CRUDE		LBS
EXXON PIPELINE CO	19920921		PIPELINE 8" GATHERING PIPELINE/LEAKING DUE TO SUSPECTED CORROSION	OIL: CRUDE		UNK
EXXON PIPELINE CO	19920922		6" PIPELINE/SOIL CONTAMINATION DISCOVERED WHILE MAINTENANCE WAS BEING PERFORMED ON THE LINE	HEAVY FUEL OIL	0	UNK
EXXON PIPELINE CO	19920922		4" PIPELINE/SOIL CONTAMINATION DISCOVERED WHILE MAINTENANCE WAS BEING PERFORMED ON THE LINE	PERAXYLENE	0	UNK
EXXON PIPELINE CO	19920926		6" DISCHARGE PIPELINE//UNKNOWN	OIL: DIESEL		UNK
EXXON PIPELINE CO	19920928		22" PIPELINE / FLASH FIRE DUE TO MALFUCTION OF EQUIPMENT		0	
EXXON PIPELINE CO	19921116		UNKNOWN / UNKNOWN SHEEN SIGHTING SHEEN SIZE:4000' X 15' COLOR UNKNOWN	OIL: CRUDE	0	UNK
EXXON PIPELINE CO	19921119	PIPELINE	PIPELINE / CORROSION PIPELINE / CORROSION	OIL: CRUDE		LBS



EXXON PIPELINE CO	19930622	VALVE	SUMP TANK/OVERFILLED DUE TO 1 INCH VALVE ON 6 INCH PIPELINE SUMP TANK/OVERFILLED DUE TO 1 INCH VALVE ON A 6 INCH PIPELINE	OIL: CRUDE	0	GAL
EXXON PIPELINE CO	19931023		8 INCH PIPELINE/LEAK DUE TO UNKNOWN CAUSES 8 INCH PIPELINE/ LEAK DUE TO UNKNOWN CAUSES	OIL: CRUDE	0	LBS
EXXON PIPELINE CO	19940128	TANK OR CONTAINER	MIXER SEAL ON STORAGE TANK,RELEASE WAS CAUSED BY SEAL FAILURE MIXER SEAL ON STORAGE TANK,RELEASE CAUSED BY SEAL FAILURE	OIL: CRUDE	0	LBS
EXXON PIPELINE CO	19940131	PIPELINE	8 INCH PIPELINE IN GATHERING SYSTEM,LEAKAGE DUE TO CORROSION 8 INCH PIPELINE IN GATHERING SYSTEM,LEAKAGE DUE TO CORROSION	OIL: CRUDE	5	BBL
EXXON PIPELINE CO	19940320	OVERFLOW	STORAGE TANK / TANK WAS OVERFILLED STORAGE TANK/TANK WAS OVERFILLED	OIL: CRUDE	0	UNK
EXXON PIPELINE CO	19940330	IMPROPER OPERATION	8 INCH PIPELINE,DURING DISMANTLING OPERATIONS,SPILL OCCURRED 8 INCH PIPELINE,DURING DISMANTLING OPERATIONS,SPILL OCCURRED	OIL: CRUDE	5	GAL
EXXON PIPELINE CO	19940529		16 FLOW LINE/LEAKING DUE TO UNKNOWN CAUSES	OIL: CRUDE-WATER MIX 50/50	0	NON
EXXON PIPELINE CO	19940529		16" PIPELINE/ INTERNAL CORROSION HOLE/ SPILLED IN FIREWALL AREA	OIL: CRUDE AND PRODUCED WATER	0	NON
EXXON PIPELINE CO	19940529		THERE IS A SUSPECTED LEAK IN A 16 INCH PIPELINE OWNED BY EXXON	OIL: CRUDE	0	UNK
EXXON PIPELINE CO	19940712		THERE IS AN OIL RELEASE W/IN 20FT OF A 20" PIPELINE / IT IS UNSURE WHETHER IT IS THE SOURCE	OIL: CRUDE	3	BBL
EXXON PIPELINE CO	19941109		STORAGE TANK HAD A HOSE DETERIATE	OIL, FUEL: NO. 2-D	0	UNK
EXXON PIPELINE CO	19950310	CONTAINER LEAK	4 INCH PIPELINE, CORROSION 4 INCH PIPELINE, CORROSION	OIL: CRUDE	4	GAL

## EXXON PIPELINE CO.

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON PIPELINE CO.	19910612		UNKNOWN/ UNKNOWN MATERIAL DISCOVERED ON A BAYOU	OIL: CRUDE	0	UNK
EXXON PIPELINE CO.	19910716		CALIBRATION TANK / SIGHT GLASS FAILURE.	OIL: CRUDE	2	GAL
EXXON PIPELINE CO.	19911031		PUMP / PUMP SEAL FAILED	OIL: CRUDE	2	GAL
EXXON PIPELINE CO.	19920831		FIRE ON 12" PIPELINE SCRAPER TRAP / VAPORS IGNITED WHILE TRAP WAS BEING OPENED	BUTANE	0	NON

## EXXON PIPELINE COMPANY

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON PIPELINE COMPANY	19920320	VANDALISM	12 INCH PIPELINE/VANDALIZED 12 INCH PIPELINE/VANDALIZED	OIL:CRUDE OIL		UNK
EXXON PIPELINE COMPANY	19921110		4" DISCHARGE PIPELINE/ UNKNOWN	OIL: CRUDE	1	GAL
EXXON PIPELINE COMPANY	19921111		PIPELINE/LEAKING/UNKNOWN CAUSE PIPELINE/LEAKING UNKNOWN CAUSE	OIL: CRUDE		UNK
EXXON PIPELINE COMPANY	19921111		2 INCH PIPELINE / LEAK DUE TO UNKNOWN CAUSE 2 INCH PIPELINE / LEAK DUE TO UNKNOWN CAUSE	OIL: CRUDE		BBL

## EXXON PLASTICS

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON PLASTICS	19920218		PIPELINE/THE LINE HAD BEEN BLOWN OUT TO CLEAR THE LINE.	METHYLACRYLATE	0	NON
EXXON PLASTICS	19920801		POLYETHANE REACTOR/CAUGHT ON FIRE POLYETHANE REACTOR/CAUGHT ON FIRE	ETHYLENE		UNK
EXXON PLASTICS	19920826		FLARE EXTINGUISHED DUE TO THE HURRICANE	ETHYLENE GAS	0	NON

EXXON PLASTICS	19920910	FITTING	RAIL CAR LOADING SYSTEM/VENT COLLECTION LINE WAS PLUGGED RAIL CAR LOADING SYSTEM/VENT COLLECTION LINE WAS PLUGGED	ETHYLENE		LBS
EXXON PLASTICS	19920910	FITTING	REACTOR/RUPTURED DISK REACTOR/RUPTURED DISK	ETHYLENE		LBS
EXXON PLASTICS	19920910	CONTAINER LEAK	HIGH PRESSURE SEPARATOR/SEPARATOR HEAD LEAKED HIGH PRESSURE SEPARATOR / SEPARATOR HEAD LEAKED	ETHYLENE		LBS
EXXON PLASTICS	19921003	OVERFLOW	ABOVE GROUND STORAGE TANK /OVERFILLED STORAGE TANK / OVERFILLED	ISO OCTANE		LBS
EXXON PLASTICS	19921221	FITTING	RUPTURE DISK ON A LOW PRESSURE VESSEL/FAILED/OVERPRESSURIZATION RUPTURE DISK ON A LOW PRESSURE VESSEL/FAILED/OVERPRESSURIZATION	VINYL ACETATE		LBS
EXXON PLASTICS	19930127	CONTAINER LEAK	COMPRESSOR PIPING / PINHOLE LEAK DEVELOPED COMPRESSOR PIPING/PINHOLE LEAK DEVELOPED	ETHYLENE/VINYL ACETATE MIX		LBS
EXXON PLASTICS	19930404		RUPTURE DISK ON A COMPRESSOR/FAILED RUPTURE DISK ON A COMPRESSOR/FAILED	ETHYLENE	0	LBS
EXXON PLASTICS	19930709	FITTING	PIPE ON A COMPRESSOR CRACKED PIPE ON A COMPRESSOR CRACKED	ETHYLENE	0	LBS
EXXON PLASTICS	19930830	VALVE	COMPRESSOR/SAFETY VALVE OPENED DUE TO EXCESS PRESSURE COMPRESSOR/SAFETY VALVE OPENED DUE TO EXCESS PRESSURE	ETHYLENE	0	LBS
EXXON PLASTICS	19930830	VALVE	COMPRESSOR/SAFETY VALVE OPENED DUE TO EXCESS PRESSURE COMPRESSOR/SAFETY VALVE OPENED DUE TO EXCESS PRESSURE	VINYL ACETATE	0	
EXXON PLASTICS	19930830	VALVE	COMPRESSOR/SAFETY VALVE OPENED DUE TO EXCESS PRESSURE COMPRESSOR/SAFETY VALVE OPENED DUE TO EXCESS PRESSURE	ACETALDEHYDE	0	UNK

EXXON PLASTICS	19930914	FITTING	PURGE COMPRESSOR / PACKING BLEW OUT PURGE COMPRESSOR/PACKING BLEW OUT	ETHYLENE	0	LBS
EXXON PLASTICS	19930922		REACTOR/RUPTURED DISC	ETHYLENE	0	NON
EXXON PLASTICS	19930923		BLOWN RUPTURE DISK	ETHYLENE GAS	0	NON
EXXON PLASTICS	19931220		A COMPRESSOR HAD A DISK RUPTURE A COMPRESSOR HAD DISK RUPTURE	ETHYLENE	0	LBS
EXXON PLASTICS	19931220		A COMPRESSOR HAD A DISK RUPTURE A COMPRESSOR HAD DISK RUPTURE	CARBONIZED PLASTIC FLUFF	0	
EXXON PLASTICS	19940415	VALVE	REACTOR/RELIEF VALVE OPENED DUE TO COMPRESSOR MALFUNCTION REACTOR/RELIEF VALVE OPENED DUE TO COMPRESSOR MALFUNCTION	ETHYLENE	0	UNK
EXXON PLASTICS	19940415	VALVE	REACTOR/RELIEF VALVE OPENED DUE TO COMPRESSOR MALFUNCTION REACTOR/RELIEF VALVE OPENED DUE TO COMPRESSOR MALFUNCTION	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940419	FITTING	REACTOR RECYCLE DUMPS//RELEASED DUE TO PRESSURE REACTOR RECYCLE DUMPS//RELEASED DUE TO PRESSURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940420	VALVE	REACTOR/RELIEF VALVE OPENED DUE TO HIGH TEMPERATURE REACTOR/RELIEF VALVE OPENED DUE TO HIGH TEMPERATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940420	VALVE	REACTOR/RELIEF VALVE OPENED DUE TO HIGH TEMPERATURE REACTOR/RELIEF VALVE OPENED DUE TO HIGH TEMPERATURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940421	FITTING	REACTOR DUMP/ OPENED DUE TO HIGH TEMPERATURE REACTOR DUMP/OPENED DUE TO HIGH TEMP	ETHYLENE	0	UNK
EXXON PLASTICS	19940421	FITTING	REACTOR DUMP/ OPENED DUE TO HIGH TEMPERATURE REACTOR DUMP/OPENED DUE TO HIGH TEMP	VINYL ACETATE	0	UNK

EXXON PLASTICS	19940423	POWER FAILURE	POLYETHYLENE REACTOR SAFETY DEVICE, LEAKED> POWER FAILURE POLYETHYLENE REACTOR SAFETY DEVICE, LEAKED>POWER FAILURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940423	POWER FAILURE	POLYETHYLENE REACTOR SAFETY DEVICE, LEAKED> POWER FAILURE POLYETHYLENE REACTOR SAFETY DEVICE, LEAKED>POWER FAILURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940428	FITTING	PLASTIC REACTOR//LEAKED DUE TO A DUMP FAILURE PLASTIC REACTOR//LEAKED DUE TO A DUMP FAILURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940428	FITTING	PLASTIC REACTOR//LEAKED DUE TO A DUMP FAILURE PLASTIC REACTOR//LEAKED DUE TO A DUMP FAILURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940430	CONTAINER LEAK	BAKER REACTOR RECYCLE KNOCK OUT POT/CAME OFF OF DEFOUL/LEAK BAKER REACTOR RECYCLE KNOCK-OUT POT,CAME OFF OF DEFOUL/LEAK	ETHYLENE	0	UNK
EXXON PLASTICS	19940430	CONTAINER LEAK	BAKER REACTOR RECYCLE KNOCK OUT POT/CAME OFF OF DEFOUL/LEAK BAKER REACTOR RECYCLE KNOCK-OUT POT,CAME OFF OF DEFOUL/LEAK	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940506	FLANGE	ETHYLENE GAS PROCESS LINE//LEAKED DUE TO A FLANGE FAILURE ETHYLENE GAS PROCESS LINE//LEAKED DUE TO A FLANGE FAILURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940507	FITTING	NON-NUCLEAR REACTOR, TEMP INCREASED TOO QUICKLY IN STARTUP NON-NUCLEAR REACTOR,TEMP INCREASED TOO QUICKLY IN STARTUP	ETHYLENE	0	UNK
EXXON PLASTICS	19940507	FITTING	NON-NUCLEAR REACATOR,TEMP INCREASED QUICKLY,MAT RELEASED NON-NUCLEAR REACATOR,TEMP INCREASED QUICKLY, MAT RELEASED	ETHYLENE	0	UNK

EXXON PLASTICS	19940511	VALVE	NON-NUCLEAR REACTOR/DUMP VALVE OPENED DUE TO UNKNOWN CAUSE NON-NUCLEAR REACTOR/DUMP VALVE OPENED DUE TO UNKNOWN CAUSE	ETHYLENE	0	UNK
EXXON PLASTICS	19940511	VALVE	REACTOR/INTERLOCK OPERATION CAUSED REACTIVE DUMP VALVE OPEN REACTOR/INTERLOCK OPERATION CAUSED REACTIVE DUMP VALVE TO OPEN	ETHYLENE	0	UNK
EXXON PLASTICS	19940524	FLANGE	E-LINE REACTOR,SECOND COLD SIDESTREAM CHECK VALVE,FLANGE OPEN E-LINE REACTOR,SECOND COLD SIDESTREAM CHECK VALVE,FLANGE OPEN	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19940609	FITTING	REACTOR/SEAL FAILURE REACTOR/SEAL FAILURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940616		STARTING UP A LINE REACTOR/OPENED UP SAFETY AND RELEASED GAS STARTING UP A LINE REACTOR/OPENED UP SAFETY AND RELEASED GAS THAT WAS IN IT	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940616		STARTING UP A LINE REACTOR/OPENED UP SAFETY AND RELEASED GAS STARTING UP A LINE REACTOR/OPENED UP SAFETY AND RELEASED GAS THAT WAS IN IT	ACETALDEHYDE	0	UNK
EXXON PLASTICS	19940616		STARTING UP A LINE REACTOR/OPENED UP SAFETY AND RELEASED GAS STARTING UP A LINE REACTOR/OPENED UP SAFETY AND RELEASED GAS THAT WAS IN IT	ETHYLENE	0	UNK
EXXON PLASTICS	19940721	FITTING	A BLOWN RUPTURE DISK A BLOWN RUPTURE DISK	ETHYLENE GLYCOL GAS	0	UNK
EXXON PLASTICS	19940727	FITTING	CHEMICAL REACTOR F LINE/MAT RELEASED>HIGH TEMPERATURE CHEMICAL REACTOR F LINE/MAT RELEASED> HIGH TEMPERATURE	ETHYLENE	0	UNK

EXXON PLASTICS	19940727	FITTING	CHEMICAL REACTOR F LINE/MAT RELEASED>HIGH TEMPERATURE CHEMICAL REACTOR F LINE/MAT RELEASED> HIGH TEMPERATURE	BUTENE 1	0	UNK
EXXON PLASTICS	19940727	FITTING	F-LINE SECONDARY COMPRESSOR/RUPTURE DISK FAILED F-LINE SECONDARY COMPRESSOR/RUPTURE DISK FAILED	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19940727	FITTING	F-LINE SECONDARY COMPRESSOR/RUPTURE DISK FAILED F-LINE SECONDARY COMPRESSOR/RUPTURE DISK FAILED	BUTENE	0	UNK
EXXON PLASTICS	19940727	IMPROPER VALVE HANDLING	EFFLUENT DUMP VALVE,DURING MAINTENANCE,ACCIDENTLY MAT RELEASE EFFLUENT DUMP VALVE,DURING MAINTENANCE,ACCIDENTLY MAT RELEASE	ETHYLENE	0	UNK
EXXON PLASTICS	19940727	IMPROPER VALVE HANDLING	EFFLUENT DUMP VALVE,DURING MAINTENANCE,ACCIDENTLY MAT RELEASE EFFLUENT DUMP VALVE,DURING MAINTENANCE,ACCIDENTLY MAT RELEASE	1, BUTENE	0	UNK
EXXON PLASTICS	19940727	FITTING	REACTOR/DUMPED DUE TO COMPRESSOR FAILURE REACTOR/DUMPED DUE TO COMPRESSOR FAILURE	BUTANE	0	UNK
EXXON PLASTICS	19940727	FITTING	REACTOR/DUMPED DUE TO COMPRESSOR FAILURE REACTOR/DUMPED DUE TO COMPRESSOR FAILURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940728	IMPROPER OPERATION	VENT TO ATMOSPHERE/TECHNICIAN FORGOT TO SWITCH TO VENT VENT TO ATMOSPHERE,TECHNICIAN FORGOT TO SWITCH TO VENT	ETHYLENE	0	UNK
EXXON PLASTICS	19940807	FITTING	REACTOR SHUT DOWN DUE TO EQUIPMENT FAILURE REACTOR SHUT DOWN DUE TO EQUIPMENT FAILURE	ETHYLENE	0	UNK

EXXON PLASTICS	19940807	FITTING	REACTOR SHUT DOWN DUE TO EQUIPMENT FAILURE REACTOR SHUT DOWN DUE TO EQUIPMENT FAILURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940807	VALVE	A-LINE REACTOR,RELIEF VALVE OPENED DUE TO OVERPRESSURE A-LINE REACTOR,RELIEF VALVE OPENED DUE TO OVERPRESSURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940807	VALVE	A-LINE REACTOR,RELIEF VALVE OPENED DUE TO OVERPRESSURE A-LINE REACTOR,RELIEF VALVE OPENED DUE TO OVERPRESSURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19940807	VALVE	F-LINE REACTOR,RELIEF VALVES OPENED DUE TO OVERTEMPERATURE F-LINE REACTOR,RELIEF VALVES OPENED DUE TO OVERTEMPERATURE	BUTENE	0	UNK
EXXON PLASTICS	19940807	VALVE	F-LINE REACTOR,RELIEF VALVES OPENED DUE TO OVERTEMPERATURE F-LINE REACTOR,RELIEF VALVES OPENED DUE TO OVERTEMPERATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19940826	VALVE	F LINE REACTOR / DUMP VALVE OPENED F LINE REACTOR/DUMP VALVE OPENED	ETHYLENE (60%)	0	UNK
EXXON PLASTICS	19940826	VALVE	F LINE REACTOR / DUMP VALVE OPENED F LINE REACTOR/DUMP VALVE OPENED	BUTANE (40%)	0	UNK
EXXON PLASTICS	19940826	VALVE	F LINE REACTOR DUMP VALVE OPENED, HIGH TEMP ON ZONE ONE F LINE REACTOR DUMP VALVE OPENED//HIGH TEMP ON ZONE ONE	ETHYLENE	0	UNK
EXXON PLASTICS	19940826	VALVE	F LINE REACTOR DUMP VALVE OPENED, HIGH TEMP ON ZONE ONE F LINE REACTOR DUMP VALVE OPENED//HIGH TEMP ON ZONE ONE	ONE BUTENE	0	UNK
EXXON PLASTICS	19940905	VALVE	REACTOR HAD A RELIEF VALVE LIFT REACTOR HAD A RELIEF VALVE LIFT	ETHYLENE	0	UNK
EXXON PLASTICS	19940905	VALVE	REACTOR HAD A RELIEF VALVE LIFT REACTOR HAD A RELIEF VALVE LIFT	VINYL ACETATE	0	UNK



EXXON PLASTICS	19940921	PUMP	SEAL FAILURE ON AN ISO-OCTANE PUMP SEAL FAILURE ON AN ISO-OCTANE PUMP	ISOOCTANE	0	UNK
EXXON PLASTICS	19940923	IMPROPER OPERATION	F LINE RECYLCER WAXY POT, RUPTURE DISK FAILED, OVERPRESSURED F LINE RECYLER WAXY POT, RUPTURE DISK FAILED, OVERPRESSURED	BUTANE	0	UNK
EXXON PLASTICS	19940923	IMPROPER OPERATION	F LINE RECYLCER WAXY POT, RUPTURE DISK FAILED, OVERPRESSURED F LINE RECYLER WAXY POT, RUPTURE DISK FAILED, OVERPRESSURED	ETHYLENE	0	UNK
EXXON PLASTICS	19941013	VALVE	B LINE REACATOR, REACTOR DUMP VALVE OPENED B LINE REACTOR//REACTOR DUMP VALVE OPENED	2% VINYL ACETATE AND 98% ETHYLENE	0	UNK
EXXON PLASTICS	19941026	FLOW LINE	F LINE VENT SEAL POT, RUPTURED DISK FAILED, CAUSE UNKNOWN F LINE VENT SEAL PPOT, RUPTURED DISK FAILED, CAUSE UNKNOWN	ISOOCTANE & BENOL OIL	0	UNK
EXXON PLASTICS	19941031		REACTOR DUMP VALVE/OPENED	ETHYLENE	0	LBS
EXXON PLASTICS	19941101		REACTOR RECYCLE DUMP//HIGH PRESSURE	ETHYLENE GAS	0	NON
EXXON PLASTICS	19941116	FITTING	COMPRESSOR/SHUT DOWN/REACTOR DUMPED TO THE ATMOSPHERE COMPRESSOR/SHUT DOWN/REACTOR DUMPED TO THE ATMOSPHERE	ETHYLENE	0	UNK
EXXON PLASTICS	19941116	FITTING	COMPRESSOR/SHUT DOWN/REACTOR DUMPED TO THE ATMOSPHERE COMPRESSOR/SHUT DOWN/REACTOR DUMPED TO THE ATMOSPHERE	METHYL ACRYLATE	0	UNK
EXXON PLASTICS	19941116	FITTING	COMPRESSOR/SHUT DOWN/REACTOR DUMPED TO THE ATMOSPHERE COMPRESSOR/SHUT DOWN/REACTOR DUMPED TO THE ATMOSPHERE	ACRYLIC ACID	0	UNK
EXXON PLASTICS	19941126	FITTING	REACTOR BAY / CRACKED PIPE REACTOR BAY/CRACKED PIPE	ETHYLENE	0	UNK

EXXON PLASTICS	19941130		LEAKING SEAL ON PUMP P980B	VINYL ACETATE	3	LBS
EXXON PLASTICS	19941130	PUMP	VESSEL PUMP 980B,SEAL ON PUMP LEAKED,RELEASING THE MATERIAL VESSEL PUMP 980B/SEAL ON PUMP LEAKED RELEASING THE MATERIAL	VINYL ACETATE	0	UNK
EXXON PLASTICS	19941130	PUMP	VESSEL PUMP 980B,SEAL ON PUMP LEAKED,RELEASING THE MATERIAL VESSEL PUMP 980B/SEAL ON PUMP LEAKED RELEASING THE MATERIAL	N, HEXANE	0	UNK
EXXON PLASTICS	19941218	FITTING	E LINE SEPARATOR/ RUPTURED DISK E LINE SEPARATOR/RUPTURED DISK	ETHYLENE	0	UNK
EXXON PLASTICS	19941218	FITTING	E LINE REACTOR,HIGH PRESSURE SEPARATOR BLEW RUPTURE DISK E LINE REACTOR,HIGH PRESSURE SEPARATOR BLEW RUPTURE DISK	ETHYLENE	0	UNK
EXXON PLASTICS	19950101		REACTOR "B" - REACTOR DUMP VALVE - CAUSED BY BLOWN SEAL ON SECONDARY COMPRESSOR	ETHYLENE	0	NON
EXXON PLASTICS	19950101		REACTOR "B" - REACTOR DUMP VALVE - CAUSED BY BLOWN SEAL ON SECONDARY COMPRESSOR	VINYL ACETATE	0	NON
EXXON PLASTICS	19950105	OVERFLOW	LOSS OF BOILERS CAUSED A FLARE, A LIQUID OVERFLOW LOSS OF BOILERS CAUSED A FLARE/A LIQUID OVERFLOW	WASTE OIL	3	BBL
EXXON PLASTICS	19950114	FITTING	C-LINE REACTOR,HIGH TEMPERATURE INTERLOCK ACTIVATION C-LINE REACTOR, HIGH TEMPERATURE INTERLOCK ACTIVATION	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19950117	FITTING	ELON REACTOR/HIGH PRESSURE INTERLOCK OPENED ELON REACTOR/HIGH PRESSURE INTERLOCK OPENED	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19950117	FITTING	E-LINE REACTOR INTERLOCK FAILED E-LINE REACTOR INTERLOCK FAILED	ETHELYNE	0	UNK
EXXON PLASTICS	19950117	FITTING	E-LINE REACTOR INTERLOCK FAILED E-LINE REACTOR INTERLOCK FAILED	VINYL ACETATE	0	UNK

EXXON PLASTICS	19950125	VALVE	A LINE RECYCLE/ DUMP VALVE OPENED A LINE RECYCLE/DUMP VALVE OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19950125	VALVE	A LINE RECYCLE/ DUMP VALVE OPENED A LINE RECYCLE/DUMP VALVE OPENED	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950131	VALVE	F LINE REACTOR,DUMP VALVE ON RECYCLE SYSTEM LOST AIR PRESSURE F LINE REACTOR//DUMP VALVE ON RECYCLE SYSTEM LOST AIR PRESSURE AND OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19950131	VALVE	F LINE REACTOR,DUMP VALVE ON RECYCLE SYSTEM LOST AIR PRESSURE F LINE REACTOR//DUMP VALVE ON RECYCLE SYSTEM LOST AIR PRESSURE AND OPENED	BUTENE	0	UNK
EXXON PLASTICS	19950221	VALVE	REACTOR/DUMP VALVE OPENED FOR ABOUT 5 SECONDS REACTOR/DUMP VALVE OPENED FOR ABOUT 5 SECONDS	ETHYLENE	0	UNK
EXXON PLASTICS	19950221	VALVE	REACTOR/DUMP VALVE OPENED FOR ABOUT 5 SECONDS REACTOR/DUMP VALVE OPENED FOR ABOUT 5 SECONDS	BUTANE	0	UNK
EXXON PLASTICS	19950307		PROCESS UNIT//RECYCLE DUMP VALVE OPEN//INSTRUMENT FAILURE	ETHYLENE GAS	0	NON
EXXON PLASTICS	19950307		PROCESS UNIT//RECYCLE DUMP VALVE OPEN//INSTRUMENT FAILURE	ACETALDEHYDE	0	NON
EXXON PLASTICS	19950307		PROCESS UNIT//RECYCLE DUMP VALVE OPEN//INSTRUMENT FAILURE	VINYL ACETATE	0	NON
EXXON PLASTICS	19950308	CONTAINER LEAK	LEAK ON HIGH TEMPERATURE KNOCKOUT POT LEAK ON HIGH TEMPERATURE KNOCKOUT POT	ETHYLENE	0	UNK
EXXON PLASTICS	19950308	FITTING	HIGH PRESSURE KNOCKOUT POT / UNKNOWN HIGH PRESSURE KNOCKOUT POT / UNKNOWN	ETHYLENE	0	UNK
EXXON PLASTICS	19950309	VALVE	F-LINE REACTOR, DUMP VALVE OPENED F-LINE REACTOR, DUMP VALVE OPENED	ETHYLENE	0	UNK

EXXON PLASTICS	19950309	VALVE	F-LINE REACTOR, DUMP VALVE OPENED F-LINE REACTOR, DUMP VALVE OPENED	BUTENE	0	UNK
EXXON PLASTICS	19950320	VALVE	RECYCLE DUMP VALVE OPENED, RELEASING MATERIALS RECYCLE DUMP VALVE OPENED, RELEASING MATERIALS	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19950320	VALVE	RECYCLE DUMP VALVE OPENED, RELEASING MATERIALS RECYCLE DUMP VALVE OPENED, RELEASING MATERIALS	METHYL ACRYLATE	0	UNK
EXXON PLASTICS	19950320	VALVE	RECYCLE DUMP VALVE OPENED, RELEASING MATERIALS RECYCLE DUMP VALVE OPENED, RELEASING MATERIALS	ACRYLIC ACID	0	UNK
EXXON PLASTICS	19950325	CONTAINER LEAK	D REACTOR, THERMAL COUPLE LEAK D REACTOR/THERMAL COUPLE LEAK	ETHYLENE	0	UNK
EXXON PLASTICS	19950327	FITTING	"A" LINE REACTOR,DUMP OPENED ON 2ND POINT,HIGH TEMP.CONDITION "A" LINE REACTOR,DUMP OPENED ON 2ND POINT, HIGH TEM CONDITION	ETHYLENE	0	UNK
EXXON PLASTICS	19950327	FITTING	"A" LINE REACTOR,DUMP OPENED ON 2ND POINT,HIGH TEMP.CONDITION "A" LINE REACTOR,DUMP OPENED ON 2ND POINT, HIGH TEM CONDITION	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950328	FITTING	PROCESS UNIT COMPRESSOR UNIT NO C101, ETHYLENE BACKED UP PROCESS UNIT COMPRESSOR UNIT NO. C101//ETHYLENE BACKED UP	ETHYLENE	0	UNK
EXXON PLASTICS	19950423	POWER FAILURE	D LINE REACTOR DUMPED DUE TO ELECTRICAL POWER DIP D LINE REACTOR DUMPED DUE TO ELECTRICAL POWER DIP	ETHYLENE	0	UNK
EXXON PLASTICS	19950424		T810 TOWER//SAFETY VALVE OPENED PREMATURLY CAUSING MATERIALS TO RELEASE	ETHYLENE	0	UNK
EXXON PLASTICS	19950508	CONTAINER LEAK	REFRIGERATION COMPRESSOR, TUBE LEAKED REFRIGERATION COMPRESSOR/TUBE LEAKED	R-12 FREON	0	UNK

EXXON PLASTICS	19950514		A-LINE CHEMICAL REACTOR,DUMP OPEN BECAUSE OF HIGH FPI TEMPERATURE A-LINE CHEMICAL REACTOR/DUMP OPEN BECAUSE OF HIGH FPI TEMP.	ETHYLENE	0	UNK
EXXON PLASTICS	19950514		A-LINE CHEMICAL REACTOR,DUMP OPEN BECAUSE OF HIGH FPI TEMPERATURE A-LINE CHEMICAL REACTOR/DUMP OPEN BECAUSE OF HIGH FPI TEMP.	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950514	FITTING	REACTOR DUMP,FALSE HIGH TEMPERATURE REACTOR DUMP / FALSE HIGH TEMPERATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19950514	FITTING	REACTOR DUMP,FALSE HIGH TEMPERATURE REACTOR DUMP / FALSE HIGH TEMPERATURE	VINYL ACETATE	95	LBS
EXXON PLASTICS	19950514	VALVE	REACTOR DUMP, OPENED DUE TO FALSE READING REACTOR DUMP/ OPENED DUE TO A FALSE READING	ETHYLENE	0	UNK
EXXON PLASTICS	19950514	VALVE	REACTOR DUMP, OPENED DUE TO FALSE READING REACTOR DUMP/ OPENED DUE TO A FALSE READING	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950526	VALVE	PROCESS LINE,LINE DUMPED(SAFETY VALVE OPENED TO RELEASE PRESS.) PROCESS LINE,LINE DUMPED(SAFETY VALVE OPENED TO RELEASE PRESS.)	ETHYLENE	0	UNK
EXXON PLASTICS	19950602	FITTING	A REACTOR DUMP OPENED, INTERLOCK ACTIVATED A REACTOR DUMP OPENED/INTERLOCK ACTIVATED	ETHYLENE GAS AND VINYL ACETATE M	0	UNK
EXXON PLASTICS	19950702		DUMP SACK, OVERPRESSURE DUMP SACK/OVERPRESSURE	ETHYLENE	0	UNK
EXXON PLASTICS	19950702		DUMP SACK, OVERPRESSURE DUMP SACK/OVERPRESSURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950702	VALVE	REACTOR/MATERIAL RELEASED THRU RELIEF VALVE>OVERPRESSURE REACTOR/MATERIAL RELEASED THRU RELIEF VALVE>OVERPRESSURE	ETHYLENE	0	UNK

EXXON PLASTICS	19950702	VALVE	REACTOR/MATERIAL RELEASED THRU RELIEF VALVE>OVERPRESSURE REACTOR/MATERIAL RELEASED THRU RELIEF VALVE>OVERPRESSURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950704	FITTING	REACTOR/DUMPED DUE TO HIGH PRESSURE REACTOR/DUMPED DUE TO HIGH PRESSURE	ETHYLENE	0	UNK
EXXON PLASTICS	19950704	FITTING	REACTOR/DUMPED DUE TO HIGH PRESSURE REACTOR/DUMPED DUE TO HIGH PRESSURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950704		DURING REMOVAL OF OUT OF SER.2 INCH FLOWLINE,MATS RELEASED DURING REMOVAL OF OUT OF SER.2 INCH FLOWLINE,MATS RELEASED	METHYL ACRYLATE	0	UNK
EXXON PLASTICS	19950726		SLOP OIL TRANSFER PUMP/DISCHARGE FILTER O RING BLEW OUT	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950726		SLOP OIL TRANSFER PUMP/DISCHARGE FILTER O RING BLEW OUT	HEXANE	0	UNK
EXXON PLASTICS	19950726		SLOP OIL TRANSFER PUMP/DISCHARGE FILTER O RING BLEW OUT	OIL, MISC: LUBRICATING	0	UNK
EXXON PLASTICS	19950731		PROCESS REACTOR / HIGH TEMP CAUSED UPSET	ETHYLENE	0	NON
EXXON PLASTICS	19950802	FITTING	FLARE LINE, BLOWN RUPTURE DISK FLARE LINE/BLOWN RUPTURE DISK	ETHYLENE	0	UNK
EXXON PLASTICS	19950820	FITTING	REACTOR DUMP OPENED/ROD LOADING ON COMPRESSOR REACTOR DUMP OPENED/ROD LOADING ON COMPRESSOR	ETHYLENE	0	UNK
EXXON PLASTICS	19950820	FITTING	REACTOR DUMP OPENED/ROD LOADING ON COMPRESSOR REACTOR DUMP OPENED/ROD LOADING ON COMPRESSOR	VINYL ACETATE	0	UNK
EXXON PLASTICS	19950928		DOG REACTOR/RELEASED MATERIALS DUE TO HIGH TEMPRETURE	ETHYLENE GAS	0	NON

EXXON PLASTICS	19951003	FITTING	INTERLOCK SYSTEM OF A REACTOR, PRESSURE BUILD UP INTERLOCK SYSTEM OF A REACTOR / PRESSURE BUILD UP	EHTYLENE GAS	0	UNK
EXXON PLASTICS	19951025	CONTAINER LEAK	PROCESS REACTOR DURING START UP OF UNIT,OVERPRESSURE>RELEASE PROCESS REACTOR / DURING START-UP OF UNIT OVERPRESSURE CAUSED RELEASE	ETHYLENE	0	UNK
EXXON PLASTICS	19951026	POWER FAILURE	THE REACTOR ON A PROCESSING UNIT, POWER INTERRUPTION THE REACTOR ON A PROCESSING UNIT/POWER INTERRUPTION	ETHYLENE	0	UNK
EXXON PLASTICS	19951102		INTERLOCK ACTIVATED DUE TO HIGH TEMPATURE IN A POLYMER LINE	ETHYLENE	0	NON
EXXON PLASTICS	19951102		INTERLOCK ACTIVATED DUE TO HIGH TEMPATURE IN A POLYMER LINE	BUTENE	0	NON
EXXON PLASTICS	19951120	FITTING	OPERATING UNIT, VESSEL PROCESS UPSET, OVERPRESSURE CAUSED OPERATING UNIT/VESSEL/PROCESS UPSET CAUSED OVER PRESSURE	ETHYLENE	0	UNK
EXXON PLASTICS	19951120	FITTING	OPERATING UNIT, VESSEL PROCESS UPSET, OVERPRESSURE CAUSED OPERATING UNIT/VESSEL/PROCESS UPSET CAUSED OVER PRESSURE	HEXENE	0	UNK
EXXON PLASTICS	19951202	CONTAINER LEAK	PLASTICS REACTOR,HIGH TEMPERATURE SPIKE CAUSED THE RELEASE PLASTICS REACTOR / HIGH TEMP SPIKE CAUSED THE RELEASE	ETHYLENE	0	UNK
EXXON PLASTICS	19951207	CONTAINER LEAK	D-LINE REACTOR, OVERPRESSURE RESULTED IN RELEASE D-LINE REACTOR / OVERPRESSURE RESULTED IN RELEASE	ETHYLENE	0	UNK
EXXON PLASTICS	19951207	CONTAINER LEAK	D-LINE REACTOR, OVERPRESSURE RESULTED IN RELEASE D-LINE REACTOR / OVERPRESSURE RESULTED IN RELEASE	BUTYL ACETATE	0	UNK

EXXON PLASTICS	19951208	CONTAINER LEAK	HIGH TEMPERATURE KNOCK OUT POT,DURING STARTUP,HEAD LEAKED HIGH TEMPERATURE KNOCK-OUT POT / DURING START-UP, THE HEAD ON THE UNIT LEAKED / CAUSE IS UNKNOWN	ETHYLENE	0	UNK
EXXON PLASTICS	19951219	VALVE	REACTOR DUMP VALVE OPENED, VALVE FAILED REACTOR DUMP VALVE OPENED/VALVE FAILED	ETHYLENE	0	UNK
EXXON PLASTICS	19951225	EXPLOSION	ETHYLENE REACTOR, EXPLOSION, UNKNOWN CAUSE ETHYLENE REACTOR/EXPLOSION/UNKNOWN CAUSE	ETHYLENE	0	UNK
EXXON PLASTICS	19951229	VALVE	REACTOR SYSTEM, A SAFETY VALVE OPENED REACTOR SYSTEM/A SAFETY VALVE OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19951229	VALVE	REACTOR SYSTEM, A SAFETY VALVE OPENED REACTOR SYSTEM/A SAFETY VALVE OPENED	VINYL ACETATE	0	UNK
EXXON PLASTICS	19951231	FLANGE	E-LINE REACTOR,CIRCULATING GAS AND FLANGE STARTED LEAKING E-LINE REACTOR / CIRCULATING GAS AND FLANGE STARTED LEAKING	ETHYLENE	0	UNK
EXXON PLASTICS	19960101	IMPROPER VALVE HANDLING	REACTOR DUMPED,RADIO SIGNAL INTERFERED WITH ELECTRIC VALVE REACTOR DUMPED,RADIO SIGNAL INTERFERED WITH ELECTRIC VALVE	ETHYLENE	0	UNK
EXXON PLASTICS	19960101	IMPROPER VALVE HANDLING	REACTOR DUMPED,RADIO SIGNAL INTERFERED WITH ELECTRIC VALVE REACTOR DUMPED,RADIO SIGNAL INTERFERED WITH ELECTRIC VALVE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19960110	IMPROPER MAINTENANCE	A"REACTOR, MAINTENANCE CROSSED WIRES DURING REPAIRS AND *** "A" REACTOR, MAINTENANCE CROSSED WIRES DURING REPAIRS AND***	ETHYLENE	0	UNK
EXXON PLASTICS	19960110	IMPROPER MAINTENANCE	A"REACTOR, MAINTENANCE CROSSED WIRES DURING REPAIRS AND *** "A" REACTOR, MAINTENANCE CROSSED WIRES DURING REPAIRS AND***	VINYL ACCETATE	0	UNK



EXXON PLASTICS	19960126	UNKNOWN	POLYETHYLENE REACTOR / OVERPRESSURED POLYETHYLENE REACTOR / OVERPRESSURED	ETHYLENE	0	UNK
EXXON PLASTICS	19960203	CONTAINER LEAK	D LINE CHEMICAL REACTOR,LINE PLUGGED CAUSING SHUT DOWN** D LINE CHEMICAL REACTOR/LINE PLUGGED CAUSING SHUT DOWN DUE TO HIGH TEMPATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19960204	VALVE	COMPRESSOR 160B SAFELTY VALVE,RELEASED MAT DUE TO THE COLD COMPRESSOR 160B/SAFETY VALVE RELEASED MATERIAL DUE TO THE COLD WEATHER	ETHYLENE	0	UNK
EXXON PLASTICS	19960219	VALVE	F-LINE REACTOR RECYCLE SYSTEM,PACKING BLEW OUT ON MOTOR *** F-LINE REACTOR RECYCLE SYSTEM / PACKING BLEW OUT ON A MOTOR OPERATED VALVE	BUTENE OLIGOMER	0	UNK
EXXON PLASTICS	19960219	VALVE	F-LINE REACTOR RECYCLE SYSTEM,PACKING BLEW OUT ON MOTOR *** F-LINE REACTOR RECYCLE SYSTEM / PACKING BLEW OUT ON A MOTOR OPERATED VALVE	ETHYLENE	0	UNK
EXXON PLASTICS	19960221	VALVE	REACTOR, VALVE WAS OPENED REACTOR/VALVE WAS OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19960221	VALVE	REACTOR, VALVE WAS OPENED REACTOR/VALVE WAS OPENED	VINYL ACETATE	0	UNK
EXXON PLASTICS	19960307	VALVE	PE CHEMICAL REACTOR DUMP VALVE OPENED PE CHEMICAL REACTOR DUMP VALVED OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19960308	IMPROPER VALVE HANDLING	REACTOR DUMP VALVE WAS OPENED BY MISTAKE REACTOR DUMP VALVE WAS OPENED BY MISTAKE	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19960308	IMPROPER VALVE HANDLING	REACTOR DUMP VALVE WAS OPENED BY MISTAKE REACTOR DUMP VALVE WAS OPENED BY MISTAKE	VINYL ACETATE	0	UNK

EXXON PLASTICS	19960331	CONTAINER LEAK	CHEMICAL REACTOR TUBING,SEAL FAILED,RESULTING IN RELEASE CHEMICAL REACTOR TUBING / SEAL FAILED RESULTING IN RELEASE	ETHYLENE	0	UNK
EXXON PLASTICS	19960404	VALVE	PROPYLENE UNLOADING PUMP,, SAFETY VALVE FAILED PROPYLENE UNLOADING PUMP/SAFETY VALVE FAILED	PROPYLENE	0	UNK
EXXON PLASTICS	19960407	VALVE	REACTOR D, PRESSURE SAFETY VALVE FAILED REACTOR D / PRESSURE SAFETY VALVE FAILED	ETHYLENE	0	UNK
EXXON PLASTICS	19960407	VALVE	REACTOR D, PRESSURE SAFETY VALVE FAILED REACTOR D / PRESSURE SAFETY VALVE FAILED	BUTYLACRYLATE	0	UNK
EXXON PLASTICS	19960429	VALVE	SAFETY VALVE ON REACTOR SYSTEM,RELEASED THE MAT,CAUSE UNDER*** SAFETY VALVE ON REACTOR SYSTEM / THE VALVE RELEASED THE MATERIAL DUE TOCAUSES UNDER INVESTIGATION	VINYL ACETATE	0	UNK
EXXON PLASTICS	19960429	VALVE	SAFETY VALVE ON REACTOR SYSTEM,RELEASED THE MAT,CAUSE UNDER*** SAFETY VALVE ON REACTOR SYSTEM / THE VALVE RELEASED THE MATERIAL DUE TOCAUSES UNDER INVESTIGATION	ETHYLENE	0	UNK
EXXON PLASTICS	19960518	VALVE	REACTOR LEAKING DISCHARGE VALVE REACTOR/LEAKING DISCHARGE VALVE	ETHYLENE	0	UNK
EXXON PLASTICS	19960518	VALVE	REACTOR LEAKING DISCHARGE VALVE REACTOR/LEAKING DISCHARGE VALVE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19960603		CHEMICAL REACTOR / SAFETY INTERLOCK ACTIVATION	ETHYLENE	0	NON
EXXON PLASTICS	19960609		INTERLOCK ACTIVATION DURING TRANSITION / REACTOR	ETHYLENE	0	NON
EXXON PLASTICS	19960609		INTERLOCK ACTIVATION DURING TRANSITION / REACTOR	VINYL ACETATE	0	NON

EXXON PLASTICS	19960630	CONTAINER LEAK	GASKET IN A TRANSFER LINE / LEAKING GASKET IN A TRANSFER LINE / LEAKING	BUTYL ACRYLATE	60	GAL
EXXON PLASTICS	19960808	CONTAINER LEAK	E-LINE REACTOR,.25 INCH AIR LINE BROKE LOOSE FROM REACTOR E-LINE REACTOR / .25IN AIR LINE BROKE LOOSE FROM THE REACTOR VENT VALVE	ETHYLENE	0	UNK
EXXON PLASTICS	19960808	CONTAINER LEAK	E-LINE REACTOR,.25 INCH AIR LINE BROKE LOOSE FROM REACTOR E-LINE REACTOR / .25IN AIR LINE BROKE LOOSE FROM THE REACTOR VENT VALVE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19960814		"D"REACTOR, OXYGEN BURNOUT, DECOMPOSITION OF THE REACTOR "D" REACTOR / OXYGEN BURNOUT / DECOMPOSITION IN THE REACTOR	ETHYLENE	0	UNK
EXXON PLASTICS	19960822	OVERFLOW	COMPRESSOR DIESEL FUEL TANK OVERFLOWED DURING FILLING COMPRESSOR DIESEL FUEL TANK OVERFLOWED DURING FILLING	OIL: DIESEL	0	UNK
EXXON PLASTICS	19960824	FIRE	STORAGE BUILDING,THERE IS A FIRE, CAUSE UNKNOWN STORAGE BUILDING, THERE IS A FIRE, CAUSE UNKNOWN	ORGANIC PEROXIDE	0	UNK
EXXON PLASTICS	19960830	VALVE	HIGH PRESSURE SPIKE CAUSED A DUMP VALVE TO RELEASE ETHYLENE** HIGH PRESSURE SPIKE CAUSED A DUMP VALVE TO RELEASE ETHYLENE AND HEXENE GAS TO THE ATMOSPHERE	HEXENE	0	UNK
EXXON PLASTICS	19960830	VALVE	HIGH PRESSURE SPIKE CAUSED A DUMP VALVE TO RELEASE ETHYLENE** HIGH PRESSURE SPIKE CAUSED A DUMP VALVE TO RELEASE ETHYLENE AND HEXENE GAS TO THE ATMOSPHERE	ETHYLENE	0	UNK
EXXON PLASTICS	19960831	FITTING	F LINE REACTOR, F LINE REACTOR DUMPED OPEN DUE TO HIGH PRESSURE F LINE REACTOR/F LINE REACTOR DUMPED OPEN DUE TO A HIGH PRESSURE SPIKE	ETHYLENE	0	UNK

EXXON PLASTICS	19960831	FITTING	F LINE REACTOR, F LINE REACTOR DUMPED OPEN DUE TO HIGH PRESSURE F LINE REACTOR/F LINE REACTOR DUMPED OPEN DUE TO A HIGH PRESSURE SPIKE	HEXENE	0	UNK
EXXON PLASTICS	19960916	VALVE	D REACTOR/SAFETY VALVE OPENED DUE TO HIGH TEMPERATURE D REACTOR / SAFETY VALVE OPENED DUE TO HIGH TEMPERATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19960925		SAFETY VALVE ON REACTOR-D / OVERPRESSURE OF REACTOR DURING STARTUP	ETHYLENE	0	NON
EXXON PLASTICS	19961008	VALVE	D LINE REACTOR SAFETY VALVE ACTIVATED, CAUSES UNKNOWN D LINE REACTOR SAFETY VALVE ACTIVATED DUE TO UNKNOWN CAUSES	ETHYLENE	0	UNK
EXXON PLASTICS	19961008	VALVE	D LINE REACTOR SAFETY VALVE ACTIVATED, CAUSES UNKNOWN D LINE REACTOR SAFETY VALVE ACTIVATED DUE TO UNKNOWN CAUSES	N BUTYL ACRYLATE	0	UNK
EXXON PLASTICS	19961022	VALVE	DUMP VALVE ON C REACTOR,HIGH TEMP ALARM IN THE PROCESS** DUMP VALVE ON C REACTOR,HIGH TEMP ALARM IN THE PROCESS*	ETHYLENE	0	UNK
EXXON PLASTICS	19961026		C LINE REACTOR, HIGH TEMP INTERLOCK ACTIVATED,CAUSING RELEASE C LINE REACTOR,HIGH TEMN INTERLOCK ACTIVATED,CAUSING RELEASE	ETHYLENE	0	UNK
EXXON PLASTICS	19961031		D REACTOR / DUMP VALVES OPENED DUE TO HIGH PRESSURE	ETHYLENE	0	NON
EXXON PLASTICS	19961031		D REACTOR / DUMP VALVES OPENED DUE TO HIGH PRESSURE D REACTOR/ DUMP VALVES OPENED DUE TO HIGH PRESSURE	ETHYLENE	0	UNK

EXXON PLASTICS	19961105	IMPROPER OPERATION	ABOVE GROUND STORAGE TANK CAP UNKNOWN,CHEMS MISALIGNED ABOVE GROUND STORAGE TANK CAP UNKNOWN, CHEMS MISALIGNED	PROPYLENE	0	UNK
EXXON PLASTICS	19961107	VALVE	B-LINE REACTOR,INTERLOCK ACTIVATION CAUSED BY HIGH TEMP SPARK* B-LINE REACTOR / AN INTERLOCK ACTIVATION CAUSED BY A HIGH TEMP. SPARK CAUSED THE DUMP VALVE TO ACTIVATE AND RELEASE T	ETHYLENE	0	UNK
EXXON PLASTICS	19961107	VALVE	B-LINE REACTOR,INTERLOCK ACTIVATION CAUSED BY HIGH TEMP SPARK* B-LINE REACTOR / AN INTERLOCK ACTIVATION CAUSED BY A HIGH TEMP. SPARK CAUSED THE DUMP VALVE TO ACTIVATE AND RELEASE T	VINYL ACETATE	0	UNK
EXXON PLASTICS	19961123	UNKNOWN	REACTOR DUMP, UNKNOWN UNIT FAILURE REACTOR DUMP / UNKNOWN UNIT FAILURE	ETHYLENE	0	UNK
EXXON PLASTICS	19961220	VALVE	REACTOR VESSEKM SAFETY VALVE OPENED DUE TO COLD WEATHER REACTOR VESSEL / SAFETY VALVE OPENED DUE TO COLD WEATHER	ETHYLENE	0	UNK
EXXON PLASTICS	19961220	VALVE	REACTOR VESSEKM SAFETY VALVE OPENED DUE TO COLD WEATHER REACTOR VESSEL / SAFETY VALVE OPENED DUE TO COLD WEATHER	HEXENE	0	UNK
EXXON PLASTICS	19961221	FITTING	BAKER LINE RECYCLE,PRIMARY COMPRESSOR OVERSHOT ITS PRESSURE BAKER LINE RECYCLE / PRIMARY COMPRESSOR OVERSHOT ITS PRESSURE AND A SAFETY DEVICE ACTIVATED	ETHYLENE	0	UNK
EXXON PLASTICS	19961221	FITTING	BAKER LINE RECYCLE,PRIMARY COMPRESSOR OVERSHOT ITS PRESSURE BAKER LINE RECYCLE / PRIMARY COMPRESSOR OVERSHOT ITS PRESSURE AND A SAFETY DEVICE ACTIVATED	VINYL ACETATE	0	UNK
EXXON PLASTICS	19961221		COMPRESSOR SEAL 130 A, SEAL WORE OUT COMPRESSOR SEAL 130 A / SEAL WORE OUT	ETHYLENE	0	UNK

EXXON PLASTICS	19961221		COMPRESSOR SEAL 130 A, SEAL WORE OUT COMPRESSOR SEAL 130 A / SEAL WORE OUT	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970117		B-LINE REACTOR, HIGH PRESSURE INTERLOCK ACTIVATION B-LINE REACTOR / HIGH PRESSURE INTERLOCK ACTIVATION	ETHYLENE	0	UNK
EXXON PLASTICS	19970117		B-LINE REACTOR, HIGH PRESSURE INTERLOCK ACTIVATION B-LINE REACTOR / HIGH PRESSURE INTERLOCK ACTIVATION	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970117	VALVE	DUMP VALVE ON REACTOR, VALVE OPENED (PROBABLY DUE TO HIGH TEMP*) DUMP VALVE ON A REACTOR / THE VALVE OPENED (PROBABLY DUE TO A HIGH TEMPREADING) CAUSING THE RELEASE OF THE MATERIAL	ETHYLENE	0	UNK
EXXON PLASTICS	19970123	FITTING	COMPRESSOR, A SEAL FAILED COMPRESSOR / A SEAL FAILED	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19970123	FITTING	COMPRESSOR, A SEAL FAILED COMPRESSOR / A SEAL FAILED	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970126	IMPROPER OPERATION	PROCESS REACTOR, OVERPRESSURE IN REACTOR DUE TO SYSTEM OVERRUN PROCESS REACTOR / OVERPRESSURE IN REACTOR DUE TO SYSTEM OVERRUN	ETHYLENE	0	UNK
EXXON PLASTICS	19970126	IMPROPER OPERATION	PROCESS REACTOR, OVERPRESSURE IN REACTOR DUE TO SYSTEM OVERRUN PROCESS REACTOR / OVERPRESSURE IN REACTOR DUE TO SYSTEM OVERRUN	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970130	VALVE	REACTOR, A DUMP VALVE OPENED REACTOR / A DUMP VALVE OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19970210	FITTING	REACTOR, INTERLOCK ACTIVATED DUE TO EQUIPMENT FAILURE CAUSING REACTOR / AN INTERLOCK ACTIVATED DUE TO EQUIPMENT FAILURE CAUSING THE RELEASE OF THE MATERIAL	ETHYLENE	325	LBS

EXXON PLASTICS	19970309	VALVE	DOGLINE REACTOR DUMP VALVE OPENED,FALSE INTERLOCK ACTIVATED* DOGLINE REACTOR DUMP VALVE OPENED / A FALSE INTERLOCK ACTIVATION CAUSED IT TO OPEN	ETHYLENE	0	UNK
EXXON PLASTICS	19970309	VALVE	DOGLINE REACTOR DUMP VALVE OPENED,FALSE INTERLOCK ACTIVATED* DOGLINE REACTOR DUMP VALVE OPENED / A FALSE INTERLOCK ACTIVATION CAUSED IT TO OPEN	N-BUTYL ACRYLATE	0	UNK
EXXON PLASTICS	19970316		D LINE REACTOR DUMPED D LINE REACTOR DUMPED	ETHYLENE	0	UNK
EXXON PLASTICS	19970316		D LINE REACTOR DUMPED D LINE REACTOR DUMPED	METHYL ACRYLATE	0	UNK
EXXON PLASTICS	19970316	UNKNOWN	REACTOR DUMP,SAFETY INTERLOCK OPENED DUE TO UNKNOWN REASON REACTOR DUMP / SAFETY INTERLOCK OPENED DUE TO UNKNOWN REASON	ETHYLENE	0	UNK
EXXON PLASTICS	19970319	VALVE	REACTOR, A SAFETY VALVE OPENED REACTOR, A SAFETY VALVE OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19970406	FITTING	REACTOR UNIT,HIGH TEMP AT STARTUP CAUSED A UNIT SHUTDOWN REACTOR UNIT/HIGH TEMPERATURE AT START UP CAUSED A UNIT SHUTDOWN AND PRODUCT DUMP	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19970406	FITTING	REACTOR UNIT,HIGH TEMP AT STARTUP CAUSED A UNIT SHUTDOWN REACTOR UNIT/HIGH TEMPERATURE AT START UP CAUSED A UNIT SHUTDOWN AND PRODUCT DUMP	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970409	FITTING	REACTOR, BROKEN WIRE REACTOR / BROKEN WIRE	ETHYLENE	0	UNK
EXXON PLASTICS	19970409	FITTING	REACTOR, BROKEN WIRE REACTOR / BROKEN WIRE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970416		REACTOR, DUMP WAS OPEN ON HIGH TEMPERATURE REACTOR, DUMP WAS OPEN ON HIGH TEMPERATURE	ETHYLENE	0	UNK

EXXON PLASTICS	19970427		SOURCE: E-LINE REACTOR/CAUSE: RUPTURED DISC	ETHYLENE GAS	0	NON
EXXON PLASTICS	19970427		SOURCE: E-LINE REACTOR/CAUSE: RUPTURED DISC	VINYL ACETATE	0	NON
EXXON PLASTICS	19970503	CONTAINER LEAK	REACTOR TUBE,FAILED AND LEAKED ETHYLENE AND VINYL ACETATE GAS REACTOR TUBE/TUBE FAILED AND LEAKED ETHYLENE AND VINYL ACETATE GAS TO THE ATMOSPHERE.	ETHYLENE	0	LBS
EXXON PLASTICS	19970503	CONTAINER LEAK	REACTOR TUBE,FAILED AND LEAKED ETHYLENE AND VINYL ACETATE GAS REACTOR TUBE/TUBE FAILED AND LEAKED ETHYLENE AND VINYL ACETATE GAS TO THE ATMOSPHERE.	VINYL ACETATE	0	LBS
EXXON PLASTICS	19970510	VALVE	REACTOR, HIGH TEMPERATURE IN THE UNIT,DUMP VALVE OPENED REACTOR / HIGH TEMPERATURE IN THE UNIT / DUMP VALVE OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19970510	VALVE	REACTOR, HIGH TEMPERATURE IN THE UNIT,DUMP VALVE OPENED REACTOR / HIGH TEMPERATURE IN THE UNIT / DUMP VALVE OPENED	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970523		REACTOR,DUMPED ON A FALSE HIGH TEMP DUE TO BURNED OUT THERMALCOUP REACTOR / REACTOR DUMPED ON A FALSE HIGH TEMPATURE DUE TO THERMAL COUPLER BURNED OUT	ETHYLENE	0	UNK
EXXON PLASTICS	19970523		REACTOR,DUMPED ON A FALSE HIGH TEMP DUE TO BURNED OUT THERMALCOUP REACTOR / REACTOR DUMPED ON A FALSE HIGH TEMPATURE DUE TO THERMAL COUPLER BURNED OUT	VINYL ACITATE	0	UNK
EXXON PLASTICS	19970523		REACTOR DUMPED ON HIGH AGITATOR AMPS REACTOR DUMPED ON HIGH AGITATOR AMPS	ETHYLENE GAS	0	UNK



EXXON PLASTICS	19970604	UNKNOWN	REACTOR & RECYCLE DUMP CAUSING RELEASE OF ETHYLENE GAS REACTOR AND RECYCLE DUMP CAUSING THE RELEASE OF ETHYLENE GAS & BUTENE GAS	BUTYLENE	0	UNK
EXXON PLASTICS	19970604	UNKNOWN	REACTOR & RECYCLE DUMP CAUSING RELEASE OF ETHYLENE GAS REACTOR AND RECYCLE DUMP CAUSING THE RELEASE OF ETHYLENE GAS & BUTENE GAS	ETHYLENE	0	UNK
EXXON PLASTICS	19970611	POWER FAILURE	REACTOR DUMPS OPEN, TOTAL POWER OUTAGE SOURCE: REACTOR DUMPS OPEN/CAUSE: TOTAL POWER OUTAGE	BUTYL ACRYLATE	0	UNK
EXXON PLASTICS	19970611	POWER FAILURE	REACTOR DUMPS OPEN, TOTAL POWER OUTAGE SOURCE: REACTOR DUMPS OPEN/CAUSE: TOTAL POWER OUTAGE	ETHYLENE	0	UNK
EXXON PLASTICS	19970611	POWER FAILURE	REACTOR DUMPS OPEN, TOTAL POWER OUTAGE SOURCE: REACTOR DUMPS OPEN/CAUSE: TOTAL POWER OUTAGE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970628	VALVE	REACTOR (RELIEF VALVE) INTERLOCK ACTIVATION REACTOR (RELIEF VALVE) INTERLOCK ACTIVATION	ACRYLIC ACID	0	UNK
EXXON PLASTICS	19970628	VALVE	REACTOR (RELIEF VALVE) INTERLOCK ACTIVATION REACTOR (RELIEF VALVE) INTERLOCK ACTIVATION	ETHYLENE	0	UNK
EXXON PLASTICS	19970628	VALVE	REACTOR (RELIEF VALVE) INTERLOCK ACTIVATION REACTOR (RELIEF VALVE) INTERLOCK ACTIVATION	METHYL ACRYLETE	0	UNK
EXXON PLASTICS	19970629	VALVE	REACTOR UNIT D, PRESSURE SAFETY VALVE LIFTED,OVERPRESSURE REACTOR UNIT:D / PRESSURE SAFETY VALVE LIFTED DUE TO OVERPRESSURE IN REACTOR	ACRYLIC ACID	0	UNK
EXXON PLASTICS	19970629	VALVE	REACTOR UNIT D, PRESSURE SAFETY VALVE LIFTED,OVERPRESSURE REACTOR UNIT:D / PRESSURE SAFETY VALVE LIFTED DUE TO OVERPRESSURE IN REACTOR	ETHYLENE	0	UNK

EXXON PLASTICS	19970629	VALVE	REACTOR UNIT D, PRESSURE SAFETY VALVE LIFTED,OVERPRESSURE REACTOR UNIT:D / PRESSURE SAFETY VALVE LIFTED DUE TO OVERPRESSURE IN REACTOR	METHYL ACRYLATE	0	UNK
EXXON PLASTICS	19970705	VALVE	REACTOR, A DUMP VALVE OPENED UP REACTOR / A DUMP VALVE OPENED UP	ETHYLENE GAS	0	UNK
EXXON PLASTICS	19970717	VALVE	INTERLOCK OPENED A REACTOR DUMP VALVE,DUE TO HIGH TEMP. INTERLOCK OPENED A REACTOR DUMP VALVE DUE TO HIGH TEMPERATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19970723	UNKNOWN	REACTOR DUMP, HIGH TEMP INTERLOCK OPENED REACTOR DUMP/HIGH TEMP INTERLOCK OPENED	CUPRIETHYLENEDIAMINE SOLUTION	0	UNK
EXXON PLASTICS	19970806	PUMP	SLOP OIL PUMP,TUBING ON THE PUMP BROKE AND MATERIAL RELEASED SLOP OIL PUMP / TUBING ON THE PUMP BROKE AND MATERIAL RELEASED	SLOP OIL	0	UNK
EXXON PLASTICS	19970815	FITTING	B-LINE REACTOR,HIGH HIGH FIRST POINT PEAK TEMP INTERLOCK BLINE REACTOR / HIGH HIGH FIRST POINT PEAK TEMPERATURE INTERLOCK ACTIVATION	ETHYLENE	0	UNK
EXXON PLASTICS	19970815	FITTING	B-LINE REACTOR,HIGH HIGH FIRST POINT PEAK TEMP INTERLOCK BLINE REACTOR / HIGH HIGH FIRST POINT PEAK TEMPERATURE INTERLOCK ACTIVATION	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970816		DUMP OPENING ON CHEMICAL REACTOR VESSEL,DUMP WAS OPENED BY DUMP OPENING ON CHEMICAL REACTOR VESSEL / DUMP WAS OPENED BY SYSTEM DUE TO PUMP FAILURE	ETHYLENE	0	UNK
EXXON PLASTICS	19970816		DUMP OPENING ON CHEMICAL REACTOR VESSEL,DUMP WAS OPENED BY DUMP OPENING ON CHEMICAL REACTOR VESSEL / DUMP WAS OPENED BY SYSTEM DUE TO PUMP FAILURE	N-BUTYL ACRYLATE	0	UNK

EXXON PLASTICS	19970818	VALVE	REACTOR,SAFETY VALVE OPENED DUE TO HIGH TEMPERATURE REACTOR / SAFETY VALVE OPENED DUE TO HIGH TEMPERATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19970818	VALVE	REACTOR,SAFETY VALVE OPENED DUE TO HIGH TEMPERATURE REACTOR / SAFETY VALVE OPENED DUE TO HIGH TEMPERATURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970828	CONTAINER LEAK	RAIL CAR/LEAKING GASKET RAILCAR / CAR NUMBER UNKNOWN / THERE IS A LEAKING GASKET	PROPYLENE	0	UNK
EXXON PLASTICS	19970828	VALVE	E LINE REACTOR DUMP VALVE OPENED,CAUSED BY HIGH THIRD POINT E LINE REACTOR DUMP VALVE OPENED / CAUSED BY HIGH THIRD POINT TEMP INTERLOCK ACTIVATION	ETHYLENE	0	UNK
EXXON PLASTICS	19970903	UNKNOWN	B REACTOR/DUMPED HIGH TEMPERATURE B REACTOR / DUMPED DUE TO HIGH TEMPERATURE	ETHYLENE	0	UNK
EXXON PLASTICS	19970903	UNKNOWN	B REACTOR/DUMPED HIGH TEMPERATURE B REACTOR / DUMPED DUE TO HIGH TEMPERATURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970905	FLANGE	FLANGE OPENED UP ON SECONDARY COMPRESSOR DUE TO POSSIBLE FATIGUE FLANGE OPENED UP ON SECONDARY COMPRESSOR DUE TO POSSIBLE FATIGUE	ETHYLENE	0	UNK
EXXON PLASTICS	19970905	FLANGE	FLANGE OPENED UP ON SECONDARY COMPRESSOR DUE TO POSSIBLE FATIGUE FLANGE OPENED UP ON SECONDARY COMPRESSOR DUE TO POSSIBLE FATIGUE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970906	VALVE	POLYTHYLENE REACTOR/COMPRESSOR PROBLEMS CAUSED THE RELEASE POLYETHYLENE REACTOR / COMPRESSOR PROBLEMS CAUSED THE RELEASE	ETHYLENE	0	UNK

EXXON PLASTICS	19970906		DOG LINE REACTOR/DUMPED DURING STARTUP PROCESS AFTER A *** DOG LINE REACTOR / DUMPED DURING STARTUP PROCESS OCCURRED AFTER A MAINTENANCE PERIOD	ETHYLENE	0	UNK
EXXON PLASTICS	19970908	UNKNOWN	REACTOR DUMPED/CAUSE UNDER INVESTIGATION REACTOR DUMPED/CAUSE UNDER INVESTIGATION	ETHYLENE	0	UNK
EXXON PLASTICS	19970913	FLANGE	ETHYLENE CHEMICAL REACTOR LEAKED AT FLANGE ETHYLENE CHEMICAL REACTOR LEAKED AT A FLANGE	ETHYLENE	0	UNK
EXXON PLASTICS	19970913	FLANGE	ETHYLENE CHEMICAL REACTOR LEAKED AT FLANGE ETHYLENE CHEMICAL REACTOR LEAKED AT A FLANGE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19970914	UNKNOWN	POLYETHYLENE REACTOR/HIGH PRESSURE INTERLOCK ACTIVATION DUE** POLYETHYLENE REACTOR / HIGH PRESSURE INTERLOCK ACTIVATION DUE TO UNKNOWN CAUSE	ETHYLENE	0	UNK
EXXON PLASTICS	19970920	VALVE	REACTOR/COMPRESSOR INTERLOCK ACTIVATION(SAFETY DEVICE FOR COMPRESSOR D REACTOR / COMPRESSOR INTERLOCK ACTIVATION (SAFETY DEVICE FOR COMPRESSOR)	ETHYLENE	0	UNK
EXXON PLASTICS	19971003		COMPRESSOR SHUT DOWN/SAFETY LIFT OPENED ON TOWER RELEASING EHTYLENE TO FLARE	ETHYLENE	0	NON
EXXON PLASTICS	19971005		SOURCE: REACTOR DUMP VALVE/CAUSE: THE SAFETY VALVE OPENED CAUSING THE RELEASE.	ETHYLENE	0	NON
EXXON PLASTICS	19971005		SOURCE: REACTOR DUMP VALVE/CAUSE: THE SAFETY VALVE OPENED CAUSING THE RELEASE.	VINYL ACETATE	0	NON
EXXON PLASTICS	19971005		SOURCE: REACTOR SAFETY DUMP VALVE/CAUSE: SAFETY DUMP VALVE OPENED CAUSING THE RELEASE.	ETHYLENE	0	NON

EXXON PLASTICS	19971005		SOURCE: REACTOR SAFETY DUMP VALVE/CAUSE: SAFETY DUMP VALVE OPENED CAUSING THE RELEASE.	VINYL ACETATE	0	NON
EXXON PLASTICS	19971008		F LINE REACTOR AND HIGH PRESSURE SEPARATER RUPTURE DISC FAILURE	BUTADIENE	0	NON
EXXON PLASTICS	19971008		F LINE REACTOR AND HIGH PRESSURE SEPARATER RUPTURE DISC FAILURE	ETHYLENE (GAS)	0	NON
EXXON PLASTICS	19971018	FITTING	C-REACTOR, DUMP ON REACTOR OPENED C-REACTOR / DUMP ON REACTOR OPENED	ETHYLENE	0	UNK
EXXON PLASTICS	19971019	VALVE	REACTOR A,SAFETY VALVE, OPENED DUE TO HIGH PRESSURE REACTOR A, SAFETY VALVE, OPENED DUE TO HIGH PRESSURE	ETHYLENE	0	UNK
EXXON PLASTICS	19971019	VALVE	REACTOR A,SAFETY VALVE, OPENED DUE TO HIGH PRESSURE REACTOR A, SAFETY VALVE, OPENED DUE TO HIGH PRESSURE	VINYL ACETATE	0	UNK
EXXON PLASTICS	19971028	VALVE	REACTOR LINE,PRESSURE ANTI-LOCK ACTIVATION CAUSED PRESSURE REACTOR LINE / PRESSURE ANTI-LOCK ACTIVATION CAUSED PRESSURE RELIEF VALVE TO OPEN	ETHYLENE	0	UNK
EXXON PLASTICS	19971028	VALVE	REACTOR LINE,PRESSURE ANTI-LOCK ACTIVATION CAUSED PRESSURE REACTOR LINE / PRESSURE ANTI-LOCK ACTIVATION CAUSED PRESSURE RELIEF VALVE TO OPEN	VINYL ACETATE	0	UNK
EXXON PLASTICS	19971117	VALVE	REACTOR VALVE PACKING FAILED,CAUSING RELEASE OF MATERIAL REACTOR / VALVE PACKING FAILED CAUSING THE RELEASE OF MATERIAL	ETHYLENE	0	UNK
EXXON PLASTICS	19971117	VALVE	REACTOR VALVE PACKING FAILED,CAUSING RELEASE OF MATERIAL REACTOR / VALVE PACKING FAILED CAUSING THE RELEASE OF MATERIAL	HEXENE	0	UNK

## EXXON REFINERY

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON REFINERY	19890915		THE CALLER BELIEVES THE EXXON REFINERY IS GIVING OFF AN ODOR	POLYMER ODOR	0	NON
EXXON REFINERY	19900514		COMPRESSON UNIT/BROKEN VALVE	HYDROGEN SULFIDE	0	NON
EXXON REFINERY	19900524		BARGE (OWNED BY HOUSTON BARGE LINES) / A PLUG BLEW OUT ON A PUMP THAT WAS SHUT OFF.	AC20 ASPHALT	0	UNK
EXXON REFINERY	19900708		SAFTY VALVE FAILED ON LIGHT ENDS UNIT	BENZENE	0	NON
EXXON REFINERY	19900725		T/S SS SPIRIT / BLEEDER OPENED CAUSING OVERFILL OF DRIP PAN	OIL: CRUDE	2	BBL
EXXON REFINERY	19900805		BARGE CHOTIAN 2982 / MATERIAL IS LEAKING FROM SMALL LEAK IN THE HULL	JET FUEL: JP-4	1	GAL
EXXON REFINERY	19900816		DOCK LOADING ARM / GASKET FAILURE.	OIL, FUEL: NO. 2	1	BBL
EXXON REFINERY	19900818		LOADING BARGE NMS 1441/ ACCIDENTALLY DISCHARGED AFTER PIGGING A LINE	SOLVENT OIL	30	GAL
EXXON REFINERY	19900828		BARGE VALVE LEFT OPEN AND OVERFILLED	GASOLINE: AUTOMOTIVE (4.23G PB/G	5	GAL
EXXON REFINERY	19900918		12" LOADING LINE/ MATERIAL INSIDE THE LINE SPILLED WHEN THE LINE WAS CUT	OIL, FUEL: NO. 2	8	GAL
EXXON REFINERY	19900929		NO. 1 DOCK LINE / FLANGE LEAKED DURING HYDROSTATIC TEST	OIL: CRUDE	0	OTH
EXXON REFINERY	19901003		8" LOADING LINE/LEAK DURING PRESSURE TEST	DIISONONYL PHTHALATE	20	GAL
EXXON REFINERY	19901008		8 INCH DOCK PIPELINE / WHILE DRAINING THE LINE, SUMP COLLECTION PAN OVERFLOWED.	NAPHTHA: COAL TAR	1	GAL

EXXON REFINERY	19901009	FLARE STACK/PILOT WENT OUT	HYDROGEN SULFIDE	0	NON
EXXON REFINERY	19901009	FLARE STACK/PILOT WENT OUT	HYDROCARBONS	0	NON
EXXON REFINERY	19901019	CHECK VALVE ON BARGE 1409 DEVELOPED A LEAK WHILE ONLOADING BARGE	JET FUEL: JP-5 (KEROSENE, HEAVY)	0	UNK
EXXON REFINERY	19901024	OVERFILL OF A DRAIN PAN DUE TO A PLUG CLOGGED	OIL: CRUDE	1	GAL
EXXON REFINERY	19901115	REMOVING A TRANSFER LINE AT THE DOCK AND OVERFLOWED A DRUM WHICH WAS HOLDING THE RESIDUE FROM THE LINE	PETROLEUM GAS OIL	20	GAL
EXXON REFINERY	19901119	EITHER BARGE LTC-59 OR LCD-4902 / LEAK BELOW WATER LINE	GASOLINE: AUTOMOTIVE (4.23G PB/G	1	GAL
EXXON REFINERY	19901120	BARGE TANK NO.7 ULAGE GAUGE/ LOADING LINE LEAK	OIL: DIESEL	1	BBL
EXXON REFINERY	19901217	6" WASH LINE / MECHANICAL CREW MISTAKINGLY CUT LINE	PROCESS GAS OIL	3	LBS
EXXON REFINERY	19901221	6 INCH MOTOR GAS LINE / PIN HOLE LEAK - CORROSION	NAPHTHA: SOLVENT	1	GAL
EXXON REFINERY	19910203	BARGE / DURING LOADING, DISCOVERED A PINHOLE LEAK IN THE BARGE.	JET FUEL: JP-1 (KEROSENE)	3	GAL
EXXON REFINERY	19910205	COMING FROM OUTFALL UNKNOWN CAUSE	WASTE OIL/LUBRICANTS - POSS. CO	15	GAL
EXXON REFINERY	19910224	TANK BARGE "KENTUCKY 233"/ PIN HOLE LEAK UNKNOWN TANK	GASOLINE: AUTOMOTIVE (UNLEAD)	10	GAL
EXXON REFINERY	19910226	BARGE MMI351/VALVE OPEN ON DISCHARGE MANIFOLD	OIL, MISC: LUBRICATING	2	GAL
EXXON REFINERY	19910228	UNLOADING SYSTEM ON THEIR DOCK / LEAKING FROM VALVES	GASOLINE: AUTOMOTIVE	2	GAL
EXXON REFINERY	19910228	UNLOADING SYSTEM ON THEIR DOCK / LEAKING FROM VALVES	OIL: DIESEL	2	GAL

EXXON REFINERY	19910301	M/V ITB JACKSONVILLE / WHILE OFFLOADING ACCIDENTALLY RELEASED MATERIAL WHEN OVERFILLED A TANK	PROCESSED GAS OIL	4	BBL
EXXON REFINERY	19910320	COLLISION BETWEEN M/V STAVANGER PRINCE AND TOW BOAT JOE PAT EXSTEIN MM 209 PLAQUEMINE POINT. SIX FOOT GASH IN STARBOARD STERN OF S.PRINCE.	OIL: CRUDE	3100	BBL
EXXON REFINERY	19910408	LEAKING CHECK VALVE ON BARGE EB 332 / TRANSFER LOADING OPERATIONS	JET FUEL: JP-1 (KEROSENE)	1	GAL
EXXON REFINERY	19910426	BARGE APEX 1818 / OVERFILLED	OIL, FUEL: NO. 2	1	BBL
EXXON REFINERY	19910427	SAFETY VALVE/UNKNOWN	BENZENE	0	NON
EXXON REFINERY	19910610	CROSS OVER HOSE ON AN OFFLOADING SYSTEM / FAILURE OF FLANGE	OTHER OIL, GAS-OIL	1	BBL
EXXON REFINERY	19910622	OUT OF SERVICE MOTOR GASOLINE LINE/WATER WASHED LINE RESULTING IN A SMALL LEAK	GASOLINE: AUTOMOTIVE (4.23G PB/G)	1	OTH
EXXON REFINERY	19910627	FLANGE BLEW ON 8" LINE MANIFOLD RELEASING MATERIAL ON DOCK SURFACE AND RAIN WATER WASHED THE MATERIAL TO THE RIVER	HEAVY OIL	1	BBL
EXXON REFINERY	19910702	NITROGEN UTILITY HOSE/ MATERIAL WAS RELEASED WHILE DRAINING THE HOSE	UNKNOWN OIL	0	GAL
EXXON REFINERY	19910807	FLOWLINE ON THE DOCK / FAULTY FITTING LEAKED.	FLUX OIL	1	GAL
EXXON REFINERY	19910807	FLOWLINE ON THE DOCK / FAULTY FITTING LEAKED.	AROMATIC CONCENTRATE	0	OTH
EXXON REFINERY	19910810	MOTOR GASOLINE TRANFER LINE/PINE HOLE LEAK	GASOLINE: AUTOMOTIVE (4.23G PB/G)	0	UNK
EXXON REFINERY	19910812	PUMP / SEAL FAILED	PROPANE	0	UNK
EXXON REFINERY	19910812	PUMP / FAILED GASKET	GASOLINE: AUTOMOTIVE (4.23G PB/G)	0	NON



EXXON REFINERY	19910826		FLARE STACK/ FLAME WENT OUT	HYDROCARBONES (H2S AND SO2)	0	NON
EXXON REFINERY	19910827		LINE INSIDE OF THE REFINERY LEAKED	HYDROCARBONES (10% BENZENE)	0	NON
EXXON REFINERY	19910827		TANK/ DEVELOPED HOLE IN THE SIDE	SODIUM HYDROXIDE	0	NON
EXXON REFINERY	19910907		SHEEN SIGHTING SOURCE/CAUSE UNKNOWN	OIL: DIESEL	0	UNK
EXXON REFINERY	19910927		TRANSFER LINE / WELD CAP BLEW OFF DURING PRESSURE TEST	N-DECYL ALCOHOL	5	GAL
EXXON REFINERY	19911022		CLEAN MASTER SEPERATOR IN REFINERY / SUMP OVERFLOWED DUE TO RAIN	WASTE OIL/LUBRICANTS - POSS. CO	20	GAL
EXXON REFINERY	19911121		TRANSFER LINE WAS CUT BY CONTRACTOR	UNKNOWN OIL	5	GAL
EXXON REFINERY	19911227		PRESSURE TESTING LINE WHEN GASKET RUPTURED	OIL: DIESEL	5	GAL
EXXON REFINERY	19920102	VALVE	TOWER FRACTIONATOR ON UNIT IN THE FACILITY/FAULTY VALVE TOWER FRACTIONATOR ON UNIT IN THE FACILITY/FAULTY VALVE.	BENZENE		UNK
EXXON REFINERY	19920129		SKIMMER LEAKED LUBE OIL OUT OF A SEAL DURING THE TESTING OF THE ENGINE/EQUIPMENT FAILURE	OIL, MISC: MOTOR	0	GAL
EXXON REFINERY	19920224		4" LUBE LINE / PINHOLE LEAK IN LINE	OIL, MISC: LUBRICATING	2	GAL
EXXON REFINERY	19920225		TUG BOAT PUMPED BILGE INTO WATER	WASTE OIL/LUBRICANTS - POSS. CO	10	GAL
EXXON REFINERY	19920306	CONTAINER LEAK	COOLING TOWER/EXCHANGER LEAK COOLING TOWER/EXCHANGER LEAK.	HYDROGEN SULFIDE		LBS
EXXON REFINERY	19920307		TANK BARGE NMS1449/LEAKING OFFLOADING LINE TANK BARGE NMS1449/LEAKING OFFLOADING LINE	SLACK WAX (CONTAINS SOME OIL)		BBL

EXXON REFINERY	19920321		LOADING LINE / LEAKING VALVE	OIL: DIESEL	10	GAL
EXXON REFINERY	19920414		SAFETY VALVE BLEW ON NO.3 FUEL LINE / EQUIPMENT FAILURE	GAS OIL	0	UNK
EXXON REFINERY	19920418		SAFETY VALVE ON EAST COKER UNIT/FURNACE SHUT DOWN CAUSED DRUM TO FOAM	BENZENE	0	LBS
EXXON REFINERY	19920508		STORAGE TANK / HOLE IN TANK	GASOLINE: AUTOMOTIVE (4.23G PB/G)	0	NON
EXXON REFINERY	19920520		PIPE STILL UNIT/COMPRESSOR SHUT DOWN DUE TO LOSS OF SUCTION	BENZENE	0	NON
EXXON REFINERY	19920531		COMPRESSOR UNIT/SHUT DOWN UNIT DUE TO ELECTRICAL PROBLEM	HYDROGEN SULFIDE	0	NON
EXXON REFINERY	19920607		SEPARATOR/HEAVY RAIN	OIL: CRUDE	0	UNK
EXXON REFINERY	19920607		8" GASOLINE LINE / DEVELOPED PINHOLE LEAK	GASOLINE: UNLEADED	1	BBL
EXXON REFINERY	19920611		SEPERATOR WAS OVERFILLED BY RAINWATER	WASTE OIL/LUBRICANTS	1	BBL
EXXON REFINERY	19920621		3 INCH PIPE HAS PINHOLE LEAK/CORROSION	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19920628	COLLISION	DISTILLATION UNIT/ VENTED DISTILLATION UNIT / VENTED	BENZENE		LBS
EXXON REFINERY	19920630		WASTE OIL SHEEN 1 FT BY 60 FT, SHEEN IS CONTAINED WITH BOOMS	WASTE OIL	1	BBL
EXXON REFINERY	19920701	RAIN OR SNOW	ROLL OFF CONTAINER/RAIN WATER CAUSED IT TO OVERFLOW ROLL OFF CONTAINER/RAIN WATER CAUSED IT TO OVERFLOW	DAF(K048)		LBS
EXXON REFINERY	19920703		TUGBOAT DISCHARGED MATERIAL FROM BILGE	OIL, MISC: MOTOR	1	GAL
EXXON REFINERY	19920704		6" FLOW LINE/LEAKED DUE TO HOLE	JET FUEL: JP-5 (KEROSENE, HEAVY)	1	BBL

EXXON REFINERY	19920726		BARGE/PIN HOLE LEAK IN BARGE	GASOLINE: AUTOMOTIVE (4.23G PB/G)	3	GAL
EXXON REFINERY	19920729		ROLL OFF BOX/BOX WAS ACCIDENTLY DROPPED	HAZARDOUS SLUDGE NO.KO48		UNK
EXXON REFINERY	19920801		UNKNOWN BARGE/LEAKING	GASOLINE: AUTOMOTIVE (4.23G PB/G)	2	GAL
EXXON REFINERY	19920806		WATER MASTER SEPARATOR/RELEASE DUE TO UNKNOWN CAUSE WATER MASTER SEPARATOR/RELEASE DUE TO UNKNOWN CAUSE	UNKNOWN OIL		UNK
EXXON REFINERY	19920818		8" PIPELINE / CRACKED	WAX: PARAFFIN	5	GAL
EXXON REFINERY	19920821	IMPROPER OPERATION	BOX HOLDING SLUDGE SPILLED DURING ONLOADING MATERIAL ON TRUCK BOX HOLDING SLUDGE SPILLED DURING ONLOADING MATERIAL ON TRUCK	OTHER OIL: SLUDGE K051		LBS
EXXON REFINERY	19920825		ROLL OFF BOX/SPILL OCCURRED WHILE LIFTING THE BOX	ADAF SLUDGE K048	0	NON
EXXON REFINERY	19920827		STORAGE TANK/PRODUCT DISCOVERED ON TOP OF THE TANK AFTER THE STORM	GASOLINE: AUTOMOTIVE (4.23G PB/G)	0	NON
EXXON REFINERY	19920828		START UP ON BUTANIZER TOWER/VENTED DUE TO FAILURE OF SAFETY VALVE	HYDROGEN SULFIDE	0	NON
EXXON REFINERY	19920828		START UP ON BUTANIZER TOWER/VENTED DUE TO FAILURE OF SAFETY VALVE	HYDROCARBONS	0	NON
EXXON REFINERY	19920902		TANKARD S.S. SOLER FUELING SHIP/OVERFLOWED	OIL: DIESEL	2	GAL
EXXON REFINERY	19920904		T/B CHOTIN 2983/PIN HOLE LEAK IN NO.1 STARBOARD TANK	GASOLINE: AUTOMOTIVE (4.23G PB/G)	1	GAL
EXXON REFINERY	19920906		8" LOADING HOSE/RESIDUAL IN HOSE AFTER TRANSFER SHEEN SIZE:UNKNOWN	OTHER OIL, HEAVY COKER OIL	1	GAL

EXXON REFINERY	19920912		DISCHARGE/LEAKED	METHYL TERT-BUTYL ETHER	0	GAL
EXXON REFINERY	19921023		UNKNOWN / UNKNOWN	METHYL TERT-BUTYL ETHER	1	GAL
EXXON REFINERY	19921103		BARGE /UNKNOWN, NOTICED SHEEN WHILE LOADING THE BARGE. SHEEN: UNKNOWN SIZE, UNKNOWN COLOR. LIGHT SHEEN	JET FUEL: JP-5 (KEROSENE, HEAVY)	1	GAL
EXXON REFINERY	19921111		DISCHARGE LINE/OIL IN DISCHARGE. SHEEN: DISSIPATED. EMPLOYEES ACCIDENTLY SUCKED UP PRODUCT WITH A PUMP.	OIL: CRUDE	1	GAL
EXXON REFINERY	19921125		ROLL-OFF BOX, MATERIAL SPILLED OFF BACK OF BOX ROLL OFF BOX/MATERIAL SPILLED OFF BACK OF BOX	DAFF FLOAT		LBS
EXXON REFINERY	19921129	FITTING	CRUDE TO ASPHALT EXCHANGER/MECHANICAL FAILURE CRUDE TO ASPHALT EXCHANGER/MECHANICAL FAILURE	BENZENE		LBS
EXXON REFINERY	19921214		BARGE CHOATIN/FUEL COMPARTMENT LEAKING DUE TO HOLE	GASOLINE: AUTOMOTIVE (4.23G PB/G)	21	GAL
EXXON REFINERY	19921227		PINHOLE LEAK IN LOADING LINE	GASOLINE: AUTOMOTIVE (4.23G PB/G)	2	GAL
EXXON REFINERY	19921231		LUBE OIL PUMP/LEAK SHEEN SIZE 1 FT X 15 FT / RAINBOW COLOR	OIL, MISC: LUBRICATING	1	GAL
EXXON REFINERY	19930114		RAIN BASIN NO.1/OIL-WATER STREAM DIVERTED DUE TO OPERATION PROB RAIN BASIN #1,OIL/WATER STREAM DIVERTED DUE TO OPERATIONAL PROBL	OIL: CRUDE		BBL
EXXON REFINERY	19930114	IMPROPER MAINTENANCE	BOX CONTAINER/DOOR ON THE BACK OF THE BOX WAS LEFT AJAR BOX CONTAINER/DOOR ON THE BACK OF THE BOX WAS LEFT AJAR	K048 SLUDGE		LBS

EXXON REFINERY	19930205	VALVE	SAFETY VALVE ON A PROCESS TOWER/SAFETY VALVE RELEASED SAFETY VALVE ON A PROCESS TOWER/SAFETY VALVE RELEASED	HYDROGEN SULFIDE		LBS
EXXON REFINERY	19930205	VALVE	SAFETY VALVE ON A PROCESS TOWER/SAFETY VALVE RELEASED SAFETY VALVE ON A PROCESS TOWER/SAFETY VALVE RELEASED	GENERAL HYDROCARBONS	0	UNK
EXXON REFINERY	19930303	TANK OR CONTAINER	STORAGE TANK / FAULTY ROOF SEAM STORAGE TANK/FAULTY ROOF SEAM	HEXANE	0	LBS
EXXON REFINERY	19930303	TANK OR CONTAINER	STORAGE TANK / FAULTY ROOF SEAM STORAGE TANK/FAULTY ROOF SEAM	BENZENE	0	LBS
EXXON REFINERY	19930303	PIPELINE	8 INCH PIPE/COUPLING CAME LOOSE WHILE DISMANTLING PIPE 8 INCH PIPE/COUPLING CAME LOOSE WHILE DISMANTLING PIPE	OTHER OIL (MIXED GASES) OTH=QUAR		OTH
EXXON REFINERY	19930307		10" LOADING LINE/PINHOLE LEAK	GASOLINE: AUTOMOTIVE (4.23G PB/G)	0	UNK
EXXON REFINERY	19930311	CONTAINER LEAK	VENT ON COMPRESSOR / SEAL LEAKED VENT ON COMPRESSOR / SEAL LEAKED	HEXANE	0	LBS
EXXON REFINERY	19930323		CARGO HOSE/DISCHARGING BARGE AND HOSE LEAKED AT MIDDLE LINK	PETROLEUM WAX	1	GAL
EXXON REFINERY	19930328	VALVE	SAFETY VALVE/ RELEASED DUE TO PRESSURE SAFETY VALVE/RELEASED DUE TO PRESSURE	BENZENE	0	UNK
EXXON REFINERY	19930329		SAFETY VALVE ON DISTILLATION TOWER / RUPTURE IN COOLING TOWER LINE CAUSED OVERPRESSURIZATION IN TOWER	BENZENE	0	NON
EXXON REFINERY	19930401		REPORTING A FIRE AT THE COKER UNIT OF THE REFINERY REPORTING A FIRE AT THE COKER UNIT OF THE REFINERY	OIL: CRUDE	0	UNK
EXXON REFINERY	19930404		REFINERY SEWER SYSTEM/OVERFLOWED DUE TO RAIN SHEEN SIZE:LARGE UNKNOWN	WASTE OIL	1	GAL

EXXON REFINERY	19930407		ABOVE GROUND STORAGE TANK/UNK GASOLINE DISCOVERED ON TANK ROOF ABOVE GROUND STORAGE TANK/UNK GASOLINE DISCOVERED ON ROOF	GASOLINE: AUTOMOTIVE (4.23G PB/G)	0	UNK
EXXON REFINERY	19930407		EXCHANGER ON PIPE SEAL UNIT / LEAK DUE TO UNKNOWN CAUSES EXCHANGER ON PIPE SEAL UNIT / LEAK DUE TO UNKNOWN CAUSES	UNKNOWN MATERIAL	0	LBS
EXXON REFINERY	19930415		WATER CLARIFICATION UNIT / CARRY OVER DUE TO RAIN SHEEN SIZE: 20' X 5' / 1' X 10' RAINBOW	UNKNOWN OIL	2	GAL
EXXON REFINERY	19930426		INCINERATOR STACK/HYDROCARBONS GOT INTO THE STACK INCINERATOR STACK/HYDROCARBONS GOT INTO THE STACK	SULFUR DIOXIDE	0	LBS
EXXON REFINERY	19930426		INCINERATOR STACK/HYDROCARBONS GOT INTO THE STACK INCINERATOR STACK/HYDROCARBONS GOT INTO THE STACK	HYDROGEN SULFIDE	0	
EXXON REFINERY	19930628		BARGE TRANSFER HOSE/RESIDUAL FUEL SPILLED FROM THE HOSE WHEN IT WAS DISCONNECTED	OIL: DIESEL	2	GAL
EXXON REFINERY	19930713	VALVE	NO.10 UNIT/LEAKING BELLOWS/SAFETY VALVE NO.10 UNIT / LEAKING BELLOWS/ SAFETY VALVE	TOTAL NONMETHANE HYDROCARBON	0	LBS
EXXON REFINERY	19930713	VALVE	NO.10 UNIT/LEAKING BELLOWS/SAFETY VALVE NO.10 UNIT / LEAKING BELLOWS/ SAFETY VALVE	BENZENE	0	
EXXON REFINERY	19930713	VALVE	NO.10 UNIT/LEAKING BELLOWS/SAFETY VALVE NO.10 UNIT / LEAKING BELLOWS/ SAFETY VALVE	HEXANE	0	UNK
EXXON REFINERY	19930828	CONTAINER LEAK	ABOVE GROUND STORAGE TANK LEAKING FROM A WATER DRAW, CAUSE UNK. ABOVE GROUND STORAGE TANK LEAKING FROM A WATER DRAW, CAUSE UNK.	JET FUEL: JP-4	0	UNK

EXXON REFINERY	19930925		FLARE ON REFINERY / FLARE BLEW OUT DUE TO UNKNOWN REASONS CAUSING RELEASE	HYDROGEN SULFIDE	0	NON
EXXON REFINERY	19931001	VALVE	A PROCESS UNIT HAD A SAFETY VALVE RELEASE DUE TO PRESSURE A PROCESS UNIT HAD A SAFETY VALVE RELEASE DUE TO PRESSURE	HYDROGEN	0	LBS
EXXON REFINERY	19931001	VALVE	A PROCESS UNIT HAD A SAFETY VALVE RELEASE DUE TO PRESSURE A PROCESS UNIT HAD A SAFETY VALVE RELEASE DUE TO PRESSURE	HYDROGEN SULFIDE	0	
EXXON REFINERY	19931001	VALVE	A PROCESS UNIT HAD A SAFETY VALVE RELEASE DUE TO PRESSURE A PROCESS UNIT HAD A SAFETY VALVE RELEASE DUE TO PRESSURE	BUTADIENE	0	UNK
EXXON REFINERY	19931018		4 INCH PIPE/THE CAUSE OF THE RELEASE IS UNKNOWN 4 INCH PIPE/THE CAUSE OF THE RELEASE IS UNKNOWN	SULFURIC ACID	0	LBS
EXXON REFINERY	19931020		MATERIAL WAS RELEASED DUEING A TRANSFER FROM SHORE TO THE M/V S R WILMINGTON DUE TO A INJECTOR VALVE FAILURE	WAX: PARAFFIN	5	BBL
EXXON REFINERY	19931110	PIPELINE		POWERFORMER FEED	0	LBS
EXXON REFINERY	19931115			SULFUR DIOXIDE	0	LBS
EXXON REFINERY	19931118		PIPE STILL UNIT//LEAKED DUE TO UNKNOWN REASONS	HYDROCARBONS	0	NON
EXXON REFINERY	19931207	PUMP	PUMP / RELEASE IS DUE TO A FIRE PUMP/RELEASE IS DUE TO A FIRE	SULFUR DIOXIDE	0	LBS
EXXON REFINERY	19931229		LOADING LINE/RELEASE IS DUE TO A LEAK	GASOLINE: AUTOMOTIVE (4.23G PB/G)	2	GAL
EXXON REFINERY	19940110		MTBE UNIT REBOILER/SOURCE OF THE RELEASE IS UNDER INVESTIGATION MTBE UNIT REBOILER/SOURCE OF THE RELEASE IS UNDER INVESTIGATION	METHYL TERT-BUTYL ETHER	0	LBS

EXXON REFINERY	19940206		NO. 5 FLARE, DUE TO EXTINGUISHED FLARE NO. 5 FLARE/DUE TO EXTINGUISHED FLARE	CHLORINATED HYDROCARBONS	0	LBS
EXXON REFINERY	19940206		NO. 5 FLARE, DUE TO EXTINGUISHED FLARE NO. 5 FLARE/DUE TO EXTINGUISHED FLARE	HYDROGEN SULFIDE	0	
EXXON REFINERY	19940222		FLARE/HYDROCARBONS GOT INTO SOURWATER STRIPPER PLANT*** FLARE/ HYDROCARBONS GOT INTO SOURWATER STRIPPER PLANT***	SULFUR DIOXIDE	0	UNK
EXXON REFINERY	19940305	CONTAINER LEAK	MECHANICAL MALFUNCTION OF MIXER ON MOTOR GAS TANK,LEAKING MECHANICAL MALFUNCTION OF MIXER ON MOTOR GAS TANK/ LEAKING INTO FACILITY STORM SEWER/ABOVE GROUND STORAGE TANK	GASOLINE: AUTOMOTIVE (UNLEADED)	0	UNK
EXXON REFINERY	19940406	LIGHTNING	FLARE STACKS/POWER FAILED DUE TO SEVERE ELECTRICAL STORMS FLARE STACKS/POWER FAILED DUE TO SEVERE ELECTRICAL STORMS	SULFUR DIOXIDE	0	UNK
EXXON REFINERY	19940421		REFINERY SEWER SYSTEM/CONTAINED OIL WHICH RELEASED TO MISSISSIPPI RIVER	WASTE OIL	1	BBL
EXXON REFINERY	19940425		LIGHT ENDS SPLITTER TOWER/SAFETY VALVE RELEASE>OVERPRESSURE LIGHT ENDS SPLITTER TOWER/SAFETY VALVE RELEASE>OVERPRESSURE	BENZENE	0	UNK
EXXON REFINERY	19940517	POWER FAILURE	REFINERY FLARES ARE EMITTING SMOKE DUE TO LOW STEAM PRESSURE* REFINERY FLARES ARE EMITTING SMOKE DUE TO LOW STEAM PRESSURE*	SMOKE AND HYDROCARBONS	0	UNK
EXXON REFINERY	19940612		OUTFALL/ ACCUMULATION OF OIL FROM SEWER SYSTEM// SHEEN:TWO SHEENS 6FT X 6FT EACH: BLACK SHEEN	UNKNOWN OIL	0	UNK
EXXON REFINERY	19940701	FLANGE	FLANGE ON A STORAGE TANK /GASKET FAILURE FLANGE ON STORAGE TANK / GASKET FAILURE	CATALYTIC NAPHTHA (BENZENE)	15	BBL



EXXON REFINERY	19940702	PIPELINE	PIPELINE/LEAKING DUE TO UNKNOWN CAUSE PIPELINE, LEAKING DUE TO UNKNOWN CAUSE	UDEX RAFFINATE	0	UNK
EXXON REFINERY	19941015	PUMP	GASKET FAILED ON DISCHARGE SIDE OF A FACILITY PUMP GASKET FAILED ON DISCHARGE SIDE OF A FACILITY PUMP	LIGHT CAT CYCLE OIL	0	UNK
EXXON REFINERY	19950125	CONTAINER LEAK	PIPE STILL NO 8, LEAKING HEAT EXCHANGER PIPE STILL NO.8/ LEAKING HEAT EXCHANGER	BENZENE	0	UNK
EXXON REFINERY	19950127	RAIN OR SNOW	RAIN BASIN NO 2, RAINED/ CAUSED IT TO OVERFLOW RAIN BASIN NO. 2, RAINED, CAUSED IT TO OVERFLOW	WASTE OIL	2	GAL
EXXON REFINERY	19950128	FITTING	TRANSFER LINE AT GAS BLENDING AREA, GASKET FAILURE TRANSFER LINE AT GAS BLENDING AREA/GASKET FAILURE	HEXANE	0	UNK
EXXON REFINERY	19950128	FITTING	TRANSFER LINE AT GAS BLENDING AREA, GASKET FAILURE TRANSFER LINE AT GAS BLENDING AREA/GASKET FAILURE	1,2,4-TRIMETHYL BENZENE	0	UNK
EXXON REFINERY	19950208		SULFUR RECOVERY UNIT/UPON STARTUP MATERIALS WERE RELEASED	SULFUR DIOXIDE	0	NON
EXXON REFINERY	19950208		SULFUR RECOVERY UNIT,UPON START UP MATERIALS WERE RELEASED SULFUR RECOVERY UNIT,UPON START-UP MATERIALS WERE RELEASED	SULFUR DIOXIDE	0	UNK
EXXON REFINERY	19950210	FITTING	POWER FORMER 1 UNIT,RELEASED MATERIAL DURING UNIT START UP POWER FORMER 1 UNIT//UNIT RELEASED MATERIAL DURING UNIT STARTUP	HYDROGEN SULFIDE	0	UNK

EXXON REFINERY	19950316	VALVE	NO.4 LIGHT END UNIT EAST SPLITTER OVERHEAD,RELIEF VALVE RELEASE NO.4 LIGHT END UNIT EAST SPLITTER OVERHEAD/RELIEF VALVE RELEASED MATERIAL DUE TO OVERPRESSURIZATION DURING START-UP	BENZENE	0	UNK
EXXON REFINERY	19950329		OUTFALL 003//EXCESSIVE RAIN RUNOFF//SHEEN SIZE: 100 FT X 100 FT// RAINBOW IN COLOR	UNKNOWN OIL	0	GAL
EXXON REFINERY	19950402	PIPELINE	GAS/ OIL LINE / CORROSION GAS/OIL LINE / CORROSION	OTHER OIL	0	UNK
EXXON REFINERY	19950416	FLANGE	FEED LINE FLANGE / BURST FEEDLINE FLANGE/BURST	OTHER OIL-HEAVY COKER GAS OIL	0	UNK
EXXON REFINERY	19950605	CONTAINER LEAK	COOLER, PIN HOLE LEAK COOLER, PIN HOLE LEAK	BENZENE	0	UNK
EXXON REFINERY	19950605	CONTAINER LEAK	COOLER, PIN HOLE LEAK COOLER, PIN HOLE LEAK	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19950606	VALVE	PROCESS EQUIPMENT,, SAFETY VALVE LEAK PROCESS EQUIPMENT/SAFETY VALVE LEAK	HYDROCARBON	0	UNK
EXXON REFINERY	19950606	VALVE	PROCESS EQUIPMENT,, SAFETY VALVE LEAK PROCESS EQUIPMENT/SAFETY VALVE LEAK	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19950629		SHEEN OBSERVED COMING FROM OUTFALL - 50FT X 100FT / RAINBOW INCIDENTAL TO HEAVY RAINS - RECOVERY BASIN NO.2 OVERFLOWED INTO OUTFAL	WASTE OIL/LUBRICANTS - POSS. CO	1	GAL
EXXON REFINERY	19950707		UNKNOWN / UNKNOWN SHEEN SIGHTING, SHEEN SIZE:UNKNOWN/COLOR:RAINBOW	UNKNOWN MATERIAL	1	GAL
EXXON REFINERY	19950829	CONTAINER LEAK	A PROCESS UNIT , LEAK HAS DEVELOPED A PROCESS UNIT/A LEAK HAS DEVELOPED	METHYL TERTIARY BUTYL ETHER	0	UNK

EXXON REFINERY	19950927	OVERFLOW	ABOVE GROUND 3000 BBL STORAGE TANK, OVERFLOW 30000 BBL STORAGE TANK/OVERFLOW	CRESYLATE SPENT CAUSTIC	0	UNK
EXXON REFINERY	19951023	FITTING	A CONDENSATE DRUM RELEASED TO THE ATMOSPHERE DUE TO PRESSURE A CONDENSATE DRUM RELEASED TO THE ATMOSPHERE DUE TO A PRESSURE INCREASE	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19960210	CONTAINER LEAK	TANK #109 WATER BOTTOMS,LEAK IN PIPE,INTERNAL CORROSION TANK #109 WATER BOTTOMS / LEAK IN THE PIPE / INTERNAL CORROSION	BENZENE//LESS THAN 10 PPM	0	UNK
EXXON REFINERY	19960319	FITTING	CATALYTIC CRACKING UNIT, COMPRESSOR FAILED CATALYTIC CRACKING UNIT, COMPRESSOR FAILED	SULFUR DIOXIDE	0	UNK
EXXON REFINERY	19960319	FITTING	CATALYTIC CRACKING UNIT, COMPRESSOR FAILED CATALYTIC CRACKING UNIT, COMPRESSOR FAILED	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19960319	FITTING	CATALYTIC CRACKING UNIT, COMPRESSOR FAILED CATALYTIC CRACKING UNIT, COMPRESSOR FAILED	HYDROCARBONS	0	UNK
EXXON REFINERY	19960821	VALVE	SAFETY VALVE ON A DRUM ON EAST COKER UNIT,MALFUNCTION OF VALVE SAFETY VALVE ON A DRUM ON EAST COKER UNIT / MALFUNCTION OF VALVE	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19960821	VALVE	SAFETY VALVE ON A DRUM ON EAST COKER UNIT,MALFUNCTION OF VALVE SAFETY VALVE ON A DRUM ON EAST COKER UNIT / MALFUNCTION OF VALVE	HYDROCARBONS	0	UNK
EXXON REFINERY	19961107	CONTAINER LEAK	HEAT EXCHANGER, A TUBE DEVELOPED A LEAK HEAT EXCHANGER / A TUBE DEVELOPED A LEAK	OIL, FUEL: NO. 2-D	0	UNK
EXXON REFINERY	19961112	VALVE	CRUDE PIPE STILL UNIT,OVERPRESSURE RESULTED IN SAFETY VALVE** CRUDE PIPE STILL UNIT / OVERPRESSURE RESULTED IN SAFETY VALVE RELEASE	OIL: CRUDE VAPORS	0	UNK

EXXON REFINERY	19970205	CONTAINER LEAK	HEAT EXCHANGER,LEAKING INTO A STEAM CONDENSATE DRUM THAT IS HEAT EXCHANGER/EXCHANGER LEAKING INTO A STEAM CONDENSATE DRUM THAT IS RELEASING TO THE ATMOSPHERE	BUTADIENE	0	UNK
EXXON REFINERY	19970205	CONTAINER LEAK	HEAT EXCHANGER,LEAKING INTO A STEAM CONDENSATE DRUM THAT IS HEAT EXCHANGER/EXCHANGER LEAKING INTO A STEAM CONDENSATE DRUM THAT IS RELEASING TO THE ATMOSPHERE	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19970314		SUSPECTED 12 INCH PIPELINE / THE LINE APPEARS TO BE LEAKING / IT IS CURRENTLY SUBMERGED DUE TO HIGH FLOOD WATERS	OIL: DIESEL	0	UNK
EXXON REFINERY	19970402	CONTAINER LEAK	COMPRESSOR LEAKING INTO COOLING WATER TOWER COMPRESSOR/COMPRESSOR LEAKING INTO COOLING WATER TOWER	BUTADIENE	0	UNK
EXXON REFINERY	19970407	FLANGE	POWER FORMER 2 UNIT HAD A LEAKING FLANGE POWER FORMER 2 UNIT HAD A LEAKING FLANGE	BENZENE	0	UNK
EXXON REFINERY	19970617		OUTFALL 003 / HEAVY RAIN WASHED RESIDUAL MATERIAL OUT OF THE SYSTEM ANDCREATED A SHEEN ON THE RIVER	UNKNOWN OIL	1	GAL
EXXON REFINERY	19970804	UNKNOWN	EXCHANGER ONA MTBE UNIT,EXCHANGER LEAK,CAUSE UNKNOWN EXCHANGER ON MTBE UNIT / EXCHANGER LEAK / CAUSE UNKNOWN	UNKNOWN MATERIAL	0	UNK
EXXON REFINERY	19970819	UNKNOWN	HYDROCARBON FOUND IN COOLING WATER,UNKNOWN SOURCE OR CAUSE HYDROCARBON FOUND IN COOLING WATER/UNKNOWN SOURCE OR CAUSE	BENZENE	0	UNK
EXXON REFINERY	19970916	CONTAINER LEAK	FAULTY EXCHANGER CAUSED A LEAK IN THE COOLING TOWER FAULTY EXCHANGER CAUSED A LEAK IN THE COOLING TOWER	BUTADIENE	0	UNK

EXXON REFINERY	19970916	CONTAINER LEAK	FAULTY EXCHANGER CAUSED A LEAK IN THE COOLING TOWER FAULTY EXCHANGER CAUSED A LEAK IN THE COOLING TOWER	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19971024		CARRY OVER FROM A STORM WATER DISCHARGE AT NPDES PERMITTED DISCHARGE OUTFALL 003 / CARRY OVER WAS CAUSED BY HEAVY RAINS	SEWER OIL	1	GAL
EXXON REFINERY	19971111	PUMP	HYDRO PACKER, PUMP FAILURE CAUSED UNIT UPSET HYDRO PACKER / PUMP FAILURE CAUSED UNIT UPSET	BENZENE	0	UNK
EXXON REFINERY	19971111	PUMP	HYDRO PACKER, PUMP FAILURE CAUSED UNIT UPSET HYDRO PACKER / PUMP FAILURE CAUSED UNIT UPSET	HYDROCARBONS	0	UNK
EXXON REFINERY	19971111	PUMP	HYDRO PACKER, PUMP FAILURE CAUSED UNIT UPSET HYDRO PACKER / PUMP FAILURE CAUSED UNIT UPSET	HYDROGEN SULFIDE	0	UNK
EXXON REFINERY	19971204	CONTAINER LEAK	LEAK INTO COOLING TOWER WATER SYSTEM LEAK INTO COOLING TOWER WATER SYSTEM	BENZENE	0	UNK
EXXON REFINERY	19971204	CONTAINER LEAK	LEAK INTO COOLING TOWER WATER SYSTEM LEAK INTO COOLING TOWER WATER SYSTEM	HYDROCARBONS	0	UNK
EXXON REFINERY	19971204	CONTAINER LEAK	LEAK INTO COOLING TOWER WATER SYSTEM LEAK INTO COOLING TOWER WATER SYSTEM	HYDROGEN SULFIDE	0	UNK

## EXXON RESIN FINISHING PL.

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON RESIN FINISHING PL.	19970206		STORAGE TANK, PRODUCT BOILED OVER STORAGE TANK / PRODUCT BOILED OVER	VAR SOL	0	UNK

## EXXON SHIPPING

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON SHIPPING	19910105		TRANSFER HOSE FROM BARGE EB-334 TO BARGE EB-333 / HOSE RUPTURED	MTBE - GASOLINE ADDITIVE	4	GAL
EXXON SHIPPING	19910128		HYDRAULIC PUMP ON A HEATER BARGE / DUE TO A COUPLING FAILURE.	HYDRAULIC OIL	2	GAL
EXXON SHIPPING	19910129		M/V EXXON LOUISVILLE / UNKNOWN CAPTAIN OF VSL UNABLE TO CONFIRM THAT OIL IN WATER IS FROM HIS VSL.	UNKNOWN OIL	0	UNK
EXXON SHIPPING	19910511		EXPANSION TANK ON A HEATER / FLUID IN SYSTEM LEAKED DUE TO HEAT FROM SUN	CHOLORIA HT-43	1	GAL
EXXON SHIPPING	19910602		TOW BOAT EXXON TENNESSEE/ OVERFILLED HYDRAULIC SYSTEM TANK	HYDRAULIC OIL (PINT)	1	OTH
EXXON SHIPPING	19910719		STORAGE TANK ON VESSEL / OPERATOR OVERFILLED TANK.	OIL, MISC: LUBRICATING	1	GAL

## EXXON SHIPPING CO

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON SHIPPING CO	19880524		T/B EB 227/229 CROSS OVER HOSE BETWEEN BARGES/HOSE RUPTURED	TOLUENE	1	BBL
EXXON SHIPPING CO	19910320		M/V STAVANGER PRINCE / LEAKING OIL FROM ONE TANK	OIL: CRUDE	3000	BBL

## EXXON SHIPPING COMPANY

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON SHIPPING COMPANY	19900503		NO. 3 PORT TANK IN BARGE HAS A 1" CRACK DUE TO UNKNOWN CAUSE	METHYL TERTIARYBUTYLETHER	3	GAL
EXXON SHIPPING COMPANY	19920406		RUPTURED TANK ONBOARD BARGE	GASOLINE: AUTOMOTIVE (4.23G PB/G)	0	UNK

EXXON SHIPPING COMPANY	19930503		T/B DIXIE 1106/AIR LINE LEAKED AN UNKOWN PRODUCT INTO THE AIR AND MADE SHEEN ON THE WATER. SHEEN: 2 INCHES X 195 FT. LIGHT IN COLOR	UNKNOWN MATERIAL	0	UNK
------------------------	----------	--	---	------------------	---	-----

## EXXON USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON USA	19900220		TUBE LEAK ON EXCHANGER	HYDROGEN SULFIDE	0	UNK
EXXON USA	19900613		SAFETY VALVE ON PRESSURE VESSEL. VESSEL WAS OVERPRESSURED AND CAUSED THE RELEASE	BENZENE	0	NON
EXXON USA	19900807		SAFETY VALVE ON A COKER DRUM / VALVE FAILED.	HYDROGEN SULFIDE	0	NON
EXXON USA	19930917		6" LINE / SEAL PLUG LEAKED CAUSING RELEASE	OIL, FUEL: NO. 6	1	BBL
EXXON USA	19930918		DRAIN PAN ON DOCK / PLUGGED BY INSECTS	ISOOCTYL ALCOHOL	0	UNK
EXXON USA	19930924		A TRANSFER LINE IN A BERTH HAD A VALVE GASKET BLOW	GASOLINE	0	GAL
EXXON USA	19931016	CONTAINER LEAK	REFINERY/SPENT ACID LINE/ PIN HOLE IN WELD REFINERY/ SPENT ACID LINE/ PIN HOLE IN WELD	SULFURIC ACID, SPENT	0	LBS
EXXON USA	19931017		DRIP PAN/SEAL FAILURE	OIL, FUEL: NO. 2-D	0	GAL
EXXON USA	19931018		MMI 302 DISCHARGED INTO THE MMI 404/MMI 404 WAS OVERFILLED WHEN A PUMP WAS OVERPOWERED	RAFFINATE (LIGHT GASOLINE)	1	GAL
EXXON USA	19931124		A STORAGE HAD A SAMPLE TAP LEFT OPEN	PETROLEUM NAPHTHA	0	NON
EXXON USA	19931124		A STORAGE TANK HAD A TAP LEFT OPEN	PETROLEUM NAPHTHA	0	NON

EXXON USA	19931209	PIPELINE	1 INCH TRANSFER LINE /RELEASE IS DUE TO CORROSION 1 INCH TRANSFER LINE //RELEASE IS DUE TO CORROSION	CREOSOTE	0	LBS
EXXON USA	19931209	PIPELINE	1 INCH TRANSFER LINE /RELEASE IS DUE TO CORROSION 1 INCH TRANSFER LINE //RELEASE IS DUE TO CORROSION	OTHER OIL (LIGHT CAT CYCLE OIL)	0	
EXXON USA	19931222	FITTING	VENT SYSTEM/THE RELEASE WAS CAUSED BY A MECHANICAL FAILURE VENT SYSTEM / THE RELEASE WAS CAUSED BY MECHANICAL FAILURE	BENZENE	0	LBS
EXXON USA	19931222	FITTING	VENT SYSTEM/THE RELEASE WAS CAUSED BY A MECHANICAL FAILURE VENT SYSTEM / THE RELEASE WAS CAUSED BY MECHANICAL FAILURE	HYDROGEN SULFIDE	0	
EXXON USA	19931222	FITTING	VENT SYSTEM/THE RELEASE WAS CAUSED BY A MECHANICAL FAILURE VENT SYSTEM / THE RELEASE WAS CAUSED BY MECHANICAL FAILURE	HYDROCARBONS	0	LBS
EXXON USA	19940102	OVERFLOW	OCEAN-GOING BARGE WAS OVERFILLED, PIC WAS NOT AWARE OF SITUATION OCEAN-GOING BARGE WAS OVERFILLED,PIC WAS NOT AWARE OF SITUATION	OIL, FUEL: NO. 2	1	OTH
EXXON USA	19940123	VALVE	ABSORBER AND SPLITTER TOWER/SAFETY VALVES RELEASED>STARTUP** ABSORBER AND SPLITTER TOWER/ SAFETY VALVES RELEASED>STARTUP**	BENZENE	0	UNK
EXXON USA	19940330		UNDERGROUND LINE/CALLER UNSURE OF CAUSE OR SIZE OF LINE UNDERGROUND LINE/CALLER UNSURE OF CAUSE OR SIZE OF LINE	GASOLINE: AUTOMOTIVE (UNLEADED)	0	UNK
EXXON USA	19940423		TRANSFER LINE / GASKET FAILURE	GASOLINE: AUTOMOTIVE (UNLEADED)	2	BBL



EXXON USA	19940426	PIPELINE	UNDERGROUND PIPELINE/LEAK DUE TO CORROSION,CALLER UNSURE SIZE UNDERGROUND PIPELINE/LEAK DUE TO CORROSION,CALLER UNSURE SIZE	OIL: CRUDE	0	UNK
EXXON USA	19940517	PIPELINE	6 INCH SLOP LINE/ BUILT EXCESS PRESSURE CAUSING RELEASE 6 INCH SLOP LINE/BUILT EXCESS PRESSURE CAUSING RELEASE	SLOP OIL UNKNOWN OIL	2	GAL
EXXON USA	19941009		STORM WATER OUTFALL//HEAVY RAINS	UNKNOWN OIL	2	BBL
EXXON USA	19950126		10 IN PIPELINE MANIFOLD/BLOWN GASKET	OIL: DIESEL	1	GAL
EXXON USA	19950309		HYDRO PRESSURE TESTING LOADING ARM AND MATERIAL WAS RELEASED DUE TO A FAULTY GASKET	OIL, FUEL: NO. 2-D	10	GAL
EXXON USA	19950422	TANK OR CONTAINER	RELEASE TO GROUND FROM HAZARDOUS WASTE STORAGE TANK** RELEASE TO GROUND FROM HAZARDOUS WASTE STORAGE TANK **	HAZARDOUS WASTE (CONTAINS 3-4 PP	0	UNK
EXXON USA	19950516	CONTAINER LEAK	SEWER, LEAK IN SEWER SEWER/LEAK IN SEWER	PRIMARY SEWAGE SLUDGE F037 WASTE	0	UNK
EXXON USA	19950809	TANK OR CONTAINER	UNKNOWN SIZE TANK LINE, CORROSION UNKNOWN SIZE TANK LINE/CORROSION	H2O CONTAINING > PPM OF BENZENE	0	UNK
EXXON USA	19950828	CONTAINER LEAK	PROCESSING CONTAINMENT AREA, LEAK PROCESSING CONTAINMENT AREA/LEAK	K049(HAZARDOUS WASTE)	0	UNK
EXXON USA	19950903	FITTING	SHUTTING DOWN SULFUR RECOVERY UNIT, UPSET SHUTTING DOWN SULFUR RECOVEREDRY UNIT/UPSET	HYDROGEN SULFIDE	0	UNK
EXXON USA	19950903	FITTING	SHUTTING DOWN SULFUR RECOVERY UNIT, UPSET SHUTTING DOWN SULFUR RECOVEREDRY UNIT/UPSET	AMMONIA, ANHYDROUS	0	UNK
EXXON USA	19950903	FITTING	SHUTTING DOWN SULFUR RECOVERY UNIT, UPSET SHUTTING DOWN SULFUR RECOVEREDRY UNIT/UPSET	SULFUR DIOXIDE	0	UNK

EXXON USA	19950903	CONTAINER LEAK	LEAKING PIPE ELBOW, CORROSION LEAKING PIPE ELBOW / CORROSION	SPENT CAUSTIC	0	UNK
EXXON USA	19950915		BARGE "STONE 24"/TANKERMAN OVERFILLED BARGE	JET FUEL: JP-5 (KEROSENE, HEAVY)	3	BBL
EXXON USA	19950923		LOADING ARN/VALVE WAS LEFT OPEN	OTHER OIL	1	BBL
EXXON USA	19951218		LIGHT OIL FINISHING UNIT/3" FLANGE RUPTURED DUE TO UNKNOWN CAUSES	OTHER OIL - LIGHT CATALYTIC OIL	0	UNK
EXXON USA	19960306		SHEEN DISCOVERED AT OUTFALL #003 FROM WASTE WATER TREATMENT PLANT / SHEEN SIZE: UNKNOWN, COLOR UNKNOWN	UNKNOWN OIL	1	GAL
EXXON USA	19960413		OUTFALL NO.003/RESIDUAL CREATED A SHEEN	OTHER OIL	0	UNK
EXXON USA	19960801	UNKNOWN	OUT OF SERVICE STORAGE TANK.#197,RIVET IN TANK BOTTOM CORRODED OUT-OF-SERVICE STORAGE TANK #197/RIVET IN TANK BOTTOM CORRODED/MATERIALRELEASED OVER LONG PERIOD OF TIME	HAZARDOUS WASTE D018	0	UNK

## EXXON, USA

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON, USA	19910624		COKE UNIT / BLOCKED LINE CAUSED RELIEF VALVE TO BLOW	BENZENE	0	NON
EXXON, USA	19920221		OVERHEAD PIPELINE LEAKING/UNKNOWN OVERHEAD PIPELINE LEAKING/UNKNOWN	NITRIC OXIDE	0	UNK
EXXON, USA	19920227	IMPROPER STORAGE/HANDLING	MAT.SPILL DURING TRANSFER FROM WASTEWATER TREATMENT SYSTEM MAT.SPILL DURING TRANSFER FROM WASTEWATER TREATMENT SYSTEM.	DAF FLOAT(SOLID WASTE)		LBS

# EXXON/BATON ROUGE PLASTICS

Discharger	Spill_date	Cause_code	Descriptio	Substance	Quantity	Unit
EXXON/BATON ROUGE PLASTICS	19940425	FITTING	REACTOR DUMP/HIGH TEMPERATURE INTERLOCK REACTOR DUMP/HIGH TEMPERATURE INTERLOCK	ETHYLENE	0	UNK